

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सासाराम-1

Email ID:-ee.rwd.sasaram1@gmail.com Mob:- 8986915310

पत्रांक. 1531/2997 सासाराम/दिनांक....10.08.2023

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-1

सेवामें,

नोडल पदाधिकारी (MR 3054)
ग्रामीणकार्यविभाग
पटना, बिहार

विषय :-

नई अनुक्षण नीति-2018MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के विरुद्ध आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि नई अनुक्षण नीति-2018 MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के लिए संवेदक को भुगतान करने हेतु अध्याचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है।

अनु० :- यथोक्त।

विश्वरामभाजु

(इ.स.म.चन्द्र पंडित)

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-1

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilization Certificate up to Aug 2023

Sl.No	Name of Scheme	Sanction No.&Date With Amount (In lace Rs.)	Amount Received (In lace Rs.)	Particulars
1	Construction of Rural roads Under MR	New Maintenance Policy-2018 MR (3054) BRRDA PATNA	12145.34634	Certified that out of Rs. 12145.34634 lakh of grants-in-aid sanctioned during the years 2021-23 In favor of EE, RWD works division Sasaram-1 sum of Rs 12047.47971 Lakh has been utilized for the purpose of MR (3054) Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 97.86663 lakh remaining unutilized at the end of the period under report.
	Total:		12145.34634	

2. Certified that I have satisfied my self that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-

- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- All other caudal formalities have been observed.

3. Physical Progress achieved:-

- Construction of Road Works.
- Construction of CD works.

Divisional Accounts Officer
R.W.D, works Division
Sasaram-1


Executive Engineer

R.W.D, works Division
Sasaram-1

OFFICE OF EXECUTIVE ENGINEER, RURAL WORKS DEPARTMENT, WORKS DIVISION, SASARAM-1

Registration Format for Scheme Head- MR(3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division:- Sasaram-1

Sl no.	Batch No	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No & Date	Administrative Approval (AA)		Amount of Surface Rectification with Initial (in Lakh)	5 Year Routine Maintenance (in Lakh)	Agreement Amount (in Lakh)	Agreement Completion as per Agreement	Date of Actual Completion	Value of IRI (in mm/sum)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	up-to-date expenditure as per MIS (in Lakh)	Registration done against work (in Lakh)	Remarks
1	2	1049 - Amara Babhanpurwa Road to Baradhi (ODR32)	10301002236	611 15.07.2022	1	47.931	26.15763	9.26992	28MBD/2022-23 & 06/03/2023	5/12/2023	0	3095	25.00	5.00	19.50112	19.50112	4.56813	
2	0006	1059-Amara Babhanpurwa Road to Belwa (ODR39)	10301002250	1412 08.09.2022	2.26	101.346	58.84442	18.09194	28MBD/2022-23 & 06/03/2023	5/12/2023	0	3050	25.00	5.00	48.25123	46.17625	10.59319	
3	0006	Rohatas Jila antargat sasaram rampur panchayat tatha dumarai main road se gram ugarbigha nirmajpur hole huakapadih gaon tak	10301003015	1412 08.09.2022	3.54	168.669	102.00525	28.27014	28MBD/2022-23 & 06/03/2023	5/12/2023	0	3076	25.00	5.00	80.45630	75.73703	17.53813	

Divisional Accounts Officer
Rural Works Department
Works Division, Sasaram-1

10/08/2023

Executive Engineer
Rural Works Department
Works Division, Sasaram-1

10/08/2023

Name of Road:- Amara Babhanpurwa Path to Baradih

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event
19/4/23	12:46:0	17	0.1	290	10.1	2900	3315	G	24.982435	84.109292	Normal
19/4/23	12:46:19	17	0.1	280	10.1	2800	3215	G	24.983358	84.10946	Curve
19/4/23	12:47:0	17	0.1	300	10.1	3000	3415	G	24.983318	84.110403	Normal
19/4/23	12:47:25	17	0.1	240	10.1	2400	2815	G	24.984078	84.110858	Normal
19/4/23	12:47:51	17	0.1	260	10.1	2600	3015	G	24.984727	84.111278	Normal
19/4/23	12:49:11	17	0.1	290	10.1	2900	3315	G	24.985458	84.11148	Normal
19/4/23	12:49:42	17	0.1	240	20.2	2400	2815	G	24.98637	84.111548	Normal
19/4/23	12:50:0	17	0.1	260	20.2	2600	3015	G	24.986595	84.11212	Curve
19/4/23	12:50:32	17	0.1	290	10.1	2900	3315	G	24.986165	84.111565	Normal
19/4/23	12:50:57	17	0.1	230	20.2	2300	2715	G	24.985287	84.111515	Normal
Average IRI											
3095											

$Y = 0 * X^2 + 1.000 * X + 415.2$
 $X = 2600$
 $Y = 3015$
 (R) RURAL ROAD
 Good
 Average
 Poor
 <4000
 4001-5000
 >5001


21.04.23
 Executive Engineer
 Rural Work's Department
 Work Division, Sasaram-1

19/04/23
 AC

19/04/2023
 Sasaram

Name of Customer: **VIKASH KUMAR SINGH**
 Name of Work: **Amara Babhanpurwa Road to Beradih**
 Lab Job number: **17**
 Date: **19-04-2023**
 Section No.: **17**

Test Date: **19-04-2023**
 Machine No.: **391**
 Start S No.: **03**
 Start E No.: **12**
 Side: **Sasaram**
 Road Type: **(R) RURAL ROAD**
 Road Name: **Babhanpurwa Road to Beradih**
 Interval:
 UV Range: **1715** To **4000** mm/km
 Dist Range: **0** To **1.1** * 1000 m
 Equation: **$Y = 0.0 \cdot X^2 + 1.000 \cdot X + 415.2$**



Print
 Generate Report and Graph
 Redraw Graph
 Map View

Activate Windows
 Go to Settings to activate Windows