

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, मधेपुरा

पत्रांक- 2679(अनु०)

दिनांक- 01/12/23

प्रेषक,

ई० विद्यानन्द प्रसाद,
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, मधेपुरा।

सेवा में,

नोडल पदाधिकारी,
3054 एम.आर. कोषांग,
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय- MR (3054) under New Maintenance Policy- 2018 के क्रियान्वित पथों के भुगतान हेतु अधियाचना के संबंध में।

प्रसंग- भवदीय पत्रांक 113 अनु० दिनांक 10.01.2020

महाषय,

उपर्युक्त विषयक प्रासंगिक पत्र के संबंध में कहना है कि कार्यप्रमण्डल मधेपुरा अन्तर्गत MR (3054) under New Maintenance Policy- 2018 योजना के पथ में पूर्ण कराये गये कार्यों का भुगतान हेतु अधियाचना विहित प्रपत्र में तैयार कर आवश्यक कार्रवाई हेतु समर्पित की जाती है।

सूचनार्थ एवं आवश्यक कार्रवाई हेतु समर्पित।

- अनु०- 1. अधियाचना विहित प्रपत्र में।
2. Recorder IRI की प्रतिहस्ताक्षरित प्रति।

विष्वासभाजन

30/11/23

(ई० विद्यानन्द प्रसाद)
कार्यपालक अभियंता,

30/11/23

Form GFR 19- A
(See Government of India's Decision (I) below Rule - 150)
Form of Utilization Certificate upto the month of 30 November 2023
New Maintenance Policy 2018

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in lacs)	Amount Received (In lacs)	Particulars
1	New Maintenance Policy 2018	Letter No 56 Dated 12.08.2020 Letter No 86 Dated 11.12.2020	Rs 99.10000 Vide Letter No :- 151 Dated 10.11.2023	Certified that out of RS 7855.07022 lacs of grants in aid sanctioned during the Years up to 2023-24 in favour of Executive Engineer, RWD Works Division Madhepura under this Department, a sum of Rs 7836.74616 lacs has been utilized for the purpose of New_MR Scheme remaining 18.32406 unutilized at the end of the period under report.
		Total :	99.10000	

Certified and verified myself that the conditions on which the grants in aid was sanctioned have been duly fulfilled / are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kinds of Checks exercised :-

- i Works have been supervised by Executive Engineer/ Superintending Engineer.
- ii Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- iii Construction material have been tested.
- iv Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/Executive Engineer.
- v All other codal formalities have been observed.

Physical Progress achieved :-

- i Construction of Road works.
- ii Construction of CD works


D.A.B.
RWD works Division
Madhepura


30/11/23
Executive Engineer
RWD works Division
Madhepura


30/11/23

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018 (Initial Rectification and Surface Renewal)

Name of Division : Madhepura

Sl.No	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allocated Amount (I Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against work done (In lac)	Remarks
					Length (In Km)	Amount (in Lac)	Initial Rectification with Surface Renewal (in lac)	5 years Routine Maintenance (In lac)										
2	RM/MA/MAD/22/0006	Construction Of Road From Near Mahadalit Tola Natal Risdeo House To Jaddiya High MMGSY[SC]hool Via Sunderp	21004713002	1192 / 28.08.2022	4.065	261.508	214.55028	42.77780	52 MBD/2022-23-- 19/12/2022	15.09.2023	19.11.2023	3077.00	25mm	5%	0.00	0.00	214.50000	Complete

[Signature]
30/11/23

Divisional Accounts Officer
RWD Works Division
Madhepura

[Signature]
30/11/23
Executive Engineer
RWD Works Division
Madhepura
[Signature]
30/11/23

Contractor :-DIVAKAR KUMAR

Y = 0 * X ^ 2 + 1.136 * X - 181			
X = 2700			
Y = 2886			
(R) RURAL ROAD			
Good	Average	Poor	
<4000	4001-5000	>5001	

<4000	4001-5000	>5001
-------	-----------	-------

$$\begin{array}{r} 84 \\ 13 \overline{) 109123} \\ \underline{130} \\ 29123 \\ \underline{260} \\ 3123 \\ \underline{260} \\ 523 \\ \underline{40} \\ 123 \end{array}$$

$$Y = 0 * X^2 + 1.136 * X - 181$$

Date	Time	Section	Length	Bumps	Speed	OR	CATEGORY	IRI	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	ROAD				
09/13/23	14:30:24	98	0.1	190	10.1	1900	G	2922	26.04622	87.089	Curve
09/13/23	14:30:59	98	0.1	180	10.1	1800	G	3842	26.04759	87.08999	Normal
09/13/23	14:31:0	98	0.1	160	10.1	1600	G	3656	26.04797	87.09.29	Normal
09/13/23	14:32:0	98	0.1	200	20.2	2000	G	3082	26.04886	87.0906	Normal
09/13/23	14:33:32	98	0.1	160	10.1	1600	G	3616	26.05108	87.09095	Speed Breaker
09/13/23	14:43:32	98	0.1	230	20.2	2300	G	3431	26.05249	87.09126	Normal
09/13/23	14:35:8	98	0.1	320	20.2	3200	G	3454	26.05319	87.09163	Normal
09/13/23	14:36:8	98	0.1	500	10.1	5000	G	3521	26.05387	87.09152	Normal
09/13/23	14:37:0	98	0.1	170	20.2	1700	G	3750	26.56142	87.09174	Culvert
09/13/23	14:37:46	98	0.1	180	20.2	1800	G	3863	26.05677	87.09183	Normal
Average IRI								3497			


Signature
13/10/23
T.T.C

Signature
14/11/23
W

Signature
20/11/23

File :FASTECO-USB-GPS V1_1_118050845.Xls, Section No. :98, Eqn : $Y = 0 * X^2 + 1.136 * X - 181$

Name of Customer :DIWAKAR KUMAR, Name of Work/ Road :Near Mahadalit Tola Natari Risideo House To Jaqdiya



Subbu
13/09/23
J.E

Subbu
13/09/23

Subbu
30/11/23