Format for Inspection of Maintenance Aspects of Completed PMGSY Work

Date of Inspection			04/05/2022							
Name of IE/PQM			IE0097KUMAR							
State Bihar		Division		Madhepura		Block I	Kumarkhand			
Name of Road (From/To)			Construction of Road From Sarhar Mahadalit Tola To Puraini							
Scheme			MMGSY[Gen]							
ATR No			3352							
Year of Clearance		05Ph-4								
Length in Flexible CC/Ot Pavement: (Km)		CC/Other P (Km)	avement	0.50000)	Total (Km)	3.13000		Pavement IN CCFp	2.63000
Estimated Cost	(As Cleared	By GOI)	224.17000							
Maintain work Amount1 Maintain wo		ork Amount2 Maint		intain work Amount3 Mai		Maintai	in work Amount4	Maintain wo	rk Amount5	
1.00000 1.34		1000	2.00000		2.48000		2.87	2.87000		
Cost Upon Completion			196.731150							
The work is a case of(New Connectivity/ Up Gradation)			New Connectivity							
Actual Date of Completion			25/03/2018							

Observation

1. Name of Item/ Activity: Maintenance of raod in respect to restoration of rain cuts as per clause 1902 of the specifications and cutting of branches of

trees shrubs of grass and weeds etc as per clause 1915 of the specifications.

a. Observations: What is the condition of roads in the respect of this item.

No Cutting of branches of trees shurbs and trimming of grass.

b.

Grading for the above item: S/U	If this item is grade U write clear reasons and suggestions for improvement:		
U	Unsatisfied.		

2. Name of Item/ Activity: Restoration of rain cuts and dressing of berms as per clause 1902 of the specifications and making up of shoulders as per

clause 1903 of the specifications.

a. Observations: What is the conditon of road in respect of this item.

No shoulder cut found, shoulder surface good condition.

b.

Grading for the above item: S/U	If this item is grade U write clear reasons and suggestions for improvement:		
s	Acceptable.		

- 3. Condition of pavement including filling pot holes and patch repairs etc as per clause 1904, 1905 and 1906 of the specifications.
- **a. Observations:** What is the condition of road in respect of this item. Detailed observations should be made as to wheather the pavement has photoles,

cracking ravelling etc. Which is causing disturbance/discomfort in driving? if yes, wheather these defects has been repaired properly under routing

maintenance?

b.				A
Observations: What is the pavement condition index(PCI) as per annexure 14.7 para 14.9 of operations manual	5	4	3	<3
		4		

Grading for the above item: S/U

If this item is grade U write clear reasons and suggestions for improvement:

No potholes cracking and reveling were found, No discomfort was observed while driving.

4. Name of Item/ Activity: Maintenance of drains as per clause 1908 of the specification, maintenance of culverts and causeways as per clause 1909

and 1910 of the specifications.

a. Observations: What is the conditon of road in respect of this item.

Culvert has been maintained.

Grading for the above item: S/U	If this item is grade U write clear reasons and suggestions for improvement:		
S	Acceptable.		

5. Name of Item/ Activity: Maintenance of road signs as per clause 1911 of the specification are white washing guard stones re-fixing display guard

stones, white washing parapets of C.D works.

a. Observations: What is the conditon of road in respect of this item.

Road signs were not properly maintained as per specification.

b.

Grading for the above item: S/U	If this item is grade U write clear reasons and suggestions for improvement:
U	Unsatisfied.

6. Name of Item/ Activity: Maintenance of guard rails and parapet rails as per clause 1912 of the specifications, maintenance of 200m and kilo meter

stones as per clause 1913 of the spcifications.

a. Observations: What is the conditon of road in respect of this item.

200 m stones and KM stones were not properly maintained as per specification.

b.

Grading for the above item: S/U	If this item is grade U write clear reasons and suggestions for improvement:		
U	Unsatisfied.		

7. Road Furniture and Markings:

Observations- Item No. 7 a: Quality Road Furniture and Makings:

Main Informatory Board Fixed:	No
Citizen Information Board Fixed:	N/A
Maintenance Board Fixed:	

Grading: Citizen information board, Main informatory board, Quality and wheather fixed during construction.

Grading for the above item: S/U/NA	If this item is grade U write clear reasons and suggestions for improvement:
U	main information board properly not maintained .

Grading: Logo boards, 200m stones and stones, Quality and weather fixed after completion.

Grading for the above item: S/U/NA	If this item is grade U write clear reasons and suggestions for improvement:		
s	Yes, the information in board is given in local language.		

Grading: Maintenance Board Fixed

Grading for the above item: S/U/NA	If this item is grade U write clear reasons and suggestions for improvement:		
U	Maintenance information board properly maintained.		

Observations- Item No. 7 b: Quality Road Furniture and Makings:

* **** ******* ****				
I. Logo Board Fixed:	N/A			
II. 200m. Stones Fixed:	Yes			
III. 1 Km. Stone Fixed:	No			
IV. Guard Stones Fixed on Curves:	N/A			
V. Mandatory and Cautionary Signage:	No			

Grading: Wheather the information in boards is given in local language.

Grading for the above item: S/U/NA	If this item is grade U write clear reasons and suggestions for improvement:
U	Road signs,200 m stones and KM stones were not properly maintained as per specification.

8. Overall Grading:

Grading for the above item: S/U/SRI	If this item is grade U write clear reasons and suggestions for improvement:
U	Road signs, 200 m stones and KM stones were not properly maintained as per specification.



-/UploadFile/2022/May/04-

~/UploadFile/2022/May/04-



 $\frac{05\text{-}}{2022/RoadMaintain ance Image File/Madhepura/2022/April/5700/2.JPG}$



2022/RoadMaintainanceImageFile/Madhepura/2022/April/5700/1.JPG

2022/RoadMaintainanceImageFile/Madhepura/2022/April/5700/7.JPG

~/UploadFile/2022/May/04-



~/UploadFile/2022/May/04-



2022/RoadMaintainanceImageFile/Madhepura/2022/April/5700/5.JPG



~/UploadFile/2022/May/04-



~/UploadFile/2022/May/04-



2022/Road

2022/RoadMaintainanceImageFile/Madhepura/2022/April/5700/8.JPG



~/UploadFile/2022/May/04-



-/UploadFile/2022/May/04-



05- 05- 05- 05- 05- 2022/RoadMaintainanceImageFile/Madhepura/2022/April/5700/10.JPG 2022/RoadMaintainanceImageFile/Madhepura/2022/April/5700/11.JPG 2022/RoadMaintainanceImageFile/Madhepura/2022/April/5700/II.JPG 2022/RoadMaintainanceImageFile/Madhepura/2022/April/5700/II.JPG 2022/RoadMaintainanceImageFile/Madhepura/2022/April/5700/II.JPG 2022/RoadMaintainanceImageFile/Madhepura/2







~/UploadFile/2022/May/04-

05-2022/RoadMaintainanceImageFile/Madhepura/2022/April/5700/13.JPG 2022/RoadMaintainanceImageFile/Madhepura/2022/April/5700/14.JPG 2022/RoadMaintainanceImageFile/Madhepura/2022/April/5700/14.DPG 2022/RoadMaintainanceImageFile/Madhepura/2022/April/5700/14.DPG 2022/RoadMaintainanceImageFile/Madhepura/2022/April/5700/14.DPG 2022/RoadMaintainanceImageFile/Madhepura/2022/April/5700/14.DPG 2022/RoadMaintainanceImageFile/Madhepura/2022/April/5700/14.DPG 2022/RoadMaintainanceImageFile/Madhepura/2022/April/5700/14.DPG 2022/RoadMaintainanceImageFile/Madhepura/2022/RoadMaintainanceImageFile/Madhepura/2022/RoadMaintainanceImageFile/Madhepura