

A/A Vide letter no. - 1447, dt. - 28.2.28

Cost of Initial Rectification
With Surface Renewal- 78.559 Lacs
Cost of 5yrs Maintenance- 28.182 Lacs
Cost of Emergent Repair- 7.856 Lacs

Total- 114.597 Lacs

T/S Amount.

Cost of Initial Rectification 90.265 Lacs 90.265 Lacs
With Surface Renewal- ~~78.559~~ Lacs
Cost of 5yrs Maintenance- ~~28.182~~ Lacs 32.289 Lacs
36.252
Total- 126.517 Lacs 122.549 Lacs

T.S. No.- 289

dt- 15/03/23

Ref. SE Letter No- 305

dt- 15/03/23

Technically Sanctioned for Rs. 126.517 Lacs

(Rupees one crore twenty six lakh fifty
one thousand and seven hundred.) only.

Technically sanction does not mean sanction
of rate Instruction given in technical should be followed strictly.

T.S. No.- 289

dt- 15/03/23

Ref. SE Letter No- 305

dt- 15/03/23

Technically Sanctioned for Rs. 122.549 Lacs

(Rupees one crore twenty two Lacs
Fifty four thousand nine hundred.)

Technically sanction does not mean sanction
of rate Instruction given in technical should be followed strictly.

(Signature)
16/3/23

Chief Engineer-2
Rural Works Department

(Signature)
16.3.23