

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, समस्तीपुर

पत्रांक1212/8180 दिनांक 8/6/23

प्रेषक:— कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, समस्तीपुर।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी—सह—सचिव
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय:— शीर्ष New Maintenance Policy 2018 मद में आवंटन उपलब्ध कराने के संबंध में।
महाशय,

उपर्युक्त विषयक शीर्ष New Maintenance Policy 2018 योजनान्तर्गत निर्मित/निर्माणाधीन पथों का विहित प्रपत्र में अधियाचना पत्र संलग्न कर भेजा जा रहा है। संबंधित पथ की कुल लंबाई 4.20 कि०मी० है जिसमें 2.78 कि०मी० में निर्माण कार्य पूर्ण किया है शेष 1.42 कि०मी० PMGSY Phase-III में अन्तर्गत स्वीकृत है।

अतः अनुरोध है कि संलग्न अधियाचना पत्र के अनुसार आवंटन उपलब्ध कराने की कृपा की जाय।

अनु०—यथोक्त।

विश्वासभाजन

8.6.23

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, समस्तीपुर

FROM GFR 19-A**(See Government of India's Division (I) below Rule- 150)****Form of Utilization Certificate upto 07.06.2023****PIU- E.E., R.W.D. Works Division, Samastipur**

S.N.	Name of Scheme	Sanction No.& Date	Amount Received	Particulars
1	Construction of Rural Road under New Maintenance Policy-2018	Secretary cum Empowered Officer BRRDA Bihar Patna vide upto Lt. no.-81 dt.31.05.2023	457233363.00	Certified that out of Rs.457233363.00 received upto 07.06.2023 in favour of Executive Engineer R.W.D. Works Division Samastipur a sum of Rs.445085325.00 has been utilized for the purpose of New Maintenance Policy-2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 12148038.00 remaining unutilized at the end of period under report.
			45,72,33,363.00	


2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for the which it was sanctioned.

Kind of Checks exercised:-

- i Works have been supervised by Executive/Superintending engineer.
- ii Periodical inspection has been conducted by Executive/Superintending engineer.
- iii Construction materials have been tested.
- iv Measurements have been recorded in the MB's and test check conducted by Assistant Engineer/Executive
- v All other codal formalities have been observed.

3 Physical Progress achieved:-

- i Construction of Road work.
- ii Construction of CD works.



Executive Engineer
Works Division Samastipur
Rural Works Dipartment

Requisition Format for scheme Head : MR(3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

[illegible]

1 Signed Hard Copy and Soft Copy (In Excel) of recorded IRI is enclosed.

2 Up-to-date Physical Progress has been uploaded in MIS

8.6.20
HN

**Executive Engineer
RWD (W) Div. Samastipur**

Name of Road :- SH To Madanpur

Section no.-48

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD			
8/6/23	11: 6: 7	48	0.1	250	0	2500	2972	G	26.007786	85.697124	Normal
8/6/23	11: 6: 42	48	0.1	230	10.1	2300	2745	G	26.007868	85.695774	Normal
8/6/23	11: 7: 18	48	0.1	220	10.1	2200	2631	G	26.007673	85.693718	Normal
8/6/23	11: 7: 45	48	0.1	240	10.1	2400	2858	G	26.007551	85.694645	Normal
8/6/23	11: 8: 6	48	0.1	220	10.1	2200	2631	G	26.007628	85.696183	Normal
8/6/23	11: 8: 39	48	0.1	230	10.1	2300	2745	G	26.007715	85.697213	Normal
8/6/23	11: 9: 4	48	0.1	240	10.1	2400	2858	G	26.007745	85.698006	Normal
8/6/23	11: 9: 54	48	0.1	250	10.1	2500	2972	G	26.007513	85.699086	Curve
8/6/23	11: 10: 14	48	0.1	240	10.1	2400	2858	G	26.007409	85.700048	Normal
8/6/23	11: 10: 50	48	0.1	230	10.1	2300	2745	G	26.007186	85.70107	Normal
8/6/23	11: 11: 3	48	0.1	220	10.1	2200	2631	G	26.006885	85.702376	Normal
8/6/23	11: 11: 44	48	0.1	230	10.1	2300	2745	G	26.006566	85.703314	Normal
8/6/23	11: 12: 4	48	0.1	220	10.1	2200	2631	G	26.006111	85.7043	Normal
8/6/23	11: 12: 42	48	0.1	230	10.1	2300	2745	G	26.005781	85.704921	Normal
8/6/23	11: 13: 3	48	0.1	240	10.1	2400	2858	G	26.00518	85.705708	Normal
8/6/23	11: 13: 14	48	0.1	230	10.1	2300	2745	G	26.004893	85.706203	Normal
8/6/23	11: 14: 11	48	0.1	210	10.1	2100	2518	G	26.00429	85.707166	Normal
8/6/23	11: 14: 41	48	0.1	240	10.1	2400	2858	G	26.004061	85.708004	Curve
8/6/23	11: 15: 19	48	0.1	230	10.1	2300	2745	G	26.003946	85.708941	Normal
8/6/23	11: 15: 34	48	0.1	240	10.1	2400	2858	G	26.003915	85.70976	Normal

08/6/23


Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD			
8/6/23	11:16:1	48	0.1	230	10.1	2300	2745	G	26.003893	85.710644	Normal
8/6/23	11:16:29	48	0.1	230	10.1	2300	2745	G	26.003058	85.710706	Normal
8/6/23	11:17:4	48	0.1	240	10.1	2400	2858	G	26.002156	85.710716	Normal
8/6/23	11:17:44	48	0.1	230	10.1	2300	2745	G	26.001381	85.711056	Curve
8/6/23	11:18:11	48	0.1	230	10.1	2300	2745	G	26.000079	85.711198	Normal
8/6/23	11:18:40	48	0.1	240	10.1	2400	2858	G	26.000051	85.711249	Normal
8/6/23	11:19:9	48	0.1	230	10.1	2300	2745	G	25.999241	85.711345	Normal
Total =			2.700	Avg.			2770.00				

8.6.23

Executive Engineer
R.W.D.(W) Division,
Samastipur

8/6/23

File : C:\Users\USER\Desktop\SH To Madanpur\08061119.Xls, Section No. : 48, Eqn : $Y = 0 * X^2 + 1.136 * X +$
Name of Customer : Sona Infracon Pvt. Ltd., Name of Work/ Road : SH TO MADANPUR, Lab Job number : 48



[Signature]

[Signature]