

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सिकहरना, ढाका।

पत्रांक - 286 (286) / सिकहरना, ढाका, दिनांक - 10-06-23

प्रेषक :-

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सिकहरना, ढाका।

सेवा में,


अपर मुख्य कार्यपालक पदाधिकारी,
ग्रामीण कार्य विभाग,
विश्वसरैया भवन, पाच्चा तल्ला, बिहार, पटना।

विषय :- M/R (3054) New Maintenance Police 2018 योजना हेतु आवंटन अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में सूचित करना है कि इस प्रमंडलान्तर्गत M/R (3054) New Maintenance Police 2018 योजना के अधीन कराये गये कार्य के विरुद्ध भुगतान हेतु आवंटन अधियाचना विहित-प्रपत्र में संलग्न कर समर्पित किया जाता है।
अनुलग्नक :- यथोक्त।

विश्वासभाजन



10.6.23
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग, कार्य प्रमंडल,
सिकहरना, ढाका।
10/06/23

MR-3054 (New Maintenance Policy-2018) के पथों में कराये गये पुनर्स्थापन कार्य हेतु अधियाचना प्रपत्र

Name of the Division :- Rural Works Department, Works Div. Dhaka

क्र०	पथ का नाम	प्रखंड का नाम	पथ की लंबाई	प्रशासनिक स्वीकृत के अनुसार				एकरारनामा के अनुसार		आकास्मिक व्यय की राशि तकनीकी स्वीकृति के अनुसार (लाख में)	कार्य पूर्ण करने की तिथि (एकरारनामा के अनुसार)	अब तक प्राप्त आवंटन (लाख में)	अब तक भुगतान की गई राशि (लाख में)	पुनर्स्थापन का कराये गये कार्य अधियाचित राशि (लाख में)	कार्य की भौतिक स्थिति	अभियुक्ति
				मूल कार्य की राशि (लाख में)	पंचवर्षिय अनुरक्षण की राशि (लाख में)	कुल राशि (लाख में)	प्रशासनिक स्वीकृति का प्रसंग	मूल कार्य की राशि (लाख में)	पंचवर्षिय अनुरक्षण की राशि (लाख में)							
1	East Champaran Jila Antargat Dhaka Chainpur Muaky marg to Jhora Ram Brahman Toli Hote Raksa Marg Seth hote Mukhya path tak Sadak nirman	ढाका	2.28	159.17300	24.00900	199.09000	2089/06.05.2022, 2090/06.05.2022 & 545/31.05.2023	175.37784	24.40182	-	01.09.2023 31.05.2023	175.36842	173.85506	9.22548	Com.	
2	Dhaka Karsahiya Path to Mushari tola hote hue Raksa Shyam Bakhyi path	ढाका	3.775	160.34900	50.49200	226.87000		175.38682	52.40428	-		175.37350	174.58261	9.24364	Com.	
Total :-				319.52200	74.50100	425.96000		350.76466	76.80610			350.74192	348.43767	18.46912		


 Divisional Accounts Officer
 Rural Works Div, Dhaka


 Executive Engineer
 RWD (W) Div. Dhaka
 10/6/23

FORM GFR 19-A

(See Government of Indian's Decision (1) below Rule-150)
Form of Utilization Certificate Upto the Month of upto.....

MR-3054 (New Maintenance Policy)

PIU :- EE RWD (W) DIVISION DHAKA

Sl.	Name of the Scheme	Sanction No. & Date with Amount (Rs. In Lakh)	Amount Received (Rs. In Lakh)	Particulars
1	Construction of Rural Roads Under MR-3054 (New maintenance Policy)			Certified that out of Rs. ...<u>304,01,825</u>..... Lacs received the year 2023-24 in favor of Executive Engineer, R.W.D. (W), Division Dhaka a sum of Rs. <u>304,01,825</u>... lacks has been utilized for the purpose of MR-3054 (New Maintenance Policy) Schemes as given in the margin for which it was sanctioned of Rs.....<u>Nil</u>..... Remaining unutilized at the end of the period under.
Total :-				

Certified that I have satisfied my self that the condition on which the grants-in-aid was sanctioned have been duly fulfilled are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

10/6-23
Divisional Account Officer

R.W.D. (W) Div., Dhaka

Kind of Checks Exercised :-

- Works have been supervised by Executive Engineer/Superintending Engineer.
- Periodical inspection has been conduct by Executive Engineer/Superintending Engineer.
- Construction material have been tested.
- Measurement have been recorded in the MBs and test check conducted by the Assistant.
- All other codal Formalities have been observed.

Physical Progress achieved :-

- Construction of Road Works.
- Construction of CD Works.

10.6.23
Executive Engineer

R.W.D.(W) Div., Dhaka

10/6/23

Name of Contractor:- Priyanka Kumari

Name of Road:-Dhaka Karsahiya Path to Mushari tola hote hue Raksa Shyam Bakhyi Path

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event
9/12/22	13:32:40	68	0.1	280	20.2	2800	2533	G	26.727278	85.15559	Normal
9/12/22	11:55:42	68	0.1	200	0	2000	1880	G	26.72659	85.155428	Normal
9/12/22	11:56:0	68	0.1	200	10.1	2000	2580	G	26.725133	85.154979	Normal
9/12/22	11:56:18	68	0.1	170	20.2	1700	1636	G	26.724612	85.154757	Normal
9/12/22	11:56:18	68	0.1	190	10.1	1900	2799	G	26.723721	85.154364	Normal
9/12/22	11:57:0	68	0.1	170	20.2	1700	2636	G	26.722783	85.154506	Curve
9/12/22	11:57:28	68	0.1	230	10.1	2300	2125	G	26.72199	85.154705	Normal
9/12/22	11:57:28	68	0.1	170	20.2	1700	1636	G	26.721462	85.154427	Normal
9/12/22	11:58:3	68	0.1	370	10.1	3700	3268	G	26.720554	85.153737	Normal
9/12/22	11:59:0	68	0.1	360	20.2	3600	3186	G	26.720152	85.153339	Normal
9/12/22	11:59:13	68	0.1	390	20.2	3900	3431	G	26.720138	85.152082	Normal
9/12/22	12:0:0	68	0.1	390	10.1	3900	3431	G	26.7194	85.151656	Normal
9/12/22	12:0:24	68	0.1	300	20.2	3000	2696	G	26.718846	85.151421	Normal
9/12/22	12:0:24	68	0.1	200	20.2	2000	2880	G	26.718033	85.150944	Normal
9/12/22	12:0:24	68	0.1	140	20.2	1400	2391	G	26.717296	85.150246	Normal
9/12/22	12:1:0	68	0.1	160	20.2	1600	1554	G	26.716452	85.150085	Normal
9/12/22	12:1:35	68	0.1	360	10.1	3600	3186	G	26.714933	85.14954	Normal
9/12/22	12:2:10	68	0.1	210	20.2	2100	1962	G	26.714316	85.14894	Normal
9/12/22	12:2:45	68	0.1	230	20.2	2300	2125	G	26.713735	85.149208	Normal
9/12/22	12:3:0	68	0.1	200	20.2	2000	2880	G	26.712625	85.148789	Normal
9/12/22	12:3:20	68	0.1	290	10.1	2900	2615	G	26.71096	85.14807	Normal
9/12/22	12:3:20	68	0.1	240	20.2	2400	2207	G	26.710406	85.147806	Normal
9/12/22	12:3:56	68	0.1	220	20.2	2200	2044	G	26.709366	85.147396	Curve
9/12/22	12:4:0	68	0.1	170	20.2	1700	3636	G	26.708638	85.14696	Normal
9/12/22	12:4:31	68	0.1	200	20.2	2000	1880	G	26.707973	85.146751	Normal
9/12/22	12:5:6	68	0.1	300	10.1	3000	2696	G	26.706921	85.146294	Normal
9/12/22	12:5:6	68	0.1	200	20.2	2000	2880	G	26.706148	85.145799	Normal
9/12/22	12:5:6	68	0.1	300	20.2	3000	2696	G	26.705556	85.145379	Normal
9/12/22	12:5:41	68	0.1	150	20.2	1500	1472	G	26.704919	85.145242	Normal
9/12/22	12:5:41	68	0.1	150	20.2	1500	1472	G	26.704576	85.145143	Curve

Subendra-Kr
09.12.22 (5:5)

Signature
9.12.22
EE

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event
9/12/22	12:6:0	68	0.1	170	20.2	1700	1636	G	26.704028	85.145009	Normal
9/12/22	12:6:17	68	0.1	220	10.1	2200	2044	G	26.702869	85.145103	Curve
9/12/22	12:7:0	68	0.1	270	10.1	2700	2452	G	26.702718	85.146135	Normal
9/12/22	12:7:0	68	0.1	340	10.1	3400	3023	G	26.702522	85.146895	Normal
9/12/22	12:7:27	68	0.1	240	20.2	2400	2207	G	26.702415	85.148058	Normal
9/12/22	12:8:3	68	0.075	390	10.1	3900	3431	G	26.702393	85.14834	Curve
Total Length			3.775		Total IRI		97272				
					Avg. IRI		2559.789				


Subendrakar
09.12.22
J-E

~~Subendrakar~~
9.12.22
ET

Name of Customer: PRAYANKA KUMARI
 Name of Work/Road: Dhaka Karsahya path to Muchari
 Lab Job number: 58
 Date: 12/9/2022
 Section No.: 58

Test Date: 12/9/2022 Road Name: to Folsn Slip/om Bhobhari path
 Machine No: 378 Road Type: (A) ASPHALTIC
 Start S. No.: Side:
 Start E. No.: U/V Range: 391 To 4800 Interval 1000 mm/ft
 Start Location: Dist Range: 0 To 0.78 0.02 1.000 m
 End Location: Equation: Best

Print Generate Report and Graph Redraw Graph Map View



Subendakr
 09.12.22
 J.E

9.12.22
 EC