

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, त्रिवेणीगंज।

पत्रांक11.09.2023/ त्रिवेणीगंज,
प्रेषक,

दिनांक 16.06.2023/

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, त्रिवेणीगंज।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह- सचिव,
ग्रामीण कार्य विभाग,
बिहार, पटना।

विषय :-

MR-3054 (New Maintenance Policy-2018) योजनान्तर्गत राशि विमुक्ति हेतु
अधियाचना समर्पित करने के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में कहना है कि MR-3054 (New Maintenance Policy-2018) योजनान्तर्गत अधियाचना इस पत्र के साथ संलग्न विहित प्रपत्र में तैयार कर समर्पित की जा रही है।

अतः अनुरोध है कि आवंटन उपलब्ध कराने की कृपा की जाय।

विश्वासभाजन

कार्यपालक अभियंता
ग्रामीण कार्य विभाग

कार्य प्रमंडल, त्रिवेणीगंज।

Rural Works Department

Requisition Format for Scheme Head- MR (3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Division :- Triveniganj

S. No	Package No	Name of Road	Project ID as per MIS	Administ rative Approval (AA) Letter No & Date	Administrative Approval (AA)		Agreement Amount (In Lacs)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	Up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in Km.)	Amount of (in Lacs)	Initial Rectification and Surface Renewal (in Lakh)	5 Years Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	MR-N/22-23-TRIVENIG AN/18.	T01 to Narhaya	21005102022	Letter No- 2011, dated 02.05.22	2.585	183.109	172.26685	28.25421	29 MBU/MR-3054-2022 23	02.01.2024	Ongoing	2923	25	5.01	0.00000	102.25690	102.25690	Ongoing
2	MR-N/2020-21- Triveniganj/ 11	Pethra Jolhanjwan to Ratauli Chowk.	210511034342	654 10.02.20	9.582	384.07620	250.71990	107.77631	21/MBU/ MR-3054/ 2020-21	05.01.2022	Completed	2936	25	5.01	187.70741	234.97900	47.27159	Completed
3	MR-N/22-23- TRIVENIG AN/12	Mareshwar Singh House to Hatwaraya Pakki Sadak via Pokhar	21005113010	Letter No- 2012, dated 02.05.22	3.507	198.290	147.45155	39.77787	26/MBU/ MR-3054/ 2022-23	07.09.2023	Completed	2953	25	5.01	0.00000	147.40205	147.40205	Completed
4	MR-N/22-23- TRIVENIG AN/03.	Laxmipur Triveniganj PMGSY Road to Bhatabari	21005112021	Letter No- 2011, dated 02.05.22	2.350	251.850	214.04919	22.33569	21/MBU/ MR-3054/ 2022-23	07.09.2023	Completed	3127	25	5.01	0.00000	214.02130	214.02130	C
Total					18.024	1017.32520	784.48749	198.14408							187.70741	698.65925	510.95184	

Executive Engineer
R.W.D. (W.D.) Triveniganj

6/16/23

6/16/23

FORM GFR - 19 - A
(See Government of India's Decision (i) below Rule - 150)
Form of Utilization Certificate up to 16.06.2023
(Programming Fund)

Sl. N.	Name of Scheme	Sanction No. & Date with Amount (in Lac.)	Total Amount Received (in Lac.)	Particulars
1	2	3	4	5
1.	Construction of Rural Road under MR-3054 (Bihar Rural Road Maintenance Policy)	Total Allotment received vide Secretary-cum-Empowered Officer BRRDA, Additional CEO, Patna. Letter No-29 Dated-01.03.2023 Letter No-53 Dated-25.03.2023 Letter No-63 Dated-13.04.2023 Letter No-68 Dated-29.04.2023 Letter No-81 Dated-31.05.2023 Letter No-85 Dated-31.05.2023	Rs- 7477.48736	Total Allotment Rs.- 7477.48736 Lakh CFMS Expenditure Rs.- 7152.64196 Lakh Balance Rs.- 324.84540 Lakh
2.	Certified that I have satisfied myself that the condition on which the grants in aid sanctioned have been duly fulfilled / are being fulfilled and that I have Exercised the following Checks to see that the money was actually utilized for the purpose for which it was sanctioned.		Total 6834.48671	
	i) Works have been supervised by Executive Engineer / Superintending Engineer. ii) Periodical inspection has been conducted by A.E. / Executive Engineer / Superintending Engineer. iii) Construction materials have been tested. iv) Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer / Executive Engineer. v) All other Codal formalities have been observed.			

16.6.2023
 Executive Engineer
 RWD, Works Division, Triveniganj

Name of Customer : Sanjay Kumar
Name of Work/ Road : Laxmipur Triveniganj PMGSY R
Lab Job number : 99
Date : 6/16/2023
Section No. : 99


Test Date : 6/16/2023 Road Name : nj PMGSY Road to Bhantabari.
Machine No : Road Type : (R) RURAL ROAD
Start S No : Side :
Start E No : Interval
Weather : UIV Range : 1305 To 5000 1000 mm/km
Start Location : Laxmipur Dist Range : 0 To 25 0.1 * 1000 m
End Location : to Bhantabari. Equation : $Y = 0 * X^2 + 0.998 * X + 109.5$

Print

Generate Report and Graph

Redraw Graph


Map View



SK
16.06.23
J.E

6/16/23
Executive Engineer
RWD (W) Divn. Triveniganj

File : C:\Users\RWD\OneDrive\Desktop\LAXMI PUR BHANTABARI.Xls, Section No. :99, Eqn : $Y = 0 \cdot X^2 + 0.998 \cdot X$
 Name of Customer : Sanjay Kumar, Name of Work/ Road : Laxmipur Triveniganj PMGSY Road to Bhantabari, Lab



S.K.
16.06.23
J.E

Executive Engineer
RWD (W) Divn. Triveniganj

16.6.23

Name of Road :- Laxmipur Triveniganj PMGSY Road to Bhantabari.

Length :- 2.350 K.M.

Name of Contractor :- Sanjay Kumar

Project Id :- 21005112021

Agreement No. :- 21MBD/MR-3054/22-3

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event			
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD				Y = 0 * X ^ 2 + 0.998 * X + 109.5		
16/6/23	11:41:7	99	0.1	250	10.1	2500	2604	G	26.141667	86.811852	Normal	X = 2300		
16/6/23	11:43:0	99	0.1	280	10.1	2800	2903	G	26.141448	86.81182	Normal	Y = 2404		
16/6/23	11:43:28	99	0.1	220	10.1	2200	2305	G	26.140634	86.811433	Normal			
16/6/23	11:44:0	99	0.1	260	10.1	2600	2704	G	26.140863	86.811469	Normal			
16/6/23	11:44:3	99	0.1	280	10.1	2800	2903	G	26.139954	86.811106	Normal	(R) RURAL ROAD		
16/6/23	11:46:24	99	0.1	290	10.1	2900	3003	G	26.139378	86.810965	Normal	Good	Average	Poor
16/6/23	11:47:0	99	0.1	330	10.1	3300	3402	G	26.138424	86.810667	Curve	<4000	4001-5000	>5001
16/6/23	11:47:0	99	0.1	350	10.1	3500	3602	G	26.138025	86.810589	Normal			
16/6/23	11:47:35	99	0.1	320	10.1	3200	3303	G	26.13757	86.810573	Curve			
16/6/23	11:48:10	99	0.1	310	10.1	3100	3203	G	26.136665	86.810754	Curve			
16/6/23	11:48:10	99	0.1	240	10.1	2400	2504	G	26.135935	86.811194	Curve			
16/6/23	11:49:0	99	0.1	320	10.1	3200	3303	G	26.135156	86.811742	SpeedBreaker			
16/6/23	11:49:21	99	0.1	300	10.1	3000	3103	G	26.134958	86.812156	Curve			
16/6/23	11:50:0	99	0.1	320	10.1	3200	3303	G	26.134368	86.812498	Curve			
16/6/23	11:50:0	99	0.1	330	10.1	3300	3402	G	26.133962	86.81269	SpeedBreaker			
16/6/23	11:50:31	99	0.1	260	10.1	2600	2704	G	26.133226	86.812981	Culvert			
16/6/23	11:51:7	99	0.1	340	10.1	3400	3502	G	26.132442	86.813991	SpeedBreaker			
16/6/23	11:51:42	99	0.1	350	10.1	3500	3602	G	26.132219	86.814493	Normal			
16/6/23	11:52:17	99	0.1	310	10.1	3100	3203	G	26.131712	86.814585	Curve			
16/6/23	11:52:17	99	0.1	280	10.1	2800	2903	G	26.13155	86.81463	Curve			
16/6/23	11:53:0	99	0.1	310	10.1	3100	3203	G	26.130871	86.814593	Normal			
16/6/23	11:53:28	99	0.1	310	10.1	3100	3203	G	26.13002	86.814981	Normal			
16/6/23	11:54:0	99	0.1	290	10.1	2900	3003	G	26.12965	86.81509	SpeedBreaker			
16/6/23	11:54:3	99	0.05	250	10.1	2500	2604	G	26.128614	86.815467	Normal			
Average							3127							

SK
16.06.23
Jt

16.6.23
/ Executive Engineer
RWD (W) Divn. Triveniganj

Lab Job number :99

Date :6/16/2023

Name of Customer :Sanjay Kumar

Name of Work/ Road :Laxmipur Triveniganj PMGSY Road to Bhantabari.

Sr.no	Location of Corrected U.I test(in km) value(mm/km)	Road catagory
-------	---	---------------

2	0.1	2604 G
3	0.2	2903 G
4	0.3	2305 G
5	0.4	2704 G
6	0.5	2903 G
7	0.6	3003 G
8	0.7	3402 G
9	0.8	3602 G
10	0.9	3303 G
11	1	3203 G
12	1.1	2504 G
13	1.2	3303 G
14	1.3	3103 G
15	1.4	3303 G
16	1.5	3402 G
17	1.6	2704 G
18	1.7	3502 G
19	1.8	3602 G
20	1.9	3203 G
21	2	2903 G
22	2.1	3203 G
23	2.2	3203 G
24	2.3	3003 G
25	2.4	2604 G

SK
16.06.23
J.E

h/16.6.23
Executive Engineer
RWD (W) Divn. Triveniganj