

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, समस्तीपुर

पत्रांक ...1283 अशुदिनांक. 22/6/23

प्रेषक:— कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, समस्तीपुर।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय:— शीर्ष New Maintenance Policy 2018 मद में आवंटन उपलब्ध कराने के संबंध में।
महाशय,

उपर्युक्त विषयक शीर्ष New Maintenance Policy 2018 योजनान्तर्गत निर्मित/
निर्माणाधीन पथों का विहित प्रपत्र में अधियाचना पत्र संलग्न कर भेजा जा रहा है।

अतः अनुरोध है कि संलग्न अधियाचना पत्र के अनुसार आवंटन उपलब्ध कराने की कृपा
की जाय।

अनु०—यथोक्त।

विश्वासभाजन

22.6.23

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, समस्तीपुर

FROM GFR 19-A**(See Government of India's Division (I) below Rule- 150)****Form of Utilization Certificate upto 21.06.2023****PIU- E.E., R.W.D. Works Division, Samastipur**

S.N.	Name of Scheme	Sanction No.& Date	Amount Received	Particulars
1	Construction of Rural Road under New Maintenance Policy-2018	Secretary cum Empowered Officer BRRDA Bihar Patna vide upto Lt. no.-85 dt.14.06.2023	464083663.00	Certified that out of Rs.464083663.00 received upto 21.06.2023 in favour of Executive Engineer R.W.D. Works Division Samastipur a sum of Rs.450347590.00 has been utilized for the purpose of New Maintenance Policy-2018 Schemes as given in the margine for which it was sanctioned and that the balance of Rs. 13736073.00 remaining unutilized at the end of period under report.
			46,40,83,663.00	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for the which it was sanctioned.

Kind of Checks exercised:-

- i Works have been supervised by Executive/Superintending engineer.
- ii Periodical inspection has been conducted by Executive/Superintending engineer.
- iii Construction materials have been tested.
- iv Measurements have been recorded in the MB's and test check conducted by Assistant Engineer/Executive
- v All other codal formalities have been observed.

3 Physical Progress achieved:-

- i Construction of Road work.
- ii Construction of CD works.

21.6.20

Executive Engineer
Works Division Samastipur
Rural Works Dipartment

RWD. Works Division : Samastipur

- 1 Signed Hard Copy and Soft Copy (In Excel) of recorded IRI is enclosed.
- 2 Up-to-date Physical Progress has been uploaded in MIS

**Executive Engineer
RWD (W) Div. Samastipur**

Name of Customer :Pratyaksha Const. Pvt. Ltd.

Name of Work/ Road :Didhara Panchyat Vishanpur More at House of Sanjay Paswan to Redio Station

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI TEGORY mm/km ROAD	Latitude	Longitude	Event
21/6/23	10:7:0	82	0.1	210	0	2100	2063 G	25.94418	85.690992	Culvert
21/6/23	10:8:6	82	0.1	250	10.1	2500	2458 G	25.944503	85.689998	Normal
21/6/23	10:8:6	82	0.1	190	20.2	1900	1865 G	25.944925	85.689192	Normal
21/6/23	10:8:42	82	0.1	120	30.3	1200	1173 G	25.945695	85.688888	Normal
21/6/23	10:8:42	82	0.1	270	30.3	2700	2656 G	25.946647	85.689007	Curve
21/6/23	10:9:0	82	0.1	200	30.3	2000	1964 G	25.947315	85.68838	Normal
21/6/23	10:9:17	82	0.1	180	30.3	1800	1766 G	25.947963	85.68771	Normal
21/6/23	10:9:17	82	0.1	170	20.2	1700	1667 G	25.948703	85.687103	Normal
21/6/23	10:10:0	82	0.1	260	10.1	2600	2557 G	25.949398	85.686397	Normal
21/6/23	10:10:0	82	0.1	230	20.2	2300	2261 G	25.949957	85.68569	Normal
21/6/23	10:10:27	82	0.1	260	10.1	2600	2557 G	25.950592	85.684898	Normal
21/6/23	10:10:27	82	0.1	160	20.2	1600	1568 G	25.951187	85.684175	Normal
21/6/23	10:11:3	82	0.1	260	30.3	2600	2557 G	25.951745	85.68342	Normal
21/6/23	10:11:38	82	0.1	280	10.1	2800	2755 G	25.95247	85.682727	Normal
21/6/23	10:12:0	82	0.1	220	20.2	2200	2162 G	25.95307	85.68202	Normal
21/6/23	10:12:13	82	0.1	200	30.3	2000	1964 G	25.953657	85.681312	Normal
21/6/23	10:12:13	82	0.1	130	30.3	1300	1272 G	25.954315	85.680655	Normal
21/6/23	10:12:13	82	0.1	160	30.3	1600	1568 G	25.955023	85.679915	Normal
21/6/23	10:12:49	82	0.1	190	20.2	1900	1865 G	25.955865	85.679628	Normal
21/6/23	10:13:0	82	0.1	180	30.3	1800	1766 G	25.956243	85.678803	Normal
21/6/23	10:13:0	82	0.1	270	30.3	2700	2656 G	25.95663	85.677878	Normal
21/6/23	10:13:24	82	0.1	270	30.3	2700	2656 G	25.957262	85.677153	Normal
21/6/23	10:13:24	82	0.1	180	30.3	1800	1766 G	25.957938	85.676515	Normal
21/6/23	10:13:24	82	0.1	130	30.3	1300	1272 G	25.958465	85.675673	Normal
21/6/23	10:13:24	82	0.1	240	20.2	2400	2360 G	25.958847	85.674763	Normal
21/6/23	10:14:0	82	0.1	180	20.2	1800	1766 G	25.958945	85.673838	Normal
21/6/23	10:15:10	82	0.1	180	10.1	1800	1766 G	25.958668	85.672945	Normal
21/6/23	10:16:0	82	0.1	230	10.1	2300	2261 G	25.9592	85.672305	Normal
21/6/23	10:16:20	82	0.1	130	30.3	1300	1272 G	25.95998	85.67212	Normal
21/6/23	10:16:50	82	0.1	230	30.3	2300	2261 G	25.960447	85.671737	Normal

$$Y = 0 * X^2 + 0.989 * X - 13.58$$

$$X = 2300$$

$$Y = 2261$$

(R) RURAL ROAD

Good <4000
Average 4001-5000
Poor >5001

2016

376


IRI Value

Machine No.

21/06/2023
21/06/2023
21/06/2023

21/06/2023

File : D:\Pratyaksha Const Pvt. Ltd\21061016.Xls. Section No. :82. Eqn : $Y = 0 \cdot X^2 + 0.989 \cdot X - 13.58$
 Name of Customer : Pratyaksha Construction Pvt. Ltd. Name of Work/ Road : Didhara Panchyat Vishanpur More at



21.6.23
A.E

(Pratyaksha Const)
21/06/2023
A.E

21/06/2023
A.E