

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल- बक्सर

पत्रांक- 944 अउ/बक्सर

दिनांक- 23/06/23

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल- बक्सर

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण (BRRDA)
बुद्ध मार्ग, पटना।

विषय- शीर्ष 3054 (बिहार ग्रामीण पथ अनुरक्षण नीति- 2018) योजना अंतर्गत राशि की अधियाचना के सम्बन्ध में।

महाशय,

उपर्युक्त विषय के सम्बन्ध में कहना है कि योजना शीर्ष 3054 मरम्मति (बिहार ग्रामीण पथ अनुरक्षण नीति- 2018) अंतर्गत कराये गए कार्यों के भुगतान हेतु राशि की आवश्यकता है जिसे अधियाचना प्रपत्र के साथ सलग्न कर भेजा जा रहा है।

अतः श्रीमान से अनुरोध है कि सलग्न विवरणी के अनुसार आवंटन उपलब्ध कराने की कृपा की जाए ताकि संवेदकों द्वारा कराये गए कार्य का भुगतान किया जा सके।

अनु०- यथोक्त

विश्वासभाजन

23.06.23

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर

23/06/23

FORM GFR 19-A
(SEE Government of India's Decision (I) below Rule-150)
Form of Utilisation Certificate upto the month of Dec 2018

MR (3054) New Maintenance Policy 2018

PIU - RWD (W), Div.- Buxar

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
1	Construction of Rural Roads under MR (3054) Maintenance	Lt. No.- 89, dt.-21.06.2023	9059.73233	Certified that out of Rs. 9059.73233 lacs received during the years in favour of Ex. Engineer, RWD (W), Div.- Buxar Bihar, a sum of Rs 9048.41963 lacs been utilized for the purpose of MR (3054) New Maintenance Policy 2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs 11.31270 lacs remaining unutilized at the end of the period under

Total -

- 2 Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/ Supertending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Supertending Engineer.
- Construction materials have been tested
- Measurements have been recorded in the MBs and test check conducted by the Assistant.
- All other codal formalities have been observed.

- 3 **Physical Progress achieved :-**

- Construction of Road works
- Construction of CD works

Executive Engineer
23/06/23

R.W.D. (w) Div. Buxar

AK
23/06/23

Requisition Format for Scheme Head- MR (3054) under Bihar Rural Road Maintenance Policy- 2018 (Initial Rectification and Surface Renewal)

Name of Works Division- RWD, Works Division- Buxar

Sl No	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lakh)		Agreement No. & Date	Date Of Completion as per Agreement	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Alloted Amount (in Lakh)	up-to-date expenditure against work as per MIS (in Lakh)	Requisition done (in Lakh)	Remarks
					Length (in Km)	Amount (in Lakh)	Initial Rectification With Surface Renewal (in Lakh)	5 Years Routine Maintenance (in Lakh)									
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
1	RM/BU/BU X/22/0011	South Lodhas Nahar Road To Englishpur Village Tak Path Nirman	10401912005	Letter No 1486 & 8/09/2022	2.5	75.11	61.43484	23.68275	02/MBD/2023-24 & 12.01.204.2023	19/10/2023	2340	25 mm	5.00%	0.0000	0.0000	61.40370	

1. Signed Hard Copy and Soft Copy (in excel) of recorded IRI is enclosed
2. Up-to-date Physical Progress has been uploaded in MIS


Executive Engineer
RWD (W), Div.- Buxar
23.06.23
23/06/23

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, बक्सर


का0आ0स...945... बक्सर/ दिनांक...23/06/23

कार्यालय आदेश


प्रमाणित किया जाता है कि बिहार ग्रामीण पथ अनुरक्षण नीती-2018 योजनान्तर्गत South Lohdas Nahar Road to Englishpur Village tak path Nirman पथ का कार्य गुणवत्ता एवं विशिष्टियों के अनुरूप पूर्ण कराया गया है। पथ के मापीपुस्त की जाँच मेरे द्वारा 10 प्रतिशत, 50 प्रतिशत सहायक अभियंता एवं कनीय अभियंता के द्वारा शत प्रतिशत किया गया है।



कनीय अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रशाखा इटादी




सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रशाखा इटादी



कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर

File : G:\BHAGWAN DUBEY\3rd road\23060620.Xls. Section No. : 86. Eqn : $Y = 0 \cdot X^2 + 0.816 \cdot X + 249$

Name of Customer : Shree Bhagwan Dubey. Name of Work/ Road : South Lohdas Nahar Road To Englishpur village



23/06/23
JE

Prabodh
23.06.23
AB

23/06/23

Name of Road:-South Lohdas Nahar Road to Englishpur Village tak Path Nirman Contractor Name:-Shree Bhagwan Dubey

Date	Time	Section	No.	Length in km	Bumps in mm	Rate	Speed mm/km	OR mm/km	IRI CATEGORY ROAD	Latitude	ongitude	Event
23/6/23	6:7:41	86	0.1	289	0	2800	2533 G	25.37652	84.6244 Normal	X = 4242		
23/6/23	6:8:0	86	0.1	189	10.1	1800	1717 G	25.37681	84.61615 Normal	Y = 3710		
23/6/23	6:8:17	86	0.1	259	10.1	2500	2288 G	25.37764	84.6143 Normal			
23/6/23	6:8:52	86	0.1	319	10.1	3100	2778 G	25.37776	84.60403 Normal			
23/6/23	6:9:0	86	0.1	189	10.1	1800	1717 G	25.37787	84.59393 Normal			
23/6/23	6:9:27	86	0.1	229	10.1	2200	2044 G	25.37793	84.5838 Normal			
23/6/23	6:9:27	86	0.1	219	10.1	2100	1962 G	25.37796	84.5739 Normal			
23/6/23	6:9:27	86	0.1	209	10.1	2000	1880 G	25.37791	84.56363 Normal			
23/6/23	6:10:3	86	0.1	209	10.1	2000	1880 G	25.37765	84.55387 Normal			
23/6/23	6:10:3	86	0.1	209	10.1	2000	1880 G	25.37747	84.5441 Normal			
23/6/23	6:10:38	86	0.1	209	10.1	2000	1880 G	25.37739	84.534 Normal			
23/6/23	6:11:13	86	0.1	229	10.1	2200	2044 G	25.37721	84.52457 Normal			
23/6/23	6:11:13	86	0.1	239	10.1	2300	2125 G	25.37728	84.51463 Normal			
23/6/23	6:11:48	86	0.1	229	10.1	2200	2044 G	25.37734	84.50403 Normal			
23/6/23	6:12:0	86	0.1	239	10.1	2300	2125 G	25.37736	84.49377 Normal			
23/6/23	6:12:24	86	0.1	229	10.1	2200	2044 G	25.37736	84.4842 Normal			
23/6/23	6:12:24	86	0.1	219	10.1	2100	1962 G	25.37737	84.4771 Normal			
23/6/23	6:13:0	86	0.1	229	10.1	2200	2044 G	25.37648	84.4749 Normal			
23/6/23	6:13:0	86	0.1	229	10.1	2200	2044 G	25.37603	84.46852 Normal			
23/6/23	6:14:0	86	0.1	299	10.1	2900	2615 G	25.37585	84.45925 Normal			
23/6/23	6:14:10	86	0.1	279	10.1	2700	2452 G	25.37585	84.45925 Normal			
23/6/23	6:15:0	86	0.1	199	10.1	1900	1799 G	25.3754	84.4512 Normal			
23/6/23	6:15:20	86	0.1	319	10.1	3100	2778 G	25.37488	84.44393 Normal			
23/6/23	6:16:0	86	0.1	179	10.1	1700	1636 G	25.37479	84.4343 Normal			
23/6/23	6:18:16	86	0.1	249	10.1	2400	2207 G	25.37466	84.42592 Normal			
23/6/23	6:18:16	86	0.1	329	10.1	3200	2930 G	25.37483	84.41615 Normal			
23/6/23	6:19:26	86	0.1	289	10.1	2800	2678 G					

$$Y = 0 * X^2 + 0.816 * X + 249$$

$$X = 4242$$

$$Y = 3710$$

(R) RURAL ROAD

Good Average Poor
<4000 4001-5000 >5001

IRI Value=2340

Machine ID=415

23.06.23

23.06.23

23.06.23

23.06.23