

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, डिहरी

डिहरी / दिनांक 28/06/23

पत्रांक 770 अछु
प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, डिहरी

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी -सह-सचिव,
ब्राडा,
भूमि विकास बैंक भवन,
बुद्ध मार्ग, पटना।

विषय :-

MR New Maintenance policy-2018 में किये गये कार्य के विरुद्ध
आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि MR New Maintenance policy-2018 अर्न्तगत कराये गये कार्यों के विरुद्ध संवेदक को भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है। इस पथ में कोई भी ATR लंबित नहीं है। उक्त पथ का सभी डाटा की प्रविष्टि MIS पर अद्यतन है।

अनु :- यथोक्त।

विश्वासभाजन

N. Kumar
28.06.23

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, डिहरी

FORM GFR 19 -A
(SEE GOVERNMENT of India's Decesion (I) below Rule - 150)
Form of Utilisation Certificate upto the Month of JUNE 2023
NEW MAINTENANCE POLICY 2018 MR (3054)

PIU - RWD DEHRI

S.No	Name of Scheme	Sanction No. & Date	Amount Received	Particulars
		With amount(in Rs. Lacs)	(In Rs. Lacs)	
1	Contruction of Rural Road under MR-3054	89 2106.2023	3656.80072	Certificate that out of Rs. 3656.80072 Lacs received during the years in favour of Executive Engineer , RWD Dehri Bihar. Sum of Rs. 3259.90896 Lacs has been utilised for the purpose of MR (3054)-2018 Fund hences as given in the margin for which it was sanctioned and that the balance of Rs. 396.87176 Lacs remaining unutilized at the end of the period under.
TOTAL			3343.87361	

Certified that I have satisfied myself that the conditions on which the grand-in-aid


- 2 was sanctioned have been duly fulfilled / are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.


Kind of Checks exercised :-

- Works have been supervised by Executive Engineer / Supertending Engineer.
- Periodical inspection has been conducted by Executive Engineer / Supertending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant.
- All other codal formalities have been observed.

3 Physical Progress achieved :-

- Construction of Road works.
- Construction of CD works.


D.A. 28/06/23
RWD (W) Div. Dehri


Executive Engineer
RWD (W) Div. Dehri

Office of the Executive Engineer, Rural Works Department, Works Division, Dehri
Requisition format Scheme Head MR (3054) under Bihar road Maintenance Policy-2018 (Rectification and Surface Renewal)

Sl No.	Package No.	Name of Road	Project Id as per MIS	Administrative Approval (AA) Letter No. and Date	Administrative Approval (AA)		Agreement (in Lakh)		Agreement No. and Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/Km)	Thickness of Bituminous Layer (in mm)	Value of Bituminous Content in Percentage	Previous total expenditure amount (in Lakh)	Up to Date expenditure as per MIS (in Lakh)	Requisition against Work Done (in Lakh)	Remarks
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RM/RO/DEH/22/0010	Dehri Nasriganj Pwd Road - Dhanthara	10301202014	141308.09.2022	4.188	251.501	181.366	50.93731	RWD/DEHRI/10MR/3054/MBD/2022-23/01.02.2023	15.11.2023	-	2612	25 MM	5%	0	0	108.7053	Complete

नोट:-

विभागीय पत्रांक-मु030(मु) 3054-4-04/2020 पार्ट 4 5047 दिनांक 23.12.2021 के आलोक में प्रमाणित किया जाता है कि-

1. गुणवत्ता पूर्ण एवं विशिष्टियों के अनुरूप कार्य कराने के बाद MIB में दर्ज किया गया है।

2. संचालित कार्य कर्मीय अभियंता द्वारा कराया गया (100% जांचा गया) सहायक अभियंता द्वारा 50% तथा कार्यपालक अभियंता द्वारा 10% जांचा गया तथा MIS पर Upload किया गया।

RWD (W) Div. Dehri

[Signature]
D.A.B.

EXECUTIVE ENGINEER
RWD, WORKS DIVISION,
DEHRI

12/06/23
28.06.23

Road Name- Dehri Nasriganj Pwd Road - Dharhara

Contractor Name- Narendra Kumar Singh

Date	Time	Section	Length	Bumps	Speed	OR	IRI	TEGORY	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD			
26/6/23	3:27:16	10	0.1	240	20.2	2400	2815	G	24.96822	84.18873	Normal
26/6/23	3:27:36	10	0.1	240	20.2	2400	2815	G	24.96922	84.18877	Normal
26/6/23	3:27:58	10	0.1	210	20.2	2100	2515	G	24.96911	84.18883	Normal
26/6/23	3:28:19	10	0.1	190	20.2	1900	2315	G	24.86743	84.19049	Normal
26/6/23	3:28:40	10	0.1	240	20.2	2400	2815	G	24.96660	84.19317	Normal
26/6/23	3:28:58	10	0.1	180	10.1	1800	2215	G	24.96658	84.19322	Normal
26/6/23	3:29:48	10	0.1	220	10.1	2200	2615	G	24.96670	84.19339	Speed Breaker
26/6/23	3:30:23	10	0.1	260	20.2	2500	2915	G	24.96657	84.19360	Normal
26/6/23	3:30:44	10	0.1	200	20.2	2000	2415	G	24.96659	84.19587	Normal
26/6/23	3:30:58	10	0.1	240	30.3	2400	2815	G	24.96610	84.19828	Normal
26/6/23	3:31:26	10	0.1	240	20.2	2400	2815	G	24.96585	84.19933	Normal
26/6/23	3:31:47	10	0.1	210	20.2	2100	2515	G	24.96555	84.20134	Normal
26/6/23	3:31:59	10	0.1	270	30.3	2700	3115	G	24.96491	84.20269	Normal
26/6/23	3:32:29	10	0.1	160	20.2	1600	2015	G	24.96504	84.20354	Normal
26/6/23	3:32:48	10	0.1	260	20.2	2600	3015	G	24.96474	84.20501	Normal
26/6/23	3:32:59	10	0.1	250	30.3	2500	2915	G	24.96460	84.20673	Normal
26/6/23	3:33:32	10	0.1	180	30.3	1800	2215	G	24.96442	84.20725	Normal
26/6/23	3:33:53	10	0.1	190	20.2	1900	2315	G	24.96431	84.20725	Normal
26/6/23	3:34:34	10	0.1	240	20.2	2400	2815	G	24.96422	84.20811	Normal
26/6/23	3:34:55	10	0.1	180	20.2	1800	2215	G	24.96337	84.20955	Normal
26/6/23	3:35:46	10	0.1	250	10.1	2500	2915	G	24.96339	84.20968	Speed Breaker
26/6/23	3:36:37	10	0.1	160	10.1	1600	2015	G	24.63307	84.21182	Normal
26/6/23	3:37:10	10	0.1	240	20.2	2400	2815	G	24.96317	84.21186	Normal
26/6/23	3:37:39	10	0.1	250	20.2	2500	2915	G	24.96314	84.21268	Normal
26/6/23	3:37:58	10	0.1	180	20.2	1800	2215	G	24.96296	84.21371	Normal
26/6/23	3:38:31	10	0.1	190	20.2	1900	2315	G	24.96290	84.21467	Normal
26/6/23	3:38:52	10	0.1	240	20.2	2400	2815	G	24.96274	84.21530	Normal
26/6/23	3:39:33	10	0.1	180	10.1	1800	2215	G	24.96275	84.21529	Normal
26/6/23	3:39:56	10	0.1	250	10.1	2500	2915	G	24.96242	84.21600	Speed Breaker
26/6/23	3:40:38	10	0.1	260	20.2	2600	3015	G	24.96226	84.21628	Normal
26/6/23	3:40:59	10	0.1	200	20.2	2000	2415	G	24.96189	84.21657	Normal
26/6/23	3:41:37	10	0.1	240	30.3	2400	2815	G	24.96099	84.21709	Normal

$$Y = 0 * X^2 + 1.000 * X + 415.2$$

$$X = 2900$$

$$Y = 3315$$

(R) RURAL ROAD

Good Average Poor

Speed Breaker

IRI Value

Average IRI-2612

28/06/23
NE

28/06/23
NE

26/6/23	3:41:58	10	0.1	200	30.3	2000	2415 G	24.96029	84.21689	Normal
26/6/23	3:42:25	10	0.1	250	30.3	2500	2915 G	24.95960	84.21685	Normal
26/6/23	3:42:50	10	0.1	270	30.3	2700	3115 G	24.95916	84.21692	Normal
26/6/23	3:43:35	10	0.1	160	20.2	1600	2015 G	24.95862	84.21768	Normal
26/6/23	3:43:52	10	0.1	280	20.2	2800	3215 G	24.95838	84.21902	Normal
26/6/23	3:44:23	10	0.1	250	30.3	2500	2915 G	24.95801	84.21959	Normal
26/6/23	3:44:44	10	0.1	180	30.3	1800	2215 G	24.95734	84.22116	Normal
26/6/23	3:45:25	10	0.1	190	20.2	1900	2315 G	24.95715	84.22140	Normal
26/6/23	3:45:56	10	0.1	240	20.2	2400	2815 G	24.95673	84.22195	Normal
26/6/23	3:46:37	10	0.1	180	20.2	1800	2215 G	24.95654	84.22268	Normal

Handwritten signature and date: 26/06/23

Handwritten notes: M. L. M. 23, 28.06.23, 28.06.23

Seco Analyzer

Name of Customer: Narend Kumar Singh
 Name of Work: Nasriganj Pwd Road - Dharhara
 Road: Nasriganj Pwd Road - Dharhara
 Lab Job number: 10
 Date: 26-06-2023
 Section No. 10


Test Date:	26-06-2023	Road Name:	Nasriganj Pwd Road - Dharhara
Machine No:	412	Road Type:	(R) RURAL ROAD
Start S No:	412	Side:	Left/Right
Start E No:	453	Interval:	
Weather:	Normal	UV Range:	1015 To 4000 mm/km
Start Location:	36822 841897	Dist Range:	0 To 43 01 1000 m
End Location:	3665484 22236	Equation:	$0 \cdot X^2 + 1.000 \cdot X + 415.2$

Print Generate Report and Graph

Redraw Graph

Map View

File: C:\Users\BRODA75\Desktop\2023\Bump Report\Narendr Kt Singh-2\Dehn Nasriganj Pwd Road - Dharhara.xlsx
 Name of Customer: Name of Work/ Road: Lab Job number:



28.06.23
 28.EE

28.06.23
 28.EE