

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल- बक्सर

पत्रांक-.....3.86...../बक्सर

दिनांक-.....14/03/23.....

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल- बक्सर

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण (BRRDA)
बुद्ध मार्ग, पटना।

विषय- शीर्ष 3054 (बिहार ग्रामीण पथ अनुरक्षण नीति- 2018) योजना अंतर्गत राशि की अधियाचना के सम्बन्ध में।

महाशय,

उपर्युक्त विषय के सम्बन्ध में कहना है कि योजना शीर्ष 3054 मरम्मति (बिहार ग्रामीण पथ अनुरक्षण नीति- 2018) अंतर्गत कराये गए कार्यों के भुगतान हेतु राशि की आवश्यकता है जिसे अधियाचना प्रपत्र के साथ सलंग्न कर भेजा जा रहा है।

अतः श्रीमान से अनुरोध है कि सलंग्न विवरणी के अनुसार आवंटन उपलब्ध कराने की कृपा की जाए ताकि संवेदकों द्वारा कराये गए कार्य का भुगतान किया जा सके।

अनु०- यथोक्त

विश्वासभाजन

14.03.23

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर

AK
14/03/2023

FORM GFR 19-A
(SEE Government of India's Decision (I) below Rule-150)
Form of Utilisation Certificate upto the month of Dec 2018

MR (3054) New Maintenance Policy 2018

PIU - RWD (W), Div.- Buxar

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
1	Constructi on of Rural Roads under MR (3054) Maintena nce	Lt. No.- 32, dt.-03.03.2023	6985.97121	Certified that out of Rs. 6985.97121 lacs received during the years in favour of Ex. Engineer, RWD (W), Div.- Buxar Bihar, a sum of Rs 6966.02771 lacs been utilized for the purpose of MR (3054) New Maintenance Policy 2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs 19.90435 lacs remaining unutilized at the end of the period under.
Total -				

- 2 Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/ Supertending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Supertending Engineer.
- Construction materials have been tested
- Measurements have been recorded in the MBs and test check conducted by the Assistant.
- All other codal formalities have been observed.

3 Physical Progress achieved :-

- Construction of Road works
- Construction of CD works

14.03.23
Executive Engineer

R.W.D. (w) Div. Buxar

AK
14.03.2023

Position Format for Scheme Head- MR (3054) under Bihar Rural Road Maintenance Policy- 2018 (Initial Rectification and Surface Renewal)

Name of Works Division- RWD, Works Division- Buxar

Sl No	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (In Lakh)		Agreement No. & Date	Date Of Completion as per Agreement	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allocated Amount (In Lakh)	Up-to-date expenditure as per MIS (In Lakh)	Requisition done against work (In Lakh)	Remarks
					Length (in KM)	Amount (in Lakh)	Initial Rectification With Surface Renewal (In Lakh)	5 Years Routine Maintenance (In Lakh)									
1	RM/BU/BU X/22/0008	Buxar Harhi SH - Badaka Nuon	NEA22000788	Letter No 1486 & 8/09/2022	4.55	231.884	172.94425	54.12625	13/MBD/2022-23 & 22.02.2023	21.11.2023	2387	25MM	5.00%	0	0	172.94112	

1. Signed Hard Copy and Soft Copy (in excel) of recorded IRI is enclosed
2. Up-to-date Physical Progress has been uploaded in MIS

Executive Engineer
RWD (W), Div.- Buxar

14.03.23
14.03.2023


कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, बक्सर

का0आ0स.....385..... बक्सर/ दिनांक.....14/03/23


कार्यालय आदेश

प्रमाणित किया जाता है कि बिहार ग्रामीण पथ अनुरक्षण नीती-2018 योजनान्तर्गत Buxar Itarhi SH - Badaka Nuon पथ का कार्य गुणवत्ता एवं विशिष्टियों के अनुरूप पूर्ण कराया गया है। पथ के मापीपुस्त की जाँच मेरे द्वारा 10 प्रतिशत एवं कनीय अभियंता के द्वारा शत प्रतिशत किया गया है।


कनीय अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रशाखा बक्सर


कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर

File : G:\BISHNU SANKAR OJHA\New folder\14031207.Xls. Section No. : 91, Eqn : $Y = 0 \cdot X^2 + 0.816 \cdot X + 249$
 Name of Customer : Ashutosh Kumar, Name of Work/ Road : Buxar Itrahi SH- Badka Nuon, Lab Job number :



[Signature]
 14-03-23

[Signature]
 14-03-23

Name of Road:- Buxar Itrahi SH- Badka Nauon Contractor's Name:-Ashotosh Kumar

Date	Time	Section	No.	Length in km	Bumps in mm	Speed Rate	OR	IRI,TEGORY	Latitude	ongitude	Event	
14/3/23	10:13:0	91	0.1	310	10.1	3100	2778 G	25.5479	83.99072	Normal		$Y = 0 * X^2 + 0.816 * X + 249$
14/3/23	10:14:0	91	0.1	290	10.1	2900	2615 G	25.5479	83.99126	Normal		X = 3000
14/3/23	10:14:26	91	0.1	240	10.1	2400	2207 G	25.54787	83.99231	Normal		Y = 2696
14/3/23	10:15:1	91	0.1	190	10.1	1900	1799 G	25.54746	83.99298	Normal		
14/3/23	10:15:36	91	0.1	270	10.1	2700	2452 G	25.54701	83.9936	Normal		(R) RURAL ROAD
14/3/23	10:16:12	91	0.1	240	10.1	2400	2207 G	25.54703	83.99465	Normal		Good
14/3/23	10:16:12	91	0.1	200	10.1	2000	1880 G	25.54714	83.99549	Normal		Average
14/3/23	10:16:47	91	0.1	290	10.1	2900	2615 G	25.54733	83.99601	Normal		Poor
14/3/23	10:18:0	91	0.1	360	10.1	3600	3186 G	25.54661	83.997	Normal		<4000 4001-5000 >5001
14/3/23	10:21:27	91	0.1	210	10.1	2100	1962 G	25.5457	83.9969	Normal		IRI Value=2387
14/3/23	10:23:0	91	0.1	260	10.1	2600	2370 G	25.54471	83.99685	Speed Breaker		Machine ID=415
14/3/23	10:24:7	91	0.1	350	10.1	3500	3104 G	25.54398	83.99722	Normal		
14/3/23	10:26:10	91	0.1	260	10.1	2600	2370 G	25.54312	83.99719	Normal		
14/3/23	10:27:0	91	0.1	310	10.1	3100	2778 G	25.54204	83.99734	Normal		
14/3/23	10:27:22	91	0.1	320	10.1	3200	2860 G	25.54116	83.99761	Normal		
14/3/23	10:28:0	91	0.1	220	10.1	2200	2044 G	25.5402	83.99783	Normal		
14/3/23	10:28:26	91	0.1	220	10.1	2200	2044 G	25.54013	83.99785	Normal		
14/3/23	10:32:0	91	0.1	110	10.1	1100	1146 G	25.54355	83.99936	Normal		
14/3/23	10:32:47	91	0.1	170	10.1	1700	1636 G	25.54457	83.99933	Normal		
14/3/23	10:33:23	91	0.1	250	10.1	2500	2288 G	25.54457	83.99933	Normal		
14/3/23	10:34:33	91	0.1	150	10.1	1500	1472 G	25.54457	83.99933	Normal		
14/3/23	10:35:8	91	0.1	190	10.1	1900	1799 G	25.54457	83.99933	Normal		
14/3/23	10:35:44	91	0.1	250	10.1	2500	2288 G	25.54457	83.99933	Normal		
14/3/23	10:36:19	91	0.1	320	10.1	3200	2860 G	25.54457	83.99933	Normal		
14/3/23	10:36:54	91	0.1	300	10.1	3000	2696 G	25.54457	83.99933	Normal		
14/3/23	10:37:30	91	0.1	360	10.1	3600	3186 G	25.54457	83.99933	Normal		
14/3/23	10:40:26	91	0.1	250	10.1	2747	2490 G	25.54457	83.99933	Speed Breaker		
14/3/23	11:46:49	91	0.1	330	10.1	3300	2941 G	25.54239	84.9057	Normal		
14/3/23	11:47:18	91	0.1	280	10.1	2800	2533 G	25.5421	84.9998	Speed Breaker		
14/3/23	11:48:29	91	0.1	300	10.1	3000	2696 G	25.5421	84.9998	Normal		
14/3/23	11:49:8	91	0.1	320	10.1	3200	2860 G	25.54193	84.1178	Normal		
14/3/23	11:50:18	91	0.1	240	10.1	2400	2207 G	25.54193	84.1178	Normal		
14/3/23	11:50:53	91	0.1	310	10.1	3100	2778 G	25.54193	84.1178	Normal		

[Signature]

14.03.23

Name of Road:- Buxar Itrahi SH- Badka Nauon Contractor's Name:-Ashotosh Kumar

Date	Time	Section	Length	Bumps	Speed	OR	IRI, I CATEGORY	Latitude, ongtitude	Event
14/3/23	11:51:27	91	0.1	290	10.1	2900	2615 G	25.54392 84.12658	Normal
14/3/23	11:51:27	91	0.1	230	10.1	2300	2125 G	25.54392 84.12658	Normal
14/3/23	11:52:3	91	0.1	250	10.1	2500	2288 G	25.54392 84.12658	Normal
14/3/23	11:52:38	91	0.1	240	10.1	2400	2207 G	25.54392 84.12658	Normal
14/3/23	11:53:13	91	0.1	190	10.1	1900	1799 G	25.54392 84.12658	Normal
14/3/23	11:53:48	91	0.1	320	10.1	3200	2860 G	25.54392 84.12658	Normal
14/3/23	11:54:48	91	0.1	330	10.1	3300	2941 G	25.54392 84.12658	Normal
14/3/23	11:54:24	91	0.1	210	10.1	2100	1962 G	25.54815 84.848	Normal
14/3/23	11:54:59	91	0.1	320	10.1	3200	2860 G	25.54815 84.848	Normal
14/3/23	11:54:59	91	0.1	150	90.9	1500	1472 G	25.54815 84.848	Normal
14/3/23	11:55:24	91	0.1	210	10.1	2100	1962 G	25.54815 84.848	Normal
14/3/23	11:55:59	91	0.1	320	10.1	3200	2860 G	25.54815 84.848	Normal
14/3/23	11:56:59	91	0.05	150	90.9	3000	2696 G	25.54815 84.848	Normal

14.03.23

14.03.23

Contractor's Name:-Ashotosh Kumar