

**कार्यपालक अभियन्ता का कार्यालय,
ग्रामीण कार्य विभाग; कार्य प्रमण्डल, भभुआ**

पत्रांक 509 / भभुआ,

दिनांक 15.03.23

प्रेषक,

कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, भभुआ

सेवामें,

अपर-मुख्य कार्यपालक पदाधिकारी,
सह-सचिव, बी0आर0आर0डी0ए0,
बिहार, पटना।

विषय:- MR/3054 मरम्मति योजना अन्तर्गत मरम्मति कार्य की अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में इस प्रमंडल में MR/3054 मरम्मति योजना अन्तर्गत मरम्मति कार्य हेतु अधियाचना विहित प्रपत्र में अंकित कर सूचनार्थ एवम् आवश्यक कार्यवाही हेतु समर्पित की जाती है।

सूचनार्थ समर्पित।

अनु0:- यथोक्त।

विश्वासभाजन

15/03/23
कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग
कार्य प्रमण्डल, भभुआ

ज्ञापांक 509 / भभुआ, दिनांक 15.03.23

प्रतिलिपि :- नोडल पदाधिकारी, MR/3054 ब्राडा, पटना को सूचनार्थ समर्पित।

15/03/23
कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, भभुआ

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilization Certificate up to date

Sl.No	Name of Scheme	Sanction No.&Date With Amount (In lace Rs.)	Amount Received (In lace Rs.)	Particulars
1	New Maintenance Policy-2018 MR (3054) BRRDA PATNA)	New Maintenance Policy-2018 MR (3054) BRRDA PATNA	7999.60740	Certified that out of 7999.60740 lakh of grants-in-aid sanctioned during the years 2022-23 In favor of EE,RWD works division Bhabhua a sum of Rs7829.42257 lakh has been utilized for the purpose of New Maintenance Policy-2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs.170.18483 lakh remaining unutilized at the end of the period under report.
	Total:		7999.60740	


2. Certified that I have satisfied my self that the cosnditions on which the grant-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was utilized for the purpose for which it was sanctioned.



Kind of Checks exercised:-

- i. Works have been supervised by Executive Engineer/ Superintending Engineer.
- ii. Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- iii. Construction materials have been tested.
- iv. Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- v. All other caudal formalities have been observed.

3. Physical Progress achieved:-

- i. Construction of Road Works.
- ii. Construction of CD works.


Divisional Accounts Officer
R.W.D, works Division
Bhabhua.


Executive Engineer
R.W.D, works Division
Bhabhua


Road Name - Tori to Radhakhand

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event
15/3/23	17:48:11	61	0.1	190	0	1900	2290 G		24.946188	83.61606	Normal
15/3/23	17:48:57	61	0.1	300	30.3	3000	3540 G		24.946213	83.61515	Normal
15/3/23	17:49:37	61	0.1	290	30.3	2900	3426 G		24.946278	83.61404	Normal
15/3/23	17:49:55	61	0.1	270	30.3	2700	3199 G		24.945928	83.613265	Normal
15/3/23	17:50:13	61	0.1	300	30.3	3000	3540 G		24.94586	83.613248	Normal
15/3/23	17:50:51	61	0.1	230	40.4	2300	2745 G		24.944921	83.613046	Normal
15/3/23	17:51:15	61	0.1	210	40.4	2100	2518 G		24.943938	83.612957	Normal
15/3/23	17:51:58	61	0.1	300	30.3	3000	3540 G		24.94307	83.61268	Normal
15/3/23	17:52:16	61	0.1	280	30.3	2800	3313 G		24.942255	83.612135	Normal
15/3/23	17:52:56	61	0.1	300	30.3	3000	3540 G		24.941609	83.611457	Normal
15/3/23	17:53:22	61	0.1	260	30.3	2600	3086 G		24.94125	83.610632	Normal
15/3/23	17:53:52	61	0.1	300	30.3	3000	3540 G		24.940818	83.609723	Normal
15/3/23	17:54:17	61	0.1	230	40.4	2300	2745 G		24.940442	83.608724	Normal
15/3/23	17:54:52	61	0.1	300	30.3	3000	3540 G		24.939694	83.608324	Curve
15/3/23	17:55:18	61	0.1	280	30.3	2800	3313 G		24.939143	83.607563	Normal
15/3/23	17:55:58	61	0.1	270	30.3	2700	3199 G		24.939619	83.606799	Normal
15/3/23	17:56:19	61	0.1	290	30.3	2900	3426 G		24.939832	83.605736	Normal
15/3/23	17:56:58	61	0.1	250	30.3	2500	2972 G		24.940502	83.605621	Curve
15/3/23	17:57:13	61	0.1	280	30.3	2800	3313 G		24.941617	83.605741	Normal
15/3/23	17:57:53	61	0.1	290	30.3	2900	3426 G		24.942268	83.605692	Normal
15/3/23	17:58:12	61	0.1	220	40.4	2200	2631 G		24.943119	83.605898	Normal
15/3/23	17:58:58	61	0.1	270	30.3	2700	3199 G		24.944213	83.606109	Normal
15/3/23	17:59:48	61	0.1	200	0	2000	2404 G		24.944619	83.605381	Normal

$$Y = 0 \cdot X^2 + 1.136 \cdot X + 132.5$$

$$X = 2000$$

$$Y = 2404$$

(R) RURAL ROAD
 Good Average Poor
 <4000 4001-5000 >5001

Total IRI
 Average 3149.78



 15/08/23



 15/08/23


Name of Customer : Parla Constructions
Name of Work/ Road : Ton to Radhakhand
Lab Job number : 61
Date : 15-03-2023
Section No. : 61

Test Date : 15-03-2023
Machine No : 412
Start S No. :
Start E No. :
Weather :
Start Location :
End Location :
Road Name : Ton to Radhakhand
Road Type : (R) RURAL ROAD
Side :
UV Range : 1290 To 5000 Interval 1000 mm/km
Dist Range : 0 To 24 0.1 = 1000 m
Equation : $Y = 0 \cdot X^2 + 1.136 \cdot X + 132.5$

Print Generate Report and Graph

Redraw Graph Map View

File : C:\Users\BRDA91\OneDrive\Desktop\sk3\new Mr Bump 22-23\pankoj\15.3.23\New Text Document.Xls
 Name of Customer : Name of Work/ Road : Lab Job number :



15/03/23
 022
 15/03/23
 Ex. En.