

कार्यपालक अभियंता का कार्यालय ग्रामीण कार्य विभाग, कार्य प्रमंडल मंगेर

पत्रांक- 306 अनु हिराह 15/3/202

दिनांक— 15 3 2023 ई मेल – ee.reomunger@gmail.com



प्रेषक.

कार्यपालक अभियंता, ग्रामीण कार्य विभाग, कार्य प्रमंडल, मुंगेर ।

सेवा में,

नोडल पदाधिकारी, नई अनुरक्षण नीति 2018'' (3054-MR) ग्रामीण कार्य विभाग, बिहार पटना।

विषय: - शीर्ष MR(3054) "नई अनुरक्षण नीति 2018" योजनान्तर्गत पथ के निर्माण में संवेदक के विपत्र भुगतान हेतु राशि की अधियाचना के सम्बन्ध में। महाशय,

उपर्युक्त विषय के संबंध में सूचित करना है कि शीर्ष MR(3054) "नई अनुरक्षण नीति 2018" योजनान्तर्गत पथ:—

- 1. Panchyat Indrukh Purbi Gram Halimpur Me Sadan Mandal Ke Ghar To Madhya Vidyalay Indrukh Tak PCC Road
- 2. Chandanpura Panchyat Milki Chak To Mushahari Tola Chandrapura Tak Sampark Path Under Jamalpur Block
- 3. NH-80 At Ramdeo Yadav House To Sichai Bandh Under Jamalpur Indrukh West Panchyat
- 4. BANK PANCHAYAT MUSLIM TOLA JANAUDHA GRAM SE MASJID HOTE HUWE WAKARPUR SIMAN TAK
- 5. Jamalpur Chandanpura Middle School Chandanpura To Gowdan Of Ramanand Kushwaha में Surface कार्य पूर्ण के भुगतान हेतु आवंटन की अधियाचना विहित प्रपत्र में भर कर की जाती है।

अतः अनुरोध है कि आवंटन उपलब्ध कराने की कृपा की जाय।

अनु0:-यथोक्त।

विश्वासमाजन

m/15/3/23

कार्यपालक अभियंता ग्रामीण कार्य विभाग कार्य प्रमंडल मुंगेर

Requisition Formate for Scheme Head - MR(3054) under Bihar Rural Road Maintenance Policy - 2018 (Initial Rectification and Surface Renewal)

Name of Works Division :- Munger

OA	4	(6)	2	-	-	No.	2
RM/MU/MU N/22/0004	RM/MU/MU N/22/0004	RM/MU/MU N/22/0004	RM/MU/MU N/22/0004	RM/MU/MU N/22/0604		Package No.	
Jannalpur Chandanpura Middle School Chandanpura To Gowdan Of Ramanand Kushwaba	BANK PANCHAYAT MUSLIM TOLA JANAUDHA GRAM SE MASJID HOTE HUWE WAKARPUR SIMAN TAK	NH-30 At Randeo Yadav House To Sichai Bandh Under Jamalpur Indrukh West Panchyat	Chandanpura Panchyat Milki Chak To Mushahari Tola Chandrapura Tak Sampark Path Under Jamalpur Block	Purbi Gram Halimpur Me Sadan Mandal Ke Ghar To Madhya Vidyahy Indrakh Tak PCC Road	Panchvat Indrukh	Name	
20803703141	20803708146	20803704030	20803704034	20803704028	4	Project ID as per MIS	
308/ 22.06.2022	308/ 22.06.2022	308/ 22.06.2022	308/ 22.06.2022	308/ 22.06.2022	5	Approval (AA) Letter No & Date	Administrative
1.465	L.	0.625	0.5	2,0	6	Length (In km)	
64.649	59.117	26.608	22.627	14.495	7	Amount of (In Lakh)	Administrative Approval (AA)
39,46574	36,28023	16.45439	13,85085	8.7457	8	Rectification with Surface Renewal (In Lakh)	Agreement Amount (In Lakh)
15,40771	13,38813	5.95353	5.14963	3.52408	9	5 Years Routine Maintenance (In Lakh)	nount (In Lakh
5-MBD-2022-	5-MBD-2022-	5-MBD-2022-	5-MBD-2022.	5-MBD-2022.	10	Agreement No. & Date	3
07-Jul-23	07-Jul-23	07-Jul-23	07-Jul-23	07-Jul-23	Н	Completion as per Agreement	Date of
					12	Actual Date of Completion	
3016	2734	2503	2872	3030	13	Value of IRI (in mm/km)	1
25.00	25.00	25.00	25.00	25.00	14	of Bitumen Layer (in mm)	
5.00	5.00	5.00	5.00	5.00	15	Bitumen Content in Percentage	
0.00000	6.00000	0.00000	0.09000	0.00000	16	Total Alloted Amount (in Lakh)	Previous
0.00000	0.00000	0.00000	0.00000	0.00000	17		un-to-dute
39,46574	36.28023	16.45439	13.85085	8.7457	10	Requisition against work done (in Lakh)	
			×	19		Remarks	

Signed Hard Copy and Soft Copy (in Excel) of recorded IRI is enclosed.
 Up-to-date Physical Progress has been uploaded in MIS.

Total = 114.79691

Executive Engineer
RWD, Works Division, Munger

EXECUTIVE ENGINEER, RURAL WORKS DEPARTMENT, WORKS DIVISION, Munger

FROM GFR 19 - A

(See Government of India's Decision (I) below Rule - 150) Form of Utilisation Certificate upto the month of Feb-2023

Name of the Head :- MR (New Maintenance Policy 2018) Fund

Month:- Feb-2023

SI. No.	Name of Scheme	Sanctioned No./ Date	Amount Received (in Lacs Rs.)	Particulars
1	2	4	5	6
1	Construction of Rural Roads under (NEW Maintenance Policy 2018) Fund	Vide Up to Letter No.32 WE dt. 03.03.2023	2859.53522	Certified that out of Rs. 2859.53522 Lacs received during the year 2019-20 in favour of Executive Engineer R.W.D. Works Division, Munger, Bihar a sum of Rs 2779.01850 Lacs has been utilized for the purpose of MR (New Maintenance Policy 2018) Fund Schemes as given in the margin for which it was sanctioned and that the balance of Rs 80.51672 Lacs remaining un-utilized at the end of the period under.
	Total -		2859.53522	

Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose fo

Kind of Checks Exercised :-

- i. Works have been supervised by Executive Engineer/Superintending Engineer.
- ii.Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
- iii. Construction materials have been tested.
- iv. Measurements have been recorded in the MBs and test checks conducted by the Assistant Engineer/ Executive Engineer.
- v. All other codal formatities have been observed.

3 Physical Progress achieved :-

- i. Construction of Road Works.
- ii. Construction of CD. Works.

Sr. Divisional Accounts Officer Rural Works Department Works Division, Munger Executive Engineer
Rural Works Department

Works Division, Munger

		Mad	hya Vi	dyalay	Indru	kh Tak	PCC Road			
Time	Section		Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	
	11					T		American Property	annuguenac	TACHE
	No.	in km	in mm	Rate	mm/km	mm/km	ROAD			
14/3/23 16: 54: 0	62	0.1	280	10.1	2800	2825	G	25 329122	86 476532	Normal
14/3/23 16: 54: 0	62	0.1	300	20.2	3000	3015	G	25 220615	96 476347	Nomal V - 22
14/3/23 16:55:0	62	0.1	320	10.1	3200	05CE	ç	25 220627	2025 70	
	ime: 54: 0: 54: 0: 55: 0: 55: 0	ime Section No. .54:0 .54:0 .62 .55:0 .62	Ime Section Length No. in km :54:0 62 0.1 :55:0 62 0.1	Madhya Vi ime Section Length Bumps No. in km in mm :54: 0 62 0.1 280 :54: 0 62 0.1 300 :55: 0 62 0.1 320	Madhya Vidyalay ime Section Length Bumps Speed No. in km in mm Rate :54:0 62 0.1 280 10.1 :54:0 62 0.1 300 20.2 :55:0 62 0.1 320 10.1	Madhya Vidyalay Indrul ime Section Length Bumps Speed OR No. in km in mm Rate mm/km :54: 0 62 0.1 280 10.1 2800 :54: 0 62 0.1 300 20.2 3000 :55: 0 62 0.1 320 10.1 3200	Madhya Vidyalay Indrukh Tak ime Section Length Bumps Speed OR IRI No. in km in mm Rate mm/km mm/km :54:0 62 0.1 280 10.1 2800 2825 :54:0 62 0.1 300 20.2 3000 3015 :55:0 62 0.1 320 10.1 3200 3250	Madhya Vidyalay Indrukh Tak PCC Road ime Section Length Bumps Speed OR IRI CATEGORY No. in km in mm Rate mm/km mm/km ROAD :54:0 62 0.1 280 10.1 2800 2825 G :55:0 62 0.1 320 20.2 3000 3015 G :55:0 62 0.1 320 10.1 3200 3250 G	Madhya Vidyalay Indrukh Tak PCC Road Section Length Bumps Speed OR IRI CATEGORY No. in km in mm Rate mm/km mm/km ROAD 62 0.1 280 20.2 3000 3015 G 62 0.1 320 10.1 3200 3250 G	Madhya Vidyalay Indrukh Tak I Section Length Bumps Speed OR IRI No. in km in mm Rate mm/km mm/km 62 0.1 280 10.1 2800 2825 62 0.1 320 20.2 3000 3015 62 0.1 320 10.1 3200 3250

Executive Engineer
RWD Works Division
Munger

<4000 ×4000

Good Average Poor <4000 4001-5000 >5001

	1825	UIV 2825.		Print			Section No.	Lab Job number 62	Name of V	Customer
			File :C:\Users\BRRDA27\Desktop\Mala Devi 14.03.2023\14031717.Xls, Section No.:62, Eqn.:test Name of Customer :Mala Devi, Name of Work/ Road :Panchyat Indrukh Purbi Gram Halimpur Me Sadan Mandal Ke	Generate Report and Graph				COUCED	Name of Work/ Panchyel Individe Publi Gram H Road:	Mola Devi
Distance * 1000 m			sktop\Mala Devi 14.03.2 vi. Name of Work/ Roa		End Location :	Start Location :	Weather:	Start E No :	Start S No:	
	0'2		2023\14031717.Xls, d :Panchyat Indrukh F		Equation :	Dist Range :	UIV Range :	Side:	385 Road Type :	₹ 5202-50+
			Section No. :62, Purbi Gram Halin	Redraw Graph	n. test	ige: 0 To	ige: 1825 To		ype: (R) RURAL ROAD	
6	2	1	Eqn :test	Ма		0.4	4000		AL ROAD	r andrya manusi r uspi Glam
			dan Mandal Ke	Map View		01 - 1000 m	1000 mm/km	Interval	ı	Gram

36 Scolenisis

Executive Engineer
RWD Works Division Munger