

**कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, अरवल।**

पत्रांक 395 अरवल/दिनांक 17/03/2023

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, अरवल

सेवा में,

नोडल पदाधिकारी (MR 3054)
ग्रामीण कार्य विभाग
पटना, बिहार

विषय :- नई अनुरक्षण नीति-2018MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के विरुद्ध आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि नई अनुरक्षण नीति-2018 MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के लिए संवेदक को भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है।

अनु :- यथोक्त।

विश्वासभाजन


कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, अरवल।
17/3/23

Name of Works Division- Arwal.

Sl No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter no. & Date	Administrative Approval (AA)		Agreement Amount (In Lakh)		Date of Completion As per Agreement	Actual Date of Completion	Value of IRI (In MM/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content percentage	Previous Total Allotted Amount (In Lakh)	Up to date expenditure as per MIS (in Lakh)	Requisition against work done (In Lakh)	Remarks	
					Length	Amount of (In Lakh)	Initial Rectification with surface Renewal (In Lakh)	5 Years Routine Maintenance (In Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RM/AR/ ARW/22/ 0005	Maintenance of Repair and Road from Kinjer Kurtha Road to Pinjarawan.	10603108003	2041/04-05-2022	1.46	55.177	44.88078	15.15363	08/MBD/2022-23/09.12.2022	8-Sep-23	-	2941	25 MM	5.000	0.00000	44.88078	Complete	
		Total			1.460	55.177	44.88078	15.15363							0.00000	44.88078		

15/3/23
Divisional Accounts Officer
R.W.D.(W) Division
Arwal.

15/3/23
Arwal.

FORM GFR -19 -A

(see Govt. of India's decision (i) below rule 150)

Form of Utilisation Certificate as on 15.03.2023

New Maintenance Policy Through CFMS

PIU:- R.W.D. Works, Division, Arwal.

Sl. No	Name of Scheme	Sanction No.& Date with amount (in Rs. Lakh)	Amount Received (in Rs. Lakh)	Particulars
1	2	3	4	5
1	Construction of Road Under New Maintenance Policy Scheme	2984.43888	2984.43888	Certified that out of Rs. 2984.43888 Lakh received till date in favour of Executive Engineer, R.W.D. Works Division, Arwal a sum of Rs. 2710.24099 Lakh has been utilized for the purpose of New Maintenance Policy Scheme as given in the margin for which it was sanctioned and that the balance of Rs. 274.19789 Lakh remaining unutilized at the end of the period under the time of completion.
		2984.43888	2984.43888	

- 2 Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the propose for which it was sanctioned.

Kind of Checks Exercised :-

- Workers have been supervised by Executive Engineer/ Superintending Engineer
- Periodical inspection has been conducted by Executive Engineer/Superintending Engineer
- Construction materials have been tested.
- Measurments have been recorded in the MB's and test check conducted by the Assistant Engineer/Executive Engineer.
- All other codal formalities have overserved

3 Physical Progress Achieved.

- Construction of Road Works
- Construction of CD Works.


15/3/23
Divisional Accounts Officer
Rural works Department
Works Division, Arwal.


Executive Engineer
Rural Works Department
Works Division, Arwal.

17/3/23

ROAD NAME:- Maintenance of Repair and Road from Kinjer Kurtha Road to Pinjarawan.

CONT. NAME:- CHANDRA BHUSHAN SINGH

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event
15/3/23	11:2:0	41	0.1	340	10.1	3400	3294 G		25.17747	84.81904	Normal
15/3/23	11:2:22	41	0.1	280	10.1	2800	2736 G		25.176613	84.819208	Normal
15/3/23	11:2:72	41	0.1	330	10.1	3300	3201 G		25.17577	84.818922	Normal
15/3/23	11:3:0	41	0.1	260	10.1	2600	2550 G		25.174985	84.8184	Normal
15/3/23	11:3:0	41	0.1	270	10.1	2700	2643 G		25.174377	84.817658	Normal
15/3/23	11:3:33	41	0.1	340	10.1	3400	3294 G		25.173528	84.817305	Normal
15/3/23	11:4:8	41	0.1	320	10.1	3200	3108 G		25.172605	84.817103	Normal
15/3/23	11:4:43	41	0.1	320	10.1	3200	3108 G		25.171705	84.816885	Normal
15/3/23	11:5:0	41	0.1	300	10.1	3000	2922 G		25.170832	84.816918	Normal
15/3/23	11:5:18	41	0.1	270	10.1	2700	2643 G		25.169887	84.81682	Normal
15/3/23	11:5:54	41	0.1	310	10.1	3100	3015 G		25.169025	84.816582	Normal
15/3/23	11:6:29	41	0.1	260	10.1	2600	2550 G		25.1687	84.817272	Normal
15/3/23	11:7:4	41	0.1	360	10.1	3600	3480 G		25.168677	84.818332	Normal
15/3/23	11:7:4	41	0.1	270	10.1	2700	2643 G		25.1686	84.819292	Normal
AVERAGE							2941				

(R) RURAL ROAD

Good Average Poor

<4000 4001-5000 >5001

$$Y = 0 \cdot X^2 + 0.930 \cdot X + 132.7$$

$$X = 6400$$

$$Y = 6084$$

15/3/23


15/3/23

A.E.

15/3/23

File : C:\DATE -15.03.2023\GRAPH.Xls. Section No. : 41, Eqn : test

Name of Customer : CHANDRA BHUSHAN SINGH, Name of Work/ Road : Maintenance of Repair and Road from



Arinash
15/3/23
JE

Arinash
15/3/23

Arinash
15/3/23
JE