

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, मुजफ्फरपुर पूर्वी-2

पत्रांक: 615 3130
प्रेषक,

मुज0/दिनांक: 18/3/23

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल मुजफ्फरपुर, पूर्वी-2
सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव,
बिहार ग्रामीण पथ विकास अभिकरण,
बिहार, पटना।


विषय: बिहार ग्रामीण पथ अनुरक्षण नीति- 2018 अनुरक्षण के तहत स्वीकृत योजनाओं के विरुद्ध
आवंटन की माँग करने के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में वित्तीय वर्ष 2019-20 नई अनुरक्षण नीति अंतर्गत वित्तीय
वर्ष 2022-23 में अनुरक्षण मद में व्यय हेतु संलग्न विवरणी के अनुसार 9.86009 (नौ लाख छयासी हजार
नौ रू0 मात्र) का आवंटन उपलब्ध कराने की कृपा की जाये ताकि किये गये अनुरक्षण कार्यों का भुगतान
किया जा सके।

अनु0:- यथोक्त।

विश्वासभाजन


कार्यपालक अभियंता
ग्रामीण कार्य विभाग, कार्य प्रमंडल,
मुजफ्फरपुर पूर्वी-2

FORM GFR 19-A

Form of utilisation Certification up to month of Jun-2022

MR3054(CFMS)

RWD ,Works Division, Muzaffarpur East-II

SL. NO.	Name of Scheme	Sanction No & Date with Amount (In Rs.)	Amount Received (In Rs.)	Particulars
1.	Construction of Rural Road under MR3054 (CFMS)	Secretary cum Empowered officer B.R.R.D.A Letter No.- Dated	Opening Balance- Rs. 33,40,91,008.00 Rs. + 0.00 Rs. 33,40,91,008.00 Rs. - 32,90,98,891.00 Rs. 49,92,117.00	Certified that out of Rs. 33,40,91,008.00 of grant in aid received during the Year 2021-2022 in favour of Executive Engineer R.W.D. Works Division, Muzaffarpur East-II. A sum of Rs. 32,90,98,891.00 has been utilized for the purpose of MR3054 (CFMS) schemes as given in the margin for which it was sanctioned and that the balance of Rs. 49,92,117.00 remaining unutilized at the end of the period under.
		Total	Rs. 33,40,91,008.00	

2. Certified that I have satisfied that the conditions on which the grants-in aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-

- I. Works have been supervised by Executive Engineer/ Superintending Engineer.
- II. Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
- III. Construction material has been tested.
- IV. Measurements have been recorded in the MBS and test check conducted by the Assistant Engineer/Executive Engineer.
- V. All other codal formalities have been observed.

3. Physical progress achieved:

- i. Construction of Road Works.
- ii. Construction of CD Works.

Executive Engineer

RWD, Works Division

Muzaffarpur East-2

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division :- Muzaffarpur East-II

S. N.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lakh)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	Up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in Km)	Amount (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RM/MU/M UZ/20/0007	Minapur PWD Road - Gosaipur Tengrah	NEA2200025 18	1205 Date:- 20.04.2020	7.15	412.0350	259.95729	70.1702	MR(3054) MBD- 57/2020-21	12/10/20 21	Ongoing	2009.915	25	5.020	250.00000	250.00000	9.86009	surface completa
																	9.86009	


 Executive Engineer
 RWD Works Division
 Muzaffarpur East-II

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, मुजफ्फरपुर पूर्वी-2

प्रमाण-पत्र


प्रमाणित किया जाता है कि Minapur PWD Road - Gosaipur Tengrah, Project ID- NEA220002518 का सभी अवयवों की जाँच शत प्रतिशत कनीय अभियंता द्वारा किया गया है। सहायक अभियंता, द्वारा सभी अवयवों की 50 प्रतिशत से अधिक जाँच किया गया है। अघोहस्ताक्षरी द्वारा 10 प्रतिशत अवयवों की जाँच की गई है।


कनीय अभियंता


सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल, मीनापुर


कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल मुज0 पूर्वी-2

File :G:\MUZAFFARPUR\Bump Report\Suresh Ray\Minapur PWD Road to GosaipurTengraha.Xls. Section No. :70.
Name of Customer :Suresh Ray. Name of Work/ Road :Minapur PWD Road to GosaipurTengraha. Lab Job number



07177122
82

~~2/2/2~~

$$\frac{1}{2} \ln$$

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR	IRI	Latitude	Longitude	Event
Road Name:-Minapur PWD Road to GosaiपुरTengraha										
6/7/22	13:18:0	70	0.1	100	0	1000	1.48	26.26218	85.35066	Normal
6/7/22	13:18:10	70	0.1	150	20.2	1500	2.13	26.26302	85.35094	Normal
6/7/22	13:18:10	70	0.1	230	20.2	2300	3.13	26.26378	85.35152	Normal
6/7/22	13:18:45	70	0.1	220	20.2	2200	3	26.26458	85.35199	Normal
6/7/22	13:19:0	70	0.1	160	20.2	1600	2.26	26.26545	85.35244	Normal
6/7/22	13:19:0	70	0.1	210	30.3	2100	2.88	26.26623	85.35286	Normal
6/7/22	13:19:20	70	0.1	200	30.3	2000	2.76	26.26703	85.35343	Normal
6/7/22	13:19:20	70	0.1	260	30.3	2600	3.49	26.2678	85.35374	Normal
6/7/22	13:19:56	70	0.1	270	20.2	2700	3.61	26.26868	85.35421	Normal
6/7/22	13:20:0	70	0.1	200	20.2	2000	2.76	26.26903	85.35497	Normal
6/7/22	13:20:0	70	0.1	160	10.1	1600	2.26	26.26896	85.35603	Normal
6/7/22	13:20:31	70	0.1	170	20.2	1700	2.38	26.26875	85.35702	Normal
6/7/22	13:21:6	70	0.1	270	10.1	2700	3.61	26.26854	85.35904	Normal
6/7/22	13:21:6	70	0.1	200	20.2	2000	2.76	26.26865	85.36002	Normal
6/7/22	13:21:41	70	0.1	220	20.2	2200	3	26.2687	85.36106	Normal
6/7/22	13:22:0	70	0.1	300	20.2	3000	3.97	26.26922	85.36168	Normal
6/7/22	13:22:0	70	0.1	220	20.2	2200	3	26.26976	85.36247	Normal
6/7/22	13:22:17	70	0.1	190	10.1	1900	2.76	26.27068	85.36263	Normal
6/7/22	13:22:17	70	0.1	180	20.2	1800	2.63	26.27157	85.36286	Normal
6/7/22	13:23:0	70	0.1	170	20.2	1700	2.51	26.27239	85.3633	Bridge
6/7/22	13:23:0	70	0.1	240	20.2	2400	2.38	26.27272	85.36424	Normal
6/7/22	13:23:27	70	0.1	210	30.3	2100	3.25	26.27322	85.36503	Normal
6/7/22	13:23:27	70	0.1	230	30.3	2300	2.88	26.27408	85.36542	Normal
6/7/22	13:23:27	70	0.1	220	30.3	2200	3.13	26.27485	85.36582	Normal
6/7/22	13:24:0	70	0.1	170	20.2	1700	3	26.27566	85.36636	Normal
6/7/22	13:24:3	70	0.1	290	30.3	2900	2.38	26.27622	85.3671	Normal
6/7/22	13:24:3	70	0.1	160	30.3	1600	3.85	26.27654	85.36801	Normal
6/7/22	13:24:38	70	0.1	180	20.2	1800	2.26	26.27699	85.36889	Normal
6/7/22	13:24:38	70	0.1	176	176	176	2.51	26.27756	85.36966	Normal

$$Y = 0 * X^2 + 0.989 * X - 13.58$$

$$X = 1200$$

$$Y = 1173$$

(R) RURAL ROAD

Good Average Poor

<4000 4001-5000 >5001

26/7/22

Road Name:-Minapur PWD Road to Gosai pur Tengraha										
Date	Time	Section	Length	Bumps	Speed	OR	TEGORY	IRI	Latitude,ongitude	Event
6/7/22	13:25:0	70	0.1	230	20.2	2300	2261 G	3.13	26.27824 85.37037	Normal
6/7/22	13:25:13	70	0.1	190	30.3	1900	1865 G	2.63	26.2789 85.37106	Normal
6/7/22	13:25:13	70	0.1	180	20.2	1800	1766 G	2.51	26.27915 85.37189	Normal
6/7/22	13:25:48	70	0.1	240	20.2	2400	2360 G	3.25	26.27986 85.37241	Normal
6/7/22	13:26:0	70	0.1	260	10.1	2600	2557 G	3.49	26.2807 85.37288	Curve
6/7/22	13:26:24	70	0.1	150	10.1	1500	1469 G	2.13	26.28051 85.37382	Normal
6/7/22	13:26:24	70	0.1	140	20.2	1400	1371 G	2	26.27988 85.37441	Normal
6/7/22	13:26:59	70	0.1	180	20.2	1800	1766 G	2.51	26.27913 85.37495	Normal
6/7/22	13:27:0	70	0.1	140	20.2	1400	1371 G	2	26.27827 85.3754	Normal
6/7/22	13:27:0	70	0.1	230	20.2	2300	2261 G	3.13	26.27747 85.37593	Normal
6/7/22	13:27:33	70	0.1	150	20.2	1500	1469 G	2.13	26.27679 85.37652	Normal
6/7/22	13:27:33	70	0.1	150	20.2	1500	1469 G	2.13	26.27668 85.37754	Normal
6/7/22	13:27:33	70	0.1	150	20.2	1500	1469 G	2.13	26.27652 85.37847	Normal
6/7/22	13:28:0	70	0.1	150	30.3	1500	1469 G	2.13	26.27652 85.37847	Normal
6/7/22	13:28:9	70	0.1	200	20.2	2000	1964 G	2.76	26.27627 85.37949	Normal
6/7/22	13:28:9	70	0.1	210	30.3	2100	2063 G	2.88	26.27601 85.38039	Normal
6/7/22	13:28:44	70	0.1	160	30.3	1600	1568 G	2.26	26.27599 85.38136	Normal
6/7/22	13:28:44	70	0.1	210	30.3	2100	2063 G	2.88	26.2759 85.38241	Normal
6/7/22	13:29:0	70	0.1	300	20.2	3000	2953 G	3.97	26.2758 85.3834	Normal
6/7/22	13:29:19	70	0.1	180	20.2	1800	1766 G	2.51	26.27595 85.38438	Normal
6/7/22	13:29:19	70	0.1	250	20.2	2500	2458 G	3.37	26.27606 85.38539	Normal
6/7/22	13:30:0	70	0.1	140	10.1	1400	1371 G	2	26.27639 85.38626	Normal
6/7/22	13:30:0	70	0.1	200	20.2	2000	1964 G	2.76	26.27718 85.38662	Normal
6/7/22	13:30:30	70	0.1	160	20.2	1600	1568 G	2.26	26.27807 85.38695	Normal
6/7/22	13:30:30	70	0.1	210	10.1	2100	2063 G	2.88	26.27895 85.38734	Normal
6/7/22	13:31:5	70	0.1	190	20.2	1900	1865 G	2.63	26.27979 85.38774	Normal
6/7/22	13:31:5	70	0.1	260	20.2	2600	2557 G	3.49	26.28068 85.38808	Normal
6/7/22	13:31:5	70	0.1	260	20.2	2600	2557 G	3.49	26.28154 85.38843	Normal
6/7/22	13:31:5	70	0.1	190	20.2	1900	1865 G	2.63	26.28231 85.38884	Normal
6/7/22	13:31:40	70	0.1	300	20.2	3000	2953 G	3.97	26.28317 85.38899	Normal
6/7/22	13:32:0	70	0.1	290	10.1	2900	2854 G	3.85	26.28414 85.38919	Normal
6/7/22	13:32:16	70	0.1	230	0	2300	2261 G	3.13	26.28478 85.38983	Normal

26.28478

85.38983

Normal

26/7/22

Date	Time	Section	Length	Bumps	Speed	OR	TEGORY	IRI	Latitude	ongitude	Event
6/7/22	13:33:26	70	0.1	220	10.1	2200	2162 G	3	26.28514	85.39049	Normal
6/7/22	13:33:26	70	0.1	210	20.2	2100	2063 G	2.88	26.28469	85.39136	Normal
6/7/22	13:34:1	70	0.1	170	20.2	1700	1667 G	2.38	26.28383	85.39145	Normal
6/7/22	13:34:1	70	0.1	240	20.2	2400	2360 G	3.25	26.28294	85.39146	Normal
6/7/22	13:34:37	70	0.1	190	20.2	1900	1865 G	2.63	26.28199	85.39162	Normal
6/7/22	13:34:37	70	0.1	230	30.3	2300	2261 G	3.13	26.28112	85.39184	Normal
6/7/22	13:35:0	70	0.1	210	30.3	2100	2063 G	2.88	26.28029	85.39222	Normal
6/7/22	13:35:12	70	0.1	210	30.3	2100	2063 G	2.88	26.27952	85.39276	Normal
6/7/22	13:35:12	70	0.1	200	20.2	2000	1964 G	2.76	26.2789	85.39357	Normal
6/7/22	13:37:0	70	0.1	120	0	1200	1173 G	1.74	26.27924	85.39593	Normal
AVG:-						2009.915					

Road Name:-Minapur PWD Road to GosaiपुरTengraha

01/07/22
25

26/6/22

26/6/22