

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल- बक्सर

पत्रांक- 433 / बक्सर

दिनांक- 20/03/23

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल- बक्सर

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण (BRRDA)
बुद्ध मार्ग, पटना।

विषय- शीर्ष 3054 (बिहार ग्रामीण पथ अनुरक्षण नीति- 2018) योजना अंतर्गत राशि की अधियाचना के
सम्बन्ध में।

महोदय,

उपर्युक्त विषय के सम्बन्ध में कहना है कि योजना शीर्ष 3054 मरम्मत (बिहार ग्रामीण पथ अनुरक्षण नीति-
2018) अंतर्गत कराये गए कार्यों के भुगतान हेतु राशि की आवश्यकता है जिसे अधियाचना प्रपत्र के साथ सलंग्न कर
भेजा जा रहा है।

अतः श्रीमान से अनुरोध है कि सलंग्न विवरणी के अनुसार आवंटन उपलब्ध कराने की कृपा की जाए ताकि
संवेदकों द्वारा कराये गए कार्य का भुगतान किया जा सके।

अनु०- यथोक्त

विश्वासभाजन


20.03.23

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर


20/03/23

FORM GFR 19-A
(SEE Government of India's Decision (I) below Rule-150)
Form of Utilisation Certificate upto the month of Dec 2018

MR (3054) New Maintenance Policy 2018

PIU - RWD (W), Div.- Buxar

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
1	Construction of Rural Roads under MR (3054) Maintenance	Lt. No.- 32, dt.-03.03.2023	6985.97121	Certified that out of Rs. 6985.97121 lacs received during the years in favour of Ex. Engineer, RWD (W), Div.- Buxar Bihar, a sum of Rs. 6966.02771 lacs been utilized for the purpose of MR (3054) New Maintenance Policy 2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 19.90435 lacs remaining unutilized at the end of the period under

Total -

- 2 Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/ Supertending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Supertending Engineer.
- Construction materials have been tested
- Measurements have been recorded in the MBs and test check conducted by the Assistant.
- All other codal formalities have been observed.

- 3 **Physical Progress achieved :-**

- Construction of Road works
- Construction of CD works

20.03.23

Executive Engineer

R.W.D. (w) Div. Buxar

AK
20/03/23

Requisition Format for Scheme Head- MR (3054) under Bihar Rural Road Maintenance Policy- 2018 (Initial Rectification and Surface Renewal)

Name of Works Division- RWD, Works Division- Buxar

Sl No	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (In Lakh)		Agreement No. & Date	Date Of Completion as per Agreement	Value of R/I (In mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allotted Amount (In Lakh)	up- to- date expenditure as per MIS (In Lakh)	Requisition against work done (In Lakh)	Remarks
					Length (in KM)	Amount (In Lakh)	Initial Rectification With Surface Renewal (In Lakh)	5 Years Routine Maintenance (In Lakh)									
1	RM/BU/BU X/22/0012	Tiyara Dhamsoi Road - Matakipur	10402002056	Letter No 1486 & 8/09/2022	3.65	164.563	121.98486	45.83725	17/MBD/2022-23 & 22.02.2023	21.11.2023	2476	25MM	5.01%	110.31776	108.89563	11.61581	

1. Signed Hard Copy and Soft Copy (in excel) of recorded IRI is enclosed
2. Up- to- date Physical Progress has been uploaded in MIS

11.6671

Executive Engineer
RWD (W), Div.- Buxar


AK
20103123

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, बक्सर

का0आ0र 370 बक्सर/ दिनांक 07/03/23


कार्यालय आदेश

प्रमाणित किया जाता है कि बिहार ग्रामीण पथ अनुरक्षण नीती-2018
योजनान्तर्गत Tiyara Dhansol Road - Matakipur पथ का कार्य गुणवत्ता एवं विशिष्टियों
के अनुरूप पूर्ण कराया गया है। पथ के मापीपुस्त की जाँच मेरे द्वारा 10 प्रतिशत
एवं कमीय अभियंता के द्वारा शत प्रतिशत किया गया है।


07.03.23


कमीय अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रशाखा बक्सर

A.E.
RWD Buxar


07.03.23
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर

File :E:\ag vinod mishra\New folder\07031526.Xls. Section No.:78, Eqn: $Y = 0 \cdot X^2 + 1.136 \cdot X + 132.5$

Name of Customer :M/S Vinod Kumar Misahra, Name of Work/ Road :Tiyara Dhansoi To Matakipur, Lab Job



[Signature]
07/03/23
S.E.

[Signature]
07/03/23

Road Name :- Tiyara Dhansoi To Matakipur Contractor Name:- M/S Vinod Kumar Mishra

Date	Time	Section	No.	Length	Bumps	Speed	OR	IRI/TEGORY	Latitude	ongitude	Event
				in km	in mm	mm/km	mm/km	ROAD			
7/3/23	14:4:0	78	0.1	310	0	2400	1569 G	25.94456 83.99739 Normal			Y = 0 * X ^ 2 + 1.136 * X + 132.5
7/3/23	14:4:32	78	0.1	260	20.2	2000	1923 G	25.94377 83.99719 Normal			X = 3200
7/3/23	14:5:0	78	0.1	270	10.1	2700	2536 G	25.94297 83.997 Normal			Y = 3767
7/3/23	14:5:7	78	0.1	380	10.1	3300	2856 G	25.94232 83.99598 Normal			
7/3/23	14:5:7	78	0.1	340	20.2	2400	2858 G	25.94232 83.99548 Normal			(R) RURAL ROAD
7/3/23	14:5:42	78	0.1	380	20.2	3300	2463 G	25.94232 83.99514 Normal			Good Average Poor
7/3/23	14:6:0	78	0.1	290	20.2	2200	2631 G	25.93978 83.99458 Normal			<4000 4001-5000 >5001
7/3/23	14:6:13	78	0.1	280	30.3	1400	1722 G	25.93882 83.99443 Culvert			
7/3/23	14:6:13	78	0.1	330	20.2	2300	2745 G	25.93872 83.99409 Normal			IRI Value=2476
7/3/23	14:6:13	78	0.1	220	30.3	2300	2745 G	25.93751 83.99397 Normal			Machine ID=415
7/3/23	14:6:49	78	0.1	280	30.3	2800	3313 G	25.93784 83.99347 Normal			
7/3/23	14:7:0	78	0.1	320	20.2	1400	1722 G	25.93547 83.993 Normal			
7/3/23	14:7:22	78	0.1	290	20.2	2000	2404 G	25.9343 83.99233 Normal			
7/3/23	14:7:22	78	0.1	300	20.2	3200	2489 G	25.94976 83.9916 Speed Breaker			
7/3/23	14:7:57	78	0.1	280	20.2	2800	2469 G	25.94909 83.99127 Normal			
7/3/23	14:7:57	78	0.1	300	20.2	3000	2569 G	25.94876 83.99093 Normal			
7/3/23	14:8:33	78	0.1	250	20.2	2500	2972 G	25.94826 83.99043 Normal			
7/3/23	14:8:33	78	0.1	280	10.1	2400	2858 G	25.93092 83.98995 Speed Breaker			
7/3/23	14:9:11	78	0.1	360	10.1	2000	2404 G	25.9305 83.98937 Normal			
7/3/23	14:9:46	78	0.1	380	10.1	2700	2539 G	25.93024 83.98832 Normal			
7/3/23	14:12:7	78	0.1	300	10.1	3300	2269 G	25.92988 83.9879 Normal			
7/3/23	14:12:42	78	0.1	240	10.1	2400	2858 G	25.92958 83.98732 Normal			
7/3/23	14:13:18	78	0.1	270	10.1	3300	2645 G	25.92923 83.98672 Normal			
7/3/23	14:13:53	78	0.1	240	10.1	2200	2631 G	25.92898 83.98648 Normal			
7/3/23	14:14:28	78	0.1	200	10.1	1400	1722 G	25.92829 83.98622 Normal			
7/3/23	14:15:39	78	0.1	270	10.1	2300	2745 G	25.92794 83.98582 Speed Breaker			
7/3/23	14:16:14	78	0.1	330	10.1	2300	2745 G	25.92728 83.9854 Speed Breaker			
7/3/23	14:16:49	78	0.1	240	10.1	2800	2601 G	25.92639 83.98515 Normal			
7/3/23	14:17:24	78	0.1	330	10.1	1400	1722 G	25.92611 83.98495 Normal			
7/3/23	14:17:24	78	0.1	220	10.1	2000	2404 G	25.92543 83.98465 Normal			
7/3/23	14:18:0	78	0.1	140	10.1	3200	2886 G	25.92498 83.9841 Normal			
7/3/23	14:18:0	78	0.1	230	10.1	2300	2745 G	25.92439 83.98498 Normal			
7/3/23	14:18:35	78	0.1	230	10.1	2300	2745 G	25.92388 83.98528 Normal			
7/3/23	14:19:10	78	0.1	280	10.1	2800	2456 G	25.92349 83.98548 Normal			
7/3/23	14:19:10	78	0.1	140	30.3	1400	1722 G	25.92271 83.98552 Normal			
7/3/23	14:19:10	78	0.1	200	10.1	2000	2404 G	25.92221 83.98565 Normal			
7/3/23	14:22:10	78	0.05	160	10.1	2800	2545 G	25.92181 83.98567 Normal			

Handwritten signature and date: 07/13/23

Handwritten text: 07/03/23