


Name of Customer : Murtidhar Singh
 Name of Work/ : Sheosagar Path to Chenaidih taluk
 Road :
 Lab Job number : 81
 Date : 21-03-2023
 Section No. : 81

Print Generate Report and Graph

Test Date : 21-03-2023
 Road Name : Sheosagar Path to Chenaidih taluk
 Road Type : (R) RURAL ROAD
 Side :
 Machine No : 391
 Start S No : 03
 Start E No : 12
 Interval :
 Weather : Normal
 UV Range : 1915 To 4000 mm/km
 Dist Range : 0 To 1.1 * 1000 m
 Start Location : 192.83.884747
 End Location : 873.83.884107
 Equation : $Y = 0.0002 \cdot X^2 + 1.000 \cdot X + 415.2$

Redraw Graph

Map View



Activate Windows

Go to Settings to activate Windows

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सासाराम-1

Email ID:-ee.rwd.sasaram1@gmail.com

Mob:- 8986915310

पत्रांक.....609 अगस्त

सासाराम / दिनांक...21.03.23

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-1

सेवामें,

नोडल पदाधिकारी (MR 3054)
ग्रामीणकार्यविभाग
पटना, बिहार

विषय :- नई अनुस्क्षण नीति-2018MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के विरूद्ध आवंटन उपलब्ध कराने के संबंध में।

महाषय,

उपरोक्त विषय के संबंध में सूचित करना है कि नई अनुस्क्षण नीति-2018 MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के लिए संवेदक को भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है।

अनु० :- यथोक्त।

विष्वासमाजन

NKUSGMR
21.03.23

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-1

21/03/23

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilization Certificate up to MARCH 2023

Sl.No	Name of Scheme	Sanction No.&Date With Amount (In lace Rs.)	Amount Received (In lace Rs.)	Particulars
1	Construction of Rural roads Under MR	New Maintenance Policy-2018 MR (3054) BRRDA PATNA	10057.30152	Certified that out of Rs. 10057.30152 lakh of grants-in-aid sanctioned during the years 2021-23 In favor of EE, RWD works division Sasaram-1 a sum of Rs 9637.73424akh has been utilized for the purpose of MR (3054) Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 419.56728 lakh remaining unutilized at the end of the period under report.
	Total:		10057.30152	

2. Certified that I have satisfied my self that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-

- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- All other caudal formalities have been observed.

3. Physical Progress achieved:-

- Construction of Road Works.
- Construction of CD works.


Divisional Accounts Officer
R.W.D, works Division
Sasaram-1


Executive Engineer
R.W.D, works Division


OFFICE OF EXECUTIVE ENGINEER, RURAL WORKS DEPARTMENT, WORKS DIVISION, SASARAM-1

Registration Format for Scheme Head- MR(3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division:- Sasaram-1

Sl no.	Batch No	Name of Road	Project ID as per MIS	Administrative Approval (AA) Date	Length (in km)	Amount of (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)	Agreement Amount (in Lakh)	Agreement Completion Date	Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	Up-to-date expenditure as per MIS (in Lakh)	Requisition done against work (in Lakh)	Remarks
1	RM/RO/ SAS/23/ 0004	Road from Chhenari - Shiosagar Path - Basti Path	10301101029	611 15.07.2022	1.000	58.093	45.96393	12.36351	12MBD/2 2-23	1-Nov-23	0	3165	25.00	5.00				44.96388	
Total																			
					1.000	58.093	45.96393	12.36351										44.96388	

Divisional Accounts Officer
Rural Works Department,
Works Division, Sasaram-1
21/03/23

Executive Engineer
Rural Works Department
Works Division, Sasaram-1
21.03.23
21/03/23

Name of Road:- Chenari-Sheosagar Path Se Chenaridih Tak

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event
		No.	In km	In mm	Rate	mm/km	mm/km	ROAD			
21/3/23	8:39:0	81	0.1	280	10.1	2800	3215	G	24.968192	83.884747	Curve
21/3/23	8:39:29	81	0.1	260	10.1	2600	3015	G	24.967322	83.884545	Normal
21/3/23	8:40:0	81	0.1	290	10.1	2900	3315	G	24.96648	83.884242	Normal
21/3/23	8:40:4	81	0.1	250	20.2	2500	2915	G	24.96567	83.883922	Normal
21/3/23	8:40:4	81	0.1	280	20.2	2800	3215	G	24.96482	83.884157	Curve
21/3/23	8:40:39	81	0.1	280	20.2	2800	3215	G	24.964268	83.884848	Normal
21/3/23	8:43:0	81	0.1	250	10.1	2500	2915	G	24.963965	83.885842	Speed Breaker
21/3/23	8:44:10	81	0.1	290	10.1	2900	3315	G	24.964023	83.88574	Curve
21/3/23	8:44:45	81	0.1	290	10.1	2900	3315	G	24.964277	83.88483	Normal
21/3/23	8:45:0	81	0.1	280	20.2	2800	3215	G	24.964873	83.884107	Culvert
Average IRI											
3165											

$$Y = 0 * X^2 + 1.000 * X + 415.2$$

$$X = 2800$$

$$Y = 3215$$

(R) RURAL ROAD

Good Average Poor

<4000 4001-5000 >5001

Executive Engineer
Rural Work's Department
Work Division, Sasaram-1

21.03.23

21/03/23
AC

21.03.23
J.E.
21.03.23
J.E.