

[illegible]

PART-'B'

WEST SURF WEST BOOK

मापि त्रुटि न भवितुम् - 1309/2022-23

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
		1st R/A			
		<u>Abstract of cost</u>			
①/4	Bored cast-in-situ				
	M35 grade RCC pile				
	do complete job				
75.04	(vide TMB		Pg-	(02/5)	
75.04	(u u		Pg-	(03/2)	
75.04	(u u		Pg-	(04/2)	
75.04	(u u		Pg-	(05/2)	
75.04	(u u		Pg-	(06/2)	
75.04	(u u		Pg-	(07/2)	
75.04	(u u		Pg-	(08/2)	
75.04	(u u		Pg-	(09/2)	
75.04	(u u		Pg-	(10/2)	
75.04	(u u		Pg-	(11/2)	
75.04	(u u		Pg-	(12/2)	
75.04	(u u		Pg-	(13/2)	
900.04	@ Rs 16548 = 10/4	= Rs 1,48,932.00.			
②/5	S/F/P HYSD bar Reinforcement				
	in formation do				
7.610 MT	(vide TMB		Pg-	(02/4)	
7.610 MT	(u u		Pg-	(03/1)	
7.610 MT	(u u		Pg-	(04/1)	
7.610 MT	(u u		Pg-	(05/1)	
7.610 MT	(u u		Pg-	(06/1)	

Continuation

16
Sch. XLV-Form No. 134

Particulars	Details of actual measurement			Contents of area
	No.	L.	B.	D.
		B/F	R ₂	2, 25, 88, 926 = ∞
		A ₂₂ 12 y. 457 A ₂		27, 10, 671 = ∞
		A ₂₂ 1 y. 1.000 (+)		2, 25, 889 = ∞
		(A) -	R ₂	2, 55, 25, 486 = ∞
		A ₂₂ S. Fee @ 10%		
(i)		Service Road = 37.50 m		
		37.50 x 522.0 x 10% =	R ₂	1958 = ∞
(ii)		RCC H-35 pile = 900 m		
		900.0 x 663.0 x 10% =	R ₂	59670 = ∞
		Total S. Fee	R ₂	61628 = ∞
		(+) B/F (A) -	R ₂	2, 55, 25, 486 = ∞
			R ₂	2, 55, 87, 114 = ∞

less 4.44% (C) R₂ 11,36,068 = ∞

R₂ 2,44,51,046 = ∞

[Signature]

13-5-2023

05

13/5/23

13