

पंजाब एग्रीकल्चरल यूनियन लिमिटेड का
एक शाखा (World Bank)

Schedule XLV-Form No. 134

014-242

DIVISION

215193

SUB-DIVISION

Measurement Book

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5th year maintenance B211					
Name of work - Tijara Dhanuoi					
Road to Baban K. Deora via					
Piriza and Harizautoli					
Agency - Hemant K. Singh					
Ag No - 33NBD/16-17					
① Restoration of rain cuts					
2 x 2 x 30m x 1.125 x 0.30 =					40.50m ²
6 x 20m x 1.125 x 0.30 =					40.50m ²
					81.00m ²
					80.55m ²
② Maintenance of shoulders					
10 x 25m x 1.125 =					281.25m ²
10 x 15m x 1.125 =					168.75m ²
					450.00m ²
					447.48m ²
③ Repair of pot holes by					
Bm.					
3 x 2.80m x 1.90 x 0.075 =					1.197m ²
4 x 3.80m x 2.70 x 0.075 =					3.078m ²
5 x 3.75m x 2.90 x 0.075 =					4.078m ²
6 x 3.60m x 3.05 x 0.075 =					4.941m ²
3 x 2.75m x 2.75 x 0.075 =					0.618m ²
					13.912m ²
④ Maintenance of CD (H.P.) - 4 No.					
⑤ Maint. of Road sign - 0.95 Km					
⑥ Maint. of 200m R.K. Stone - 1.85 Km					

Continuation

