

4 year maintenance

69

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work: Rajarajmangalam main Road to Cherkha Tuntun Baitha Keshar muslim Tolga Talu					
2. Agency: Arun Singh cons-2 Suppliers Pvt Ltd.					
3. Agreement No: 149/SBD/2018-2019					
4. Actual dt. of completion: 28.02.2020					
Measurement as below					
① Restoration of drain cuts with soil - do fill					
20 x 15.0 x 0.90 x 0.30 = 81.0					
15 x 16.0 x 0.80 x 0.30 = 57.6					
17 x 20.50 x 0.70 x 0.30 = 7.305					
2 x 18.50 x 0.80 x 0.30 = 8.88					
3 x 20.90 x 0.70 x 0.30 = 13.167					
4 x 18.50 x 0.65 x 0.30 = 14.43					
3 x 20.90 x 0.71 x 0.30 = 13.35					
1 x 2.90 x 0.65 x 0.30 = 0.56					
1 x 1.50 x 0.60 x 0.30 = 0.27					
					Qty = 174.37
					Say Qty = 174.15
② maintenance of earthen shoulder					
do fill					
2 x 30 x 30.0 x 0.75 = 450					
1 x 20.50 x 0.65 = 13.32					
1 x 20.90 x 0.70 = 14.6					

Continuation

C.O Qty = 477.9

P. 770

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			BFR 172781 = cu		
④ patch repair on already filled pot holes with 75 mm WBSM surface					
Qty = 20.56 m ² vide TMB page 71					
⑤ 300 = 40 / m ² — R 6599 = cu					
⑤ maintenance of Hume pipe culvert — du E11					
Qty = 2.0 nos vide TMB page 71					
⑥ 1117 = cu / each — R 2239 = cu					
⑥ maintenance of slab type culvert — du E12					
Qty = 8.0 nos vide TMB page 71					
⑦ 2309 = 03 / each — R 18472 = cu					
⑦ maintenance of drain sign — du E12					
Qty = 2.42 km vide TMB page 71					
⑧ 1079 = 51 / km — R 2600 = cu					
⑧ maintenance of drain 8 km stone — du E11					
Qty = 2.42 km vide TMB page 72					
⑨ 735 = 27 / km — R 1779 = cu					
					R 258415 = cu

