

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, समस्तीपुर
e-mail- eerwdsamastipur@gmail.com

पत्रांक 804 8/30 दिनांक 8/4/24

प्रेषक:—

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, समस्तीपुर।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी—सह—सचिव
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय:—

शीर्ष New Maintenance Policy 2018 मद में आवंटन उपलब्ध कराने के संबंध में।


महाशय,

उपर्युक्त विषयक शीर्ष New Maintenance Policy 2018 योजनान्तर्गत निर्मित/
निर्माणाधीन पथों का विहित प्रपत्र में अधियाचना पत्र संलग्न कर भेजा जा रहा है।

अतः अनुरोध है कि संलग्न अधियाचना पत्र के अनुसार आवंटन उपलब्ध कराने की कृपा
की जाय।

अनु०—यथोक्त।

विश्वासभाजन


कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, समस्तीपुर
Rw.
8.4.24

FROM GFR 19-A

(See Government of India's Division (I) below Rule- 150)

Form of Utilization Certificate upto 08.04.2024

PIU- E.E., R.W.D. Works Division, Samastipur

S.N.	Name of Scheme	Sanction No.& Date	Amount Received	Particulars
1	Construction of Rural Road under New Maintenance Policy-2018	Secretary cum Empowered Officer BRRDA Bihar Patna vide upto Lt. n.-47, dt.25.03.2024	932441238.00	Certified that out of Rs.932441238.00 received upto 08.04.2024 in favour of Executive Engineer R.W.D. Works Division Samastipur a sum of Rs.910507560.00 has been utilized for the purpose of New Maintenance Policy-2018 Schemes as given in the margine for which it was sanctioned and that the balance of Rs.21933678.00 remaining unutilized at the end of period under report.
			93,24,41,238.00	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for the which it was sanctioned.

Kind of Checks exercised:-

- i Works have been supervised by Executive/Superintending engineer.
- ii Periodical inspection has been conducted by Executive/Superintending engineer.
- iii Construction materials have been tested.
- iv Measurements have been recorded in the MB's and test check conducted by Assistant Engineer/Executive
- v All other codal formalities have been observed.

3 Physical Progress achieved:-

- i Construction of Road work.
- ii Construction of CD works.

[Signature]
Executive Engineer

Works Division Samastipur

Rural Works Dipartment

[Signature]
8.4.24

Requisition Format for scheme Head : MR(3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

RWD, Works Division : Samastipur																			
Sl No	Package No	Project ID as Per MIS	Name of Road	Administrative Approval (AA) Letter No & Date		Administrative		Agreement Amount		Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in MM)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	Upto date Expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
				Length (Km)	Amount (in Lakh)	Initial Rectification with Surface Renewal	5 Year Routine Maintenance												
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	
1	RM/SA/SAM/24/0004	32016113011	T03 Bhoze jaranpur To Bhawanipur harigan Tola	2328 & 04.05.2023	1.340	106.180	89.288	9.567	23(MBD)2023-24	10.07.2024	Complete	2893	25	5.0	0	0	85.200	Complete	
Total																			
85.200																			

- 1 Signed Hard Copy and Soft Copy (In Excel) of recorded IRI is enclosed.
- 2 Up-to-date Physical Progress has been uploaded in MIS


 Executive Engineer
 RWD (W) Div. Samastipur
 8.4.24

Name of Road:- T03 Bhore Jairampur To Bhawanipur Harijan Tola.

Section no.-68

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY	Latitude	Longitude	Event
1/4/24	14:10:9	68	0.1	250	0	2500	2972	ROAD	25.81588	85.918448	Normal
1/4/24	14:10:41	68	0.1	240	10.1	2400	2858	G	25.815995	85.919055	Normal
1/4/24	14:11:13	68	0.1	230	10.1	2300	2745	G	25.816116	85.920133	Normal
1/4/24	14:11:46	68	0.1	240	10.1	2400	2858	G	25.816599	85.92085	Curve
1/4/24	14:12:11	68	0.1	230	10.1	2300	2745	G	25.817376	85.92072	Normal
1/4/24	14:12:52	68	0.1	250	10.1	2500	2972	G	25.817936	85.920216	Normal
1/4/24	14:13:8	68	0.1	230	10.1	2300	2745	G	25.818054	85.919224	Curve
1/4/24	14:13:41	68	0.1	240	10.1	2400	2858	G	25.818985	85.919367	Normal
1/4/24	14:14:13	68	0.1	250	10.1	2500	2972	G	25.81972	85.919939	Normal
1/4/24	14:14:51	68	0.1	240	10.1	2400	2858	G	25.820547	85.920228	Curve
1/4/24	14:15:10	68	0.1	260	10.1	2600	3086	G	25.821412	85.920418	Normal
1/4/24	14:15:48	68	0.1	250	10.1	2500	2972	G	25.822256	85.92074	Normal
1/4/24	14:16:8	68	0.1	250	10.1	2500	2972	G	25.823051	85.921139	Normal
Total=			1.30	Km	Avg. 2893.31						

04/04/24
04/04/24

[Signature]
Executive Engineer
R.W.D.(W) Division,
Samastipur

Name of Customer : Praveen Kumar
 Name of Work/ Road : T03 Bhore Jairampur To Bhawe
 Lab Job number : 68
 Date : 01.04.2024
 Section No. : 68

Test Date : 01.04.2024
 Machine No : 396
 Start S No :
 Start E No :
 Weather :
 Start Location :
 End Location :
 Road Name : T03 Bhore Jairampur To Bhawe
 Road Type : (R) RURAL ROAD
 Side :
 Interval :
 UIV Range : 1745 To 4000 mm/km
 Dist Range : 0 To 1.4
 Equation : $Y = 0 * X^2 + 1.136 * X + 132.5$

Print Generate Report and Graph

Redraw Graph

Map View

File : C:\Users\USER\Desktop\T03 Bhore Jairampur To Bhawanipur Harijan Tola 1340m\27021417.Xls, Section No.
 Name of Customer : Praveen Kumar, Name of Work/ Road : T03 Bhore Jairampur To Bhawanipur Harijan Tola, Lab

UIV
mm/
km

2745

1745

Distance * 1000 m

1.3

1.2

1.1

1

0.9

0.8

0.7

0.6

0.5

0.4

0.3

0.2

0.1

0

04/04/24
 124
 58

04/04/24
 124
 58