

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, वायसी।

पत्रांक 321

वायसी / दिनांक 09/04/2024

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, वायसी।

सेवा में,

नोडल पदाधिकारी,
MR 3054 नई अनुरक्षण नीति 2018,
ग्रामीण कार्य विभाग,
बिहार, पटना।

विषय: शीर्ष MR 3054 नई अनुरक्षण नीति 2018 अंतर्गत पथ में कराये गए कार्य के विरुद्ध अधियाचना भेजने के संबंध में।


महाशय,

उपर्युक्त विषय के संबंध में कहना है कि शीर्ष MR 3054 नई अनुरक्षण नीति 2018 अंतर्गत पथ में कराये गए कार्य के विरुद्ध अधियाचना इस पत्र के साथ समर्पित की जा रही है।

विश्वासभाजन,


09/04/24

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, वायसी।


09/04/2024.

OFFICE OF EXECUTIVE ENGINEER, RURAL WORKS DEPARTMENT, WORKS DIVISION, Baisi (Purnia)

Format for Scheme Head- MR(3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)
Division:- Baisi (Purnia)

Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No & Date	Administrative Approval (AA)		Agreement Amount (In Lakh)		Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allotted Amount (in Lakh)	up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
			Length (in km)	Amount of (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)									
3	4	5	6	7	8	9	11	12	13	14	15	16	17	18	19
L061 - T03 to Dengh baraili (VR61)	21105402034	995 & 05.08.2023	2	103.4660	93.09971	17.8049	31-08-2024	-	3108	25.00	5.02	0.00	0.00	93.09961	
Putani Chowk Pul To Islampur	21105413007	123 & 06.07.2023	1.4	89.72800	89.20446	11.47285	31-08-2024	-	2874	25.00	5.02	0.00	0.00	89.20436	
Durpaili To Kewbart Tola	21105413008	995 & 05.08.2023	1.468	104.2460	99.27177	18.5236	31-08-2024	-	2917	25.00	5.02	0.00	0.00	99.27166	

Signature

Executive Engineer
Rural Works Department
Works Division, Baisi
(Purnia)

Nivedita W.
09/04/24

Name of Customer: Ashok Kumar Gupta
 Name of Work: Dhurpali To Kewarath Tola
 Road:
 Lab Job number: 73
 Date: 09-04-2024
 Section No: 73


Test Date: 09-04-2024
 Road Name: Dhurpali To Kewarath Tola
 Machine No: 1398
 Road Type: (A) ASPHALTIC
 Start S No:
 Side:
 Start E No:
 Interval:
 Weather:
 UIV Range: 909 To 4000 mm/km
 Start Location:
 Dist Range: 0 To 15 01 -1000 m
 End Location:
 Equation: $Y=0.7X^2+0.989X+13.58$

Print Generic Report and Graph

Redraw Graph

Map View

File D:\Bump Ashok\Dhurpali To Kewarath Tola.xlsx Section No.: 73. Eqn: $Y=0.7X^2+0.989X+13.58$
 Name of Customer: Ashok Kumar Gupta, Name of Work: Road :Dhurpali To Kewarath Tola, Lab Job number :73



Thanks
 9.4.24
 J.E

9/9/24
 10E

Name Of Work-Dhurpuli To Kewarath Tola

Date	Time	Section	Length	Bumps	Speed	OR	IRI	ATEGORY	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD			
9/4/24	11:5:45	73	0.1	280	0	2800	2903	G	26.249957	86.81579	Normal
9/4/24	11:12:26	73	0.1	210	20.2	2100	2103	G	26.117822	86.579258	Normal
9/4/24	11:12:56	73	0.1	300	20.2	3000	3103	G	26.119007	86.584123	Normal
9/4/24	11:13:22	73	0.1	320	30.3	3200	3303	G	26.118578	86.583215	Normal
9/4/24	11:13:55	73	0.1	190	20.2	190	1909	G	26.118327	86.582205	Normal
9/4/24	11:14:17	73	0.1	310	20.2	3100	3203	G	26.118327	86.582205	Speed Bre
9/4/24	11:14:47	73	0.1	310	20.2	3100	3203	G	26.11818	86.581212	Normal
9/4/24	11:15:20	73	0.1	200	20.2	2000	2106	G	26.118045	86.580218	Normal
9/4/24	11:15:50	73	0.1	280	10.1	2800	2903	G	26.117802	86.579242	Normal
9/4/24	11:16:22	73	0.1	310	10.1	3100	3203	G	26.118092	86.57848	Speed Breaker
9/4/24	11:16:52	73	0.1	310	10.1	3100	3203	G	26.118187	86.57843	Normal
9/4/24	11:17:25	73	0.1	320	10.1	3200	3303	G	26.117815	86.579292	Normal
9/4/24	11:17:55	73	0.1	310	20.2	3100	3203	G	26.118025	86.580218	Normal
9/4/24	11:18:35	73	0.1	310	20.2	3100	3203	G	26.118172	86.581228	Normal
Average							2917.93				

$$Y = 0 * X^2 + 0.989 * X + 13.58$$

$$X = 2205$$

$$Y = 2305$$

(R) RURAL ROAD

Good Average Poor
 <4000 4001-5001 >5001


Blank
 9.4.24
 J.E.


2917.93
 pg

कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमंडल, वायसी।
Email – rwdbaysi@gmail.com

प्रमाण पत्र

प्रमाणित किया जाता है कि पथ – Durpalli To Kewbart Tola , Project ID – 21105413008 का सभी अवयवों की जाँच शत प्रतिशत कनीय अभियंता द्वारा किया गया है। सहायक अभियंता द्वारा सभी अवयवों की 50 प्रतिशत से अधिक जाँच किया गया है। अधोहस्ताक्षरी द्वारा 10 प्रतिशत अवयवों की जाँच की गई है।


कनीय अभियंता


सहायक अभियंता


कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, वायसी।

(See Government of India's decision (I) below rule- 150)
Form of Utilization certificate up to the month of March 2023
PIU:- E.E RWD(W)DIV-Baisi

SL.NO.	Name of Schemes	Sanction No.& Date with Amount (In Lacs)	Amount received (In Lacs)	Particulars
1	2	3	4	5
1	New Maint. Policy-2018 (MR)	Lt.No-45 Dt-18.06.2020 Lt.No-47 Dt-24.06.2020 Lt.No-69 Dt-24.09.2020 Lt.No-72 Dt-07.10.2020 Lt.No-84 Dt-26.11.2020 Lt.No-1 Dt-01.01.2021 Lt.No-5 Dt-12.01.2020 Lt.No-8 Dt-23.01.2021 Lt.No-17 Dt-26.02.2021 Lt.No-20 Dt-19.03.2021 Lt.No-23 Dt-26.03.2021 Lt.No-27 Dt-04.05.2021 Lt.No-30 Dt-21.05.2021 Lt.No-40 Dt-14.06.2021 Lt.No-52 Dt-24.08.2021 Lt.No-60 Dt-09.11.2021 Lt.No-2 Dt-03.01.2022 Lt.No-5 Dt-25.01.2022 Lt.No-10 Dt-21.02.2022 Lt.No-13 Dt-29.02.2022 Lt.No-20 Dt-14.03.2022 Lt.No-27 Dt-21.03.2022 Lt.No-38 Dt-18.10.2022 Lt.No-45 Dt-18.11.2022 Lt.No-4 Dt-10.01.2023 Lt.No-17 Dt-09.02.2023 Lt.No-38 Dt-17.03.2023 Lt.No-67 Dt-27.04.2023 Lt.No-81 Dt-31.05.2023	7910.65606	Certified that out of Rs. 7910.65606 Lacs of grants-in-aid sanctioned during the years 2023-24 in favour of Executive Engineer R. W. D. Works Division, Baisi sum of Rs. 7860.50581 Lacs has been utilized for the purpose of New Maint. Policy 2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 50.15025 Lac remaining unutilized at the end of the period under report.
		TOTAL	7910.65606	

2. Certified that I have satisfied myself that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled, are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kinds of checks exercised:-

- i. Works has been supervised by Executive Engineer / Superintending Engineer.
- ii. Periodic as inspection has been conducted by Executive Engineer / Superintending Engineer.
- iii. Construction materials have been tested.
- iv. Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer / Executive Engineer.
- v. All other codal formalities have been observed.

3. Physical Progress achieved:-

- i. Construction of Road Works.
- ii. Construction of CD Works.

DIVISIONAL ACCOUNTS OFFICER

R.W.D. Works Division, Baisi



EXECUTIVE ENGINEER

R.W.D. Works Division, Baisi