

Scanned with CamScanner

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	ABSTRACT OF COST				
1/7	Maintenance of				60
	H.P. Culvert-				
01 Nos	• V.P-26				
	①	1130.67	1 Ewer	B	1131.0
2/10	Maintenance of 200m				
	and Km Post				
	0.290km V.P-26				
	②	726.47	1 Km	B	211.00
3.	Pr. not applied				
	Thermo plastic Compens				
	Paint on road edge				
	ab - E19				
	56.60 m ² V.P-26				
	④	735.44	m ²	B	41626.0
	Add 12.7.615 at 12.7.615				42968.00
	Less 10.1. below				5586.00
	= 4855.00				4855.00
	= 43699.00				43699.00
	16.2.2024 J.E				
	Total				
	16/02/24				
	A.E				