

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3rd year maintenance					
<u>Abstract of cost</u>					
(1) Restoration of Rain cut with Seal					
Qty vide TMBP 57 item 1					
40.09 m ² @ Rs 380.58 / m ²					15238 =
(2) Maintenance of earthen shoulder					
Qty vide TMBP 58 item 2					
28.30 m ² @ Rs 58.60 / m ²					5174 =
(3) Repair of pot holes bituminous surface					
Qty vide TMBP 58 item 3					
15.73 m ² @ Rs 339.24 / m ²					5336 =
(4) Repair of pot holes premix carpet and seal coat					
Qty vide TMBP - 58 item 4					
15.75 m ² @ Rs 464.24 / m ²					7312 =
(5) Patch repair of Bituminous surface					
Qty vide TMBP 59 item 5					
15.78 m ² @ Rs 322.36 / m ²					5087 =
(6) Maintenance of Slab culvert					
Qty vide TMBP 59 item 6					
2 Nos @ Rs 2309.03 / No					4618 =
(7) Maintenance of					

Continuation