

| Particulars                                         | Details of actual measurement |    |    |    | Contents of area |
|-----------------------------------------------------|-------------------------------|----|----|----|------------------|
|                                                     | No.                           | L. | B. | D. |                  |
| 3rd year maintenance                                |                               |    |    |    |                  |
| <u>Abstract of cost</u>                             |                               |    |    |    |                  |
| (1) Restoration of Rain cut with Soil               |                               |    |    |    |                  |
| Qty vide TMBP 57 item 1                             |                               |    |    |    |                  |
| 40.09 m <sup>2</sup> @ Rs 380.58 / m <sup>2</sup>   |                               |    |    |    | 15238 =          |
| (2) Maintenance of earthen shoulder                 |                               |    |    |    |                  |
| Qty vide TMBP 58 item 2                             |                               |    |    |    |                  |
| 28.30 m <sup>2</sup> @ Rs 58.60 / m <sup>2</sup>    |                               |    |    |    | 5174 =           |
| (3) Repair of pot holes bituminous surface          |                               |    |    |    |                  |
| Qty vide TMBP 58 item 3                             |                               |    |    |    |                  |
| 15.73 m <sup>2</sup> @ Rs 339.24 / m <sup>2</sup>   |                               |    |    |    | 5336 =           |
| (4) Repair of pot holes premix carpet and seal coat |                               |    |    |    |                  |
| Qty vide TMBP - 58 item - 4                         |                               |    |    |    |                  |
| 15.75 m <sup>2</sup> @ Rs 464.24 / m <sup>2</sup>   |                               |    |    |    | 7312 =           |
| (5) Patch repair of Bituminous surface              |                               |    |    |    |                  |
| Qty vide TMBP 59 item - 5                           |                               |    |    |    |                  |
| 15.78 m <sup>2</sup> @ Rs 322.36 / m <sup>2</sup>   |                               |    |    |    | 5087 =           |
| (6) Maintenance of Slab culvert                     |                               |    |    |    |                  |
| Qty vide TMBP 59 item - 6                           |                               |    |    |    |                  |
| 2 Nos @ Rs 2309.03 / No                             |                               |    |    |    | 4618 =           |
| (7) Maintenance of                                  |                               |    |    |    |                  |

Continuation