

RAJESH K. MARU VADAV

⑥

SNY Bedi Gidhar Mani to chhahi Gidhar
Schedule XLV-Form No. 134

MMGSY SC

MMGSY-SC

MMGSY-SC

Executive Engineer

RWDMM Division Karmar

DIVISION

RWDMM SUB-DIVISION

Bazari

MEASUREMENT BOOK

-1940

कार्ड

Abstract of cost

77

Sch. XLV—Form No. 134.

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) Restoration of rain					
cuts with soil—E.I.T.					
70.59m ³ O.V.T.M.B.P.—(73)					
@ 386.28/m ³ — Rs. 27268.00					
(2) Making up of berms/					
shoulder—E.I.T.					
335.18m ² O.V.T.M.B.P.—(74)					
@ 57.57/m ² — Rs. 19296.00					
(3) Repair of pot holes					
filled with 75mm BM					
3.69m ³ O.V.T.M.B.P.—(74)					
@ 9976.65/m ³ — Rs. 36814.00					
(4) Pot Repair over pot					
holes with 20mm M.S.S					
43.20m ² O.V.T.M.B.P.—(74)					
@ 251.10/m ² — Rs. 12354.00					
(5) pot repair over					
bituminous surface					
49.22m ² O.V.T.M.B.P.—(75)					
@ 262.85/m ² — Rs. 12937.00					
(6) Maintenance of					
H.P. Culverts—E.I.T.					
2.00 No. O.V.T.M.B.P.—(75)					
@ 1131.25/each — Rs. 2263.00					
(7) Maint. of Road signs—E.I.T.					
0.15km O.V.T.M.B.P.—(75)					
@ 1078.34/km — Rs. 162.00					
(8) Maint. of 200m x 8km					
stone —E.I.T.					

Continuation

Continuation