

~~Prasant  
Kumar~~

MMGSY (SC)

दिनांक 21/04/21 - 6.4.2021

# Schedule XLV-Form No. 134

mmbsy

Mindahchale to Paswan DIVISION

Tola (Haya Tola) SUB-DIVISION

## MEASUREMENT BOOK

एडमिशन आमतौर पर 7384







Particulars	Details of actual measurement			Contents of area
	No.	L.	H.	
				BF = 20.00 m <sup>2</sup>
	2	6.00	0.90	= 11.38 "
	3	7.00	0.80	= 16.80 "
	6	4.00	1.00	= 24.00 "
	1	12.00	0.95	= 11.40 "
	1	6.20	0.90	= 5.58 "
				<u>28.58 m<sup>2</sup></u>
Item (3) Repair of pot holes filled				
with 75 mm B.C. etc.				
	11	2.00	0.90	= 0.090 m <sup>3</sup>
				Limit = 0.02 m <sup>3</sup>
Item (4) Patch repair over pot holes				
with m.s.s. carpet with				
seal coat - do - etc.				
	1	6.15	1.20	= 7.38 m <sup>2</sup>
Item (5) Patch repair over B.T.				
Surface with 20 mm p.c.				
with seal coat - do - etc.				
	2	4.10	0.90	= 7.38 m <sup>2</sup>
Item (6) Filling of cracks & joints				
using liquid bituminous				
seal coat - do - etc.				
Continuation				Qty = 315.00 m <sup>3</sup>

PTD



Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Item (7)	digout treatment of isolated failed pavement.				
	--- do --- do --- do --- etc				
	1x	6.10	1.20	0.075	0.55 m <sup>3</sup>
Item (8)	Rebars of concrete pavement patching with 20mm thick port. --- do --- do --- etc				
	1x	3.90	0.90		3.51 m <sup>2</sup>
Item (8)	Maintenance of Manoe pipe culvert --- do --- etc				
				Qty = 0.1 nos	
Item (9)	Painting guard stones / boundary pillars --- do --- etc				
				Qty	3.71 m <sup>2</sup>
Item (10)	Maintenance of Road signs --- do --- etc				
				Qty =	0.465 km
Item (11)	Maintenance of 900M & 6m stones --- do --- etc				
				Qty =	0.465 km.

Continuation

P.T.O



Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Item (12) Cutting of branches of trees & shrubs - do - etc.					Qty = 1.00 Nos.
Item (13) Cutting of shrubs from road way - do - etc.					Qty = 31.5 Nos.
Item (14) Trimming of grass & weeds - do - do - etc.					Qty = 708.75 m <sup>2</sup>

Item (15) White washing of base - per walls - do - etc.					Qty = 21.00 m <sup>2</sup>
---	--	--	--	--	----------------------------

(Signature) Subhash  
 29/01/23  
 J.E.

Material statement

(i) Earth	—	23.247 m <sup>3</sup>
(ii) Stone	—	0.427 m <sup>3</sup>
(iii) Cement	—	4.02 kg
(iv) Bricks	—	29.583 kg

(Signature)

Continuation  
 29/01/23  
 J.E.

P.T.O





Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	Surcharge - 10%				
(I) Earth		23.247 m <sup>3</sup>			
10% of el		23 = 23/m <sup>3</sup>		Rs	55000
(II) Pot holes - 0.02 m <sup>3</sup>					
10% of el		721 = 60/m <sup>3</sup>		Rs	1200
(III) Pavers (7.33 x 2) = 14.76 m <sup>2</sup>					
10% of el		14 = 0.76/m <sup>2</sup>		Rs	21200
				Rs	77200
<p>29/01/23 J.E. Sankar</p> <p>29/01/23 AB</p> <p>ABSTRACT OF COST</p>					
(1)	Restoration of rain cuts/Berms with 50% do do do etc				
	13.28 m <sup>3</sup>	wide T m <sup>3</sup> large (37)			
	el	386 = 14/m <sup>3</sup>		Rs	5128 = 00
(2)	making up of borrow shoulder do do etc				
	38.58 m <sup>2</sup>	wide T m <sup>2</sup> large (38)			
	el	57 = 36/m <sup>2</sup>		Rs	5081 = 00
(3)	Repairs of pot holes filled with 75 mm or 30 do etc				
	0.02 m <sup>3</sup>	wide T m <sup>3</sup> large (39)			
	el	12000 = 32/m <sup>3</sup>		Rs	200 = 00
				el el	10409 = 00

Continuation

P70





Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					10409=00
(4) Patch repair over pot					
holes with mass concrete with					
lead coat - do - do - etc					
7.38 m <sup>2</sup> wide TMB Page (38)					
at 274 = 24/m <sup>2</sup> — 1, 9024=00					
(5) Patch repair over BT					
Surface with roman base					
-- do -- do -- do -- etc					
7.38 m <sup>2</sup> wide TMB Page (38)					
at 278 = 60/m <sup>2</sup> — 1, 2056=00					
(6) Patch repair over concrete					
joists - do - etc					
315.00 m wide TMB Page (38)					
at 394 = 94/m — 1, 1241=00					
(7) Repair treatment of					
isolated tiled pavements					
-- do -- do -- do -- etc					
0.55 m <sup>3</sup> wide TMB Page (39)					
at 10000 = 32/m <sup>3</sup> — 1, 5500=00					
(8) Repair of concrete					
pavement patching with					
20mm -- do -- do -- etc					
3.51 m <sup>2</sup> wide TMB Page (39)					
at 274 = 24/m <sup>2</sup> — 1, 963=00					
					22,193=00

Continuation

PTO





Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					Rs 22-193=00
(9) Maintenance of Hume pipe culvert-do etc					
1.00 nos. vide T.M.B. Page (39)					
at 1130=67/each — Rs					1131=00
(10) Painting girders & Gloms/ Brackets on pillars-do etc					
3.71 m <sup>2</sup> vide T.M.B.P. (39)					
at 16=324/m <sup>2</sup> — Rs					61=00
(11) Maintenance of Road signs -- do -- etc					
0.465 km. vide T.M.B. Page (39)					
at 1077=82/km — Rs					501=00
(12) Maintenance of room 2 km. stones -- do -- etc					
0.465 km. vide T.M.B. Page (39)					
at 627=43/km — Rs					292=00
(13) Cutting of branches of trees & shrubs -- do -- etc					
1.00 nos. vide T.M.B.P. (40)					
at 109=74/each — Rs					110=00
(13) Cutting of shrubs from roadway -- do -- etc					
315.00 nos. vide T.M.B.P. (40)					
at 6=73/each — Rs					2120=00
					Rs 26408=00

Continuation

PTD



