

# 4th Year Maintenance bill

25

Sch. XLV-Form No. 134

| Particulars                                    | Details of actual measurement |    |    |    | Contents of area |
|------------------------------------------------|-------------------------------|----|----|----|------------------|
|                                                | No.                           | L. | B. | D. |                  |
| Name of Work:- Maintenance of Road from        |                               |    |    |    |                  |
| Sankheira M.M.G.Sy Road Mandir to              |                               |    |    |    |                  |
| Paghari Brahamsthan                            |                               |    |    |    |                  |
| Name of Agency:- Shri Muktar Yadav             |                               |    |    |    |                  |
| Agreement No:- 24.SB/D/2017-18 (M.M.G.Sy S.C.) |                               |    |    |    |                  |
| Estimated Cost :- 67,85,863.00                 |                               |    |    |    |                  |
| Agreement Value :- 81,07,276.00                |                               |    |    |    |                  |
| Rate:- 10.1 below from B.O.G.                  |                               |    |    |    |                  |
| Date of Start:- 22.02.2018                     |                               |    |    |    |                  |
| Date of completion - 21.08.2018                |                               |    |    |    |                  |
| Actual date of completion:- 20.11.2018         |                               |    |    |    |                  |

| Record Measurement                     |        |        |      |        |                |
|----------------------------------------|--------|--------|------|--------|----------------|
| ① Restoration of Raincuts / Berms with |        |        |      |        |                |
| soil. noozum etc.                      |        |        |      |        |                |
| 1x                                     | 12.00x | 1.12x  | 0.35 | 4.704  | m <sup>3</sup> |
| 3x                                     | 9.00x  | 1.100x | 0.30 | 8.910  | m <sup>3</sup> |
| 2x                                     | 15.00x | 0.95x  | 0.28 | 7.980  | m <sup>3</sup> |
| 1x                                     | 8.00x  | 1.05x  | 0.35 | 2.940  | m <sup>3</sup> |
| 2x                                     | 17.00x | 1.12x  | 0.35 | 13.328 | m <sup>3</sup> |
| 1x                                     | 13.00x | 1.00x  | 0.30 | 3.900  | m <sup>3</sup> |
| 1x                                     | 7.00x  | 1.12x  | 0.35 | 2.744  | m <sup>3</sup> |
| 3x                                     | 14.00x | 1.10x  | 0.40 | 18.480 | m <sup>3</sup> |
| 2x                                     | 19.00x | 1.05x  | 0.35 | 13.965 | m <sup>3</sup> |
| 1x                                     | 10.00x | 0.95x  | 0.30 | 2.850  | m <sup>3</sup> |
| 2x                                     | 15.00x | 1.10x  | 0.35 | 11.550 | m <sup>3</sup> |
| 1x                                     | 13.00x | 1.10x  | 0.30 | 4.290  | m <sup>3</sup> |

Total Qty. = 95.641 m<sup>3</sup>

Continuation

# Abstract of Cost.

28

Sch. XLV-Form No. 134

| Particulars                                                                                              | Details of actual measurement |    |    |                            | Contents of area |
|----------------------------------------------------------------------------------------------------------|-------------------------------|----|----|----------------------------|------------------|
|                                                                                                          | No.                           | L. | B. | D.                         |                  |
| 12                                                                                                       |                               |    |    |                            |                  |
| (1/1) Restoration of Painsuts/Berms with soil maximum etc.                                               |                               |    |    |                            |                  |
| Qty. 95.641 m <sup>3</sup>                                                                               |                               |    |    | Vide T.M.B.<br>Page - 25   |                  |
| @ 345.59/m <sup>3</sup>                                                                                  |                               |    |    |                            | Rx - 33052.57    |
| (2/2) Making up of Berms/shoulder, stripping excess soil from the shoulder surface to achieve level etc. |                               |    |    |                            |                  |
| Qty. 536.47 m <sup>2</sup>                                                                               |                               |    |    | Vide T.M.B.<br>Page - 26   |                  |
| @ 50.96/m <sup>2</sup>                                                                                   |                               |    |    |                            | Rx - 27338.51    |
| (3/3) Repair of Pot holes filled with 75mm Bm.                                                           |                               |    |    |                            |                  |
| Qty. 5.89 m <sup>3</sup>                                                                                 |                               |    |    | Vide T.M.B.<br>Page - 27   | 58,189.11        |
| @ 9877.63/m <sup>3</sup>                                                                                 |                               |    |    |                            | Rx -             |
| (4/4) Patch repair over Pot holes with surface dressing.                                                 |                               |    |    |                            |                  |
| Qty. 77.546 m <sup>2</sup>                                                                               |                               |    |    | Vide T.M.B.<br>Page No. 27 |                  |
| @ 108.45/m <sup>2</sup>                                                                                  |                               |    |    |                            | Rx - 8409.86     |
| (5/5) Patch repair over bituminous surface with surface dressing.                                        |                               |    |    |                            |                  |
| Qty. 77.546 m <sup>2</sup>                                                                               |                               |    |    | Vide T.M.B.<br>Page - 27   |                  |
| @ 97.70/m <sup>2</sup>                                                                                   |                               |    |    |                            | Rx - 7576.24     |
| (6/7) Maintenance of C.D. works (H.P. Culvert)                                                           |                               |    |    |                            |                  |
| Qty. 3.50 Nos.                                                                                           |                               |    |    | Vide T.M.B.<br>Page - 27   | 3267.12          |
| @ 1089.04/each                                                                                           |                               |    |    |                            | Rx - 32.67       |
| (7/9) Maintenance of Road signs                                                                          |                               |    |    |                            |                  |
| Qty. 1.20 Km                                                                                             |                               |    |    | Vide T.M.B.<br>Page - 27   |                  |
| @ 1046.26/km                                                                                             |                               |    |    |                            | Rx - 1255.51     |

Continuation

Continuation

2/2/20  
RFB