

M.B.NO- 332

MMSY (S.C)

Schedule XLV-Form No. 13A

Executive Engineer

Rural Work Department

Work Division, Marhaura

TARAIYA

DIVISION

M/S Ma construction

Name of F. con - Abhinav Kumar Singh

SUB-DIVISION

# MEASUREMENT BOOK

Construction of Road CD Dorks From Narayanpur

Pokhri Sani Mandir To Ram Hari Singh ke Ghara

Heis Under MMSY

# 5th year Maintenance Bill

60

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Work—Maintenance of Road from Narayanpur Pokhar Shiv Mandir to Ram Narresh Singh Ke Ghar Jak.					
Name of Agency—M/s Maan Construction					
Agreement No—07/MBD/17-18					
Actual Dt of completion—10.10.2018					
Date of entry—29.09.2018					

## RECORD ENTRY

① Restoration of Rain

cuts—do—do—1/5.

$$6 \times 4.50 \times 1.25 \times 0.300 = 10.25 \text{m}^3$$

$$7 \times 6.50 \times 1.20 \times 0.300 = 16.38 \text{m}^3$$

$$8 \times 3.60 \times 1.25 \times 0.300 = 10.80 \text{m}^3$$

$$1 \times 25.00 \times 1.20 \times 0.300 = 9.00 \text{m}^3$$

$$4 \times 7.50 \times 1.25 \times 0.300 = 11.25 \text{m}^3$$

$$3 \times 8.00 \times 1.30 \times 0.300 = 9.36 \text{m}^3$$

$$6 \times 3.50 \times 1.30 \times 0.300 = 8.19 \text{m}^3$$

$$10 \times 4.60 \times 1.20 \times 0.300 = 16.56 \text{m}^3$$

$$5 \times 3.50 \times 1.150 \times 0.300 = 6.038 \text{m}^3$$

$$3 \times 8.50 \times 1.20 \times 0.300 = 9.18 \text{m}^3$$

Continuation

STW-10716003

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(5) Patch Repair over bituminous do do tiles. Same qty vt. ins. (10/11) -					177.24m <sup>2</sup> <del>166</del>
(6) Maintenance of H.C do do as per IS.					2 Nos
(7) White washing of roof do do - IS.					42.00m <sup>2</sup>
					<del>Cost</del> 99/09/22 JE

ABSTRACT OF COST

(1) Restoration of Pans Cuts - do - do - IS. 137.968m <sup>3</sup> (V.T.M.B.P. No-61) @ Rs. 380.58/m <sup>3</sup> - Rs. 52508.20
(2) Maintenance of weather shoulders - do - do - IS. 752.71m <sup>3</sup> (V.T.M.B.P. No-61). @ Rs. 58.37/m <sup>3</sup> - Rs. 43936.20
(3) Repair of Put holes filled with BM - do - do - as per IS. 13.149m <sup>3</sup> (V.T.M.B.P. No-62) @ Rs. 20043.58/m <sup>3</sup> - Rs. 263553.20

Continuation

