

5th Year Maintenance

33

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Maintenance of road from Bams ghat RBD road via Bams Dhamu Tola to Hasampur under MMSY (W.B)					
Agency- Santosh Kumar					
Agreement No- 18 SBD/2017-18					
Date of start - 10/08/2017					
Actual date of Completion - 20/04/2019					
① Restoration of Raincuts					
4	x	11.00	x 0.20	x 0.30 =	15.84m ³
1	x	8.10	x 0.90	x 0.30 =	4.37m ³
5	x	15.10	x 1.25	x 0.30 =	28.12m ³
3	x	10.50	x 1.15	x 0.25 =	9.05m ³
1	x	6.10	x 1.20	x 0.25 =	1.83m ³
4	x	12.00	x 1.25	x 0.30 =	18.00m ³
3	x	9.25	x 1.15	x 0.25 =	7.98m ³
5	x	22.00	x 1.20	x 0.30 =	39.60m ³
3	x	8.50	x 1.10	x 0.30 =	8.41m ³
2	x	7.15	x 0.80	x 0.25 =	2.86m ³
4	x	8.10	x 1.25	x 0.30 =	12.00m ³
5	x	21.00	x 1.20	x 0.30 =	36.00m ³
2	x	6.50	x 1.10	x 0.25 =	3.57m ³
6	x	25.10	x 1.15	x 0.30 =	51.75m ³
4	x	15.10	x 1.25	x 0.30 =	22.50m ³
3	x	12.50	x 1.10	x 0.25 =	10.31m ³

Continuation

272.19m³

Abstract of cost

38

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of Rain cuts					
B-VTMB P33 ① =		272.19m			
P35 ③ =		97.92m			
		370.11m			
② Maintenance of earthen shoulder					
B-VTMB P34 ② =		1412.62m			
P35 ④ =		682.45m			
		2095.07m			
③ Maintenance of bituminous surface road					
(i) Repair to pot holes 75mm B.M.					
B-VTMB P36 ⑤ i =		35.93m			
⑥ i =		9013.89m			
(ii) Repair to pot holes					
B-VTMB P36 ⑤ ii =		485.09m			
⑥ ii =		451m			
(iii) Patch repair:-					
B-VTMB P36 ⑤ iii =		485.09m			
⑥ iii =		264.70m			

Continuation

7,79,615=00

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
④ Maintenance of slabs culvert					
Q-VTHB/37④=8 Nos					
Ch-1783=46/each R-14268=0					
⑤ Cutting of branches of trees					
Q-VTHB/37⑤=9 Nos					
Ch-76=19/each R-686=0					
⑥ Cutting of shrubs					
Q-VTHB/37⑥=42 Nos					
Ch-4=67/each-R-196=0					
R-794/765=0					

20/5/24
AE

21/05/24
AE

21/05/24
AE