

217 clyd mby H 9 0321 9812 11
Shedule XLV Form No. 134.

mmbs (sc)

DIVISION


SUB-DIVISION

Measurement Book

1423

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Comments of area
	No.	L.	B.	D.	
	3rd year maintenance work				
NAME of WORK:	maintenance of road and				
	C.D. Work from Sonkarsa				
	PMGSY road to Bidara				
	material to be used				
	177655				
Agency:	S. L. Sharma Const.				
	Prab Raman Kumar				
Agreement No.	67SPD/2017-18				
Date of 3rd year maintenance work	26/03/23				
Date of 3rd year maintenance complete	25/03/24				
Date of entry					
(1)	restoration of damaged road				
	area with soil erosion				
	after E/I				
	2+24	4.85	1.125	0.30	6.55 m ²
	2+24	5.50	1.125	0.30	7.42 "
	5+	6.15	1.125	0.30	10.38 "
	2+	7.25	1.125	0.30	4.89 "
	2+24	5.90	1.125	0.30	7.96 "
					37.20 m ²
(2)	making of bearing shoulder				
	stripping the existing soil				
	from shoulder after E/I				
	2+24	8.75	1.125		39.37 m ²
	2+24	6.25	1.125		28.12 "
Continuation					67.49 m ²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.		
	2+	6.05	0.4N		4.92M ²
	2+2+	6.15	0.6N		14.7611
	2+2+	0.1N	0.6N		0.9611
					20.64M ²
					
ABSTRACT OF COST					
30/6/2018					
(1/1)	Restoration of sand/cut drains				
	with sand as per E/L				
	at site T.M.B.P. - 53(1)				
	37.20M ²	@	327.54/m ²	1	12378.00
(2/2)	M.M.S. 25-4.1 concrete shoulder				
	as per E/L				
	at site T.M.B.P. - 53(2)				
	177.19M ²	@	49.71/m ²	1	8808.00
(3/3)	Repair of pot hole at site				
	with 150mm B.M. as per				
	E/L				
	at site T.M.B.P. - 53(3)				
	2.77M ³	@	10573.43/m ³	1	29288.00
(4/4)	Patch & repair over pot hole				
	with 20mm P.M.C. with seal				
	coat type B as per E/L				
	at site T.M.B.P. - 53(4)				
	36.90M ²	@	279.29/m ²	1	10306.00

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				0.54	605811.4
(5/5) patch repair over bitumen					
on surface with 20mm					
PMC with seal coat type					
as per E/I					
at vide T.M.B.P.					
at vide T.M.B.P. 54 (5)					
36.91 m ² @ 296.68/m ²					10950.00
(6/7) maintenance of H.P. covered					
as per E/I					
at vide T.M.B.P. 55 (6)					
01 No. @ 940.23/m ²					940.23
(7/9) maintenance of road					
as per E/I					
at vide T.M.B.P. 55 (7)					
0.11 km @ 935.04/km					103.00
01 No. @ 1076.62/km					
(8/10) maintenance of 20m and					
6 m. stone as per E/I					
at vide T.M.B.P. 55 (8)					
0.13 km @ 565.49/km					74.00
(9/11.i) cutting of 20m and 6m					
as per E/I					
at vide T.M.B.P. 55 (9-i)					
02 No. @ 85.65/m ²					171.00
(ii) cutting of 20m and 6m					
as per E/I					
at vide T.M.B.P. 55 (9-ii)					

Continuation CIV-72827-0

