

$$Q_4 = 279.05 \text{ m}^3$$

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ABSTRACT OF COST</u>					
(1/1) Restoration of Raincuts / Berms with soil	do	do	do	do	
Qty = 273.05 m ³					(TMB P-18)
@ Rs 395.76/m ³					Rs 110437 = 00
(1/2) Making up of Berms/shoulders, Stripping Excess Soil	do	do	do	do	
Qty = 1244.10 m ²					(TMB P-19)
@ Rs 59.28/m ²					Rs 73750 = 00
(3/4) patch Repair over Bituminous Surface	do	do	do	do	
Qty = 120.63 m ²					(TMB P-20)
@ Rs 212.37/m ²					Rs 25631 = 00
(4/6) Maintenance of CD works flame pipe	do	do	do	do	
Qty = 06 nos					(vide TMB P-20)
@ Rs 1130.67/5					Rs 6784 = 00
(5/7) Maintenance of CD works (slab Culvert)	do	do	do	do	
Qty = 03 nos					(TMB P-20)
@ Rs 2329.20/5					Rs 6988 = 00
(6/8) Maintenance of Road Sign.	do	do	do	do	
Qty = 0.62 KM					(TMB P-20)
@ Rs 1077.82/KM					Rs 668200
(7/9) Maintenance of 200 # KM stones	do	do	do	do	
Qty = 0.74 KM					Continuation (TMB P-20)
@ Rs 570.89/KM					Rs 425 = 00

