

2nd year maintenance Bill

Abst 2nd of 43 Cost

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work — maint. of Rd from					
M. G. S. P. 004 Sotkatito					
Narain Nagar					
Agency — Nikath Kumar					
Agreement No — 206 SBD/2021-22					
Date of Start — 25/05/2021					
Date of Completion — 24/02/2022					
Actual Date of Completion — 26/05/2022					
①					
1 Restoration of Paving					
Bene / with Soil moorum					
— Do — FI —					
32.68 m ³ OUT MBP — (32) 0					
②					
2 making of Bene shoulder					
Stirring ends 1st					
— Do — FI —					
182.22 m ² OUT MBP — (40)					
③					
3 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					
④					
4 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					
⑤					
5 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					
⑥					
6 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					
⑦					
7 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					
⑧					
8 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					
⑨					
9 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					
⑩					
10 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					
⑪					
11 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					
⑫					
12 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					
⑬					
13 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					
⑭					
14 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					
⑮					
15 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					
⑯					
16 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					
⑰					
17 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					
⑱					
18 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					
⑲					
19 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					
⑳					
20 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					
㉑					
21 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					
㉒					
22 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					
㉓					
23 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					
㉔					
24 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					
㉕					
25 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					
㉖					
26 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					
㉗					
27 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					
㉘					
28 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					
㉙					
29 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					
㉚					
30 patch repair over					
bituminous surface					
with 20 mm mix surf					
— Do — FI —					
25.30 m ² OUT MBP — (40)					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(4) 6 maintenance of (1 turnse pipe curval) C/D work — — RO — FI —					
2.00 Nos OUT MBP- (40)					
@ PS- 1166.58 Each PS- 2333.00					
(5) 8 maintenance of Road Sign — RO — FI —					
0.06 Km @ UT MBP- (45)					
@ PS- 1104.14 / Km PS- 66.00					
(6) 9 maintenance of 200m and km Stone post — RO — FI —					
0.08 Km @ UT MBP- (41)					
@ PS- 582.83 / Km PS- 47.00					
(7) 10(i) cutting of 162 arsh of tree and shrubs — RO — FI —					
2.00 Nos @ UT MBP- (41)					
@ PS- 113.64 Each PS- 227.00					
(8) 10(ii) cutting of shrubs from Roadway — RO — FI —					
6.00 @ UT MBP- (47)					
@ PS- 6.98 Each PS- 42.00					

C.O. PS- 32320.00

Continuation

B. F. RS - 32320.00

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑨ 10 (iii) Trimming of grass and weeds — DO — FI —					
3.15 m ² OUT M.B.P. ⑪					
@ RS - 2.33 / m ² RS -					7.00
⑩ 11 white washing of porcelain walls of CD crock and tap handles — DO — FI —					
41.99 m ² OUT M.B.P. ⑫					
@ RS - 16.87 / m ² RS -					708.00
				RS -	33035.00
ADD G.S.T @ 12% ⑬				RS -	3964.00

ADD L.CES @ 1% ⑭	RS -	330.00
	RS -	37329.00
Less For 0.11% Below as		
Per Agreement ⑮	(-) RS -	41.00
	payable RS -	37288.00

⑭
25/5/24
JE

Copy
13/8/24
00