

MB-No - 1073

Schedule XLV-Form No. 134

R.W.D. Platelayer
Division

R.W.D. Michigan Sub-Division

MMSY-CEN

MEASUREMENT BOOK

Shri. Kumar Ashok

33
Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
VIT M.D. P.Ho	(31)				
120 N (3) - 52.45 m ²					
as 315.99/m ² — 167.32 =					
4/153(iii) Pothole repair over					
bituminous surface					
VIT M.D. P.Ho	(32)				
120 N (3) - 52.88 m ²					
as 341.38/m ² — 180.51 =					
5/18.7 (ii) Maintenance of Sub base					
With M.D. P.Ho	(33)				
as 1831.44/m ² — 1831.50 =					
13/06/19 Singh (1831.55) + 1000 G 88124 = 13/06/19 Singh (1831.55) - 1000 G 485 = AC 87639 =					

Fifth Year Maintenance work					
Type of Road - Type of Pothole - End of Strength					
PMCSY P.Ho to Shimla pure road					
Item ① After P.Ho A.K.P.A. Ashok Restoration of Ramps / Banks					
With soil Monsoon					
10 X 3.15 X 1.20 X 0.300 = 11.34 m ²					
9 X 2.65 X 1.10 X 0.280 = 6.55 m ²					
10 X 2.95 X 0.95 X 0.300 = 8.40 m ²					
8 X 3.65 X 1.15 X 0.300 = 10.07 m ²					
11 X 4.25 X 1.15 X 0.250 = 13.44 m ²					
12 X 5.10 X 1.20 X 0.300 = 22.03 m ²					
10 X 3.25 X 1.15 X 0.280 = 9.34 m ²					
12 X 3.10 X 1.25 X 0.280 = 11.62 m ²					
10 X 2.40 X 1.10 X 0.200 = 5.28 m ²					
					98.07

Continuation