

2nd year maintenance B/L

30

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/w: Anandakorpur P. Chanderho					
Rai Shekhar J. to Thathi					
Back of Shekhar Mahadad					
Adm.					
Agency: M/S Shanti Construction.					
Agg No. 15/MBD/2000-21					
D.O.S. 12/05/2000					
D.O.C. 17/05/2001					
Adm.					
② Refinement of Ram work.					
2x 5m x 10m x 0.80 x 0.30					28.80 m ³
2x 3m x 15m x 0.80 x 0.40					30.60 m ³
1x 10m x 0.90 x 0.80					8.60 m ³
2x 3m x 6.50m x 0.90 x 0.45					16.57 m ³
					Qty 84.57 m ³
					63.00 m ³
② Making up of beam					
Shoulder					
2x 9m x 22m x 0.75					297.00 m ³
2x 8m x 25m x 0.65					260.00 m ³
2x 17m x 10m x 0.75					255.00 m ³
1x 19m x 0.85					16.15 m ³
					Qty 678.15 m ³
(3) Patch repair over bitu					
minors surface with 20mm					
Mix 200/200mm type					

Continuation

Continuation