

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3rd Year Maint Bill					
Name - Maint of Road from					
Chora Malba of Gram					
Panchayat Barah to					
Barah Prirahan Mistry					
Road in Harman Block					
Agency - Rajkish Kumar					
Singh.					
Ag. value - 60800/2018-19					
Date of Actual Completion					
10/11/2019					
Date of entry - 30/11/22					
Measurement					
(1) Restoration of Road					
Est - do - do per					
L.H.S - $3 \times 30 \times 1.125 \times 0.30 = 30.38 \text{ m}^3$					
R.H.S - $3 \times 30 \times 1.125 \times 0.90 = 90.28 \text{ m}^3$					
P.H.S - $2 \times 30 \times 1.125 \times 0.20 = 13.50 \text{ m}^3$					
L.H.S - $9 \text{ m} \times 0.90 \text{ m} \times 0.15 = 1.22 \text{ m}^3$					
$= 75.48 \text{ m}^3$					
(2) Making up Berms					
Shoulder - do - per					
L.H.S - $6 \times 30 \times 1.125 = 202.50 \text{ m}^2$					
R.H.S - $6 \times 30 \times 1.125 = 202.50 \text{ m}^2$					
P.H.S - $15 \text{ m} \times 1.00 \text{ m} = 15.00 \text{ m}^2$					
$= 420.00 \text{ m}^2$					
(P.T.O)					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
③ Repair of Pot-holes					
with 75 mm gpm					
do do					
12 m x 0.90 x 0.075 = 0.81 m ³					
19 m x 0.75 x 0.075 = 1.07 m ³					
1 x 6.00 x 3.75 x 0.075 = 1.69 m ³					
18 x 0.90 x 0.90 x 0.075 = 1.09 m ³					
14 x 0.60 x 0.60 x 0.075 = 0.38 m ³					
					= 5.04 m ³
④ Patch repair over					
Pot-holes - do do					
do do					
Area = 5.04 / 0.075					
					= 67.20 m ²
⑤ Patch repair over					
bituminous surface					
do do					
Qty same as					
above Area					
of item ④ = 67.20 m ²					
⑥ Maint. of C.D.					
do do					
1 x 2 = 2 Nos					
⑦ Maint. of roads - culvert					
do do					
Qty = 1 x 1 = 1 No					
(P-7.0)					

Continuation

Scanned with CamScanner

Scanned with CamScanner

Scanned with CamScanner

20/11/22
J.E