

2nd year maintenance

51

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/w: Maint. of Road from Toz					
Munneshebari mahato keghar					
to Khanpur Dakshin Mahato Talo.					
Agency-	Md. Samir Alam				
Aggr. No.	55(SRD) / 2021-22				
D.O.W.	12.08.2024				
Actual D.O.C.	05.08.2022				

① Restoration of Reinforcement -

R.H.S	10x	3.50x	0.95x	0.35 =	11.64
	8x	4.00x	0.70x	0.35 =	7.84
	15x	2.50x	0.90x	0.30 =	10.12
	9x	3.00x	0.85x	0.35 =	8.03
	12x	2.65x	0.90x	0.30 =	8.59
L.H.S	11x	3.55x	0.80x	0.35 =	10.93
	8x	2.00x	0.75x	0.30 =	3.60
	7x	4.15x	0.95x	0.25 =	9.66
					70.41 m ³

② Making up of Beams -

R.H.S	4x	7.50x	0.80	—	24.00
	8x	6.00x	0.75	—	36.00
	10x	8.00x	0.90	—	72.00
	12x	5.50x	0.85	—	56.10
	9x	8.50x	0.80	—	61.20
L.H.S	15x	6.55x	0.90	—	88.42
	17x	7.25x	0.75	—	92.44

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(5) Maint. of slab culvert -					
Qty wide THB R (52)					
2.00 nos	2394.96	/	cm		R 4790 =
					R 74686 =
Acyl Cost + L.C.W. 13%.					R 9709 =
Acyl S. Fee					R 553 =
					R 84948 =
Qty Below 15.79 %.					R 13413 =
					R 71535 =

Material

Qty - 138.71 m³

Slabs - 1.456 m³

Bricks - 0.115 MT

R.L. - 0.016 MT

06/08/24
JE