

Q/w - 35.93 m³

S/chips - 0.759 m³

Bhomen - 0.060 MT

Res - 0.008 MT

~~Res~~
55/5-22
08

3rd year maintenance

W/w - Maint. of Road from 1060

Dhotgame Culam toke huc REO

Road Rai tole chowk tole

Agency - Riskikesh Rongpa

Agg. No. 19 (SBS) / 2020-21

D.O.W -

Actual D.O.C - 30.04.2021

Date of entry -

① Restoration of Rain Cuck -

$$12 \times 2.65 \times 0.80 \times 0.35 = 8.90$$

$$10 \times 3.60 \times 0.95 \times 0.30 = 9.97$$

$$17 \times 2.50 \times 0.75 \times 0.30 = 9.56$$

$$12 \times 2.25 \times 0.90 \times 0.30 = 7.29$$

$$18 \times 2.60 \times 0.85 \times 0.35 = 13.92$$

Continuation

49.64 m³

2042

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑤ Patch repair on RT Surface -					
Qty with THB R (39)					
41.57 m ² @ R 257.10/m ² - R. 10688 =					
⑥ Main. of Road Sign -					
Qty with THB R (39)					
0.11 Km @ R 1077.82/Km - R. 119 =					
⑦ Proc. of Laying Road marking -					
Qty with THB R (40)					
145.10 m ² @ R 735.44/m ² - R. 106639 =					
⑧ Main. of already planted trees -					
Qty with THB R (40)					
40.10 m ² @ R 574.10/each - R. 22960 =					
R. 195926 =					

Area Asst + L. cost 134. GRs 25470 =

Area S. Fee - GR. 656 =

R. 222052 =

Less Below 0.25% (-) R. 555 =

R. 221497 =

80/4.34
80/08

Matr

Qty - 80.01 m³

S/meter. 3.783 m³