

Sch. XLV—Form No. 134

| Sch. XLV—Form No. 134                |                               |    |    |    | Contents of area |
|--------------------------------------|-------------------------------|----|----|----|------------------|
| Particulars                          | Details of actual measurement |    |    |    |                  |
|                                      | No.                           | L. | B. | D. |                  |
| <u>2nd year Maintenance Bill</u>     |                               |    |    |    |                  |
| <u>Name of work:— Maintenance of</u> |                               |    |    |    |                  |
| <u>Road from Manghauri Kuzam</u>     |                               |    |    |    |                  |
| <u>Khan dola to Basa dola under</u>  |                               |    |    |    |                  |
| <u>MCCSY (BRICKS)</u>                |                               |    |    |    |                  |

Agency — Rajeev Kumar

Agreement No. — 15SPD/2020-2021

dt 10/8/2020

Duration period of 1st year Maint.:

25/5/2021 to 24/5/2022

25/5/2021

In Restoration of rain cuts

with soil maximum

and technical

specification clause 1002

|     |    |      |      |                     |
|-----|----|------|------|---------------------|
| 2x2 | 30 | 0.90 | 0.30 | 32.40m <sup>3</sup> |
| 1   | 26 | 1.0  | 0.30 | 7.80m <sup>3</sup>  |
| 1x2 | 19 | 1.0  | 0.30 | 11.40m <sup>3</sup> |
| 1   | 14 | 0.90 | 0.30 | 3.78m <sup>3</sup>  |
| 1   | 19 | 0.90 | 0.30 | 5.13m <sup>3</sup>  |
|     |    |      |      | 60.51m <sup>3</sup> |

2. Maintenance of earthen

shoulders filling with

fresh selected soil

as per technical

specification clause 1002.

|     |    |     |    |                     |
|-----|----|-----|----|---------------------|
| 2x2 | 26 | 0.9 | 0. | 93.60m <sup>3</sup> |
|-----|----|-----|----|---------------------|

| Particulars                              | Details of actual measurement |    |    |     | Contents of area |
|------------------------------------------|-------------------------------|----|----|-----|------------------|
|                                          | No.                           | L. | B. | D.  |                  |
| ① Restoration of ram cuts                |                               |    |    |     |                  |
|                                          |                               |    |    | do. | all area         |
| 72.90 m <sup>2</sup> Qty Page (35) 2hr ① |                               |    |    |     |                  |
| ② 371259/m                               |                               |    |    | R.  | 2767220          |
| ② making up bon/sma <sup>2</sup> ship    |                               |    |    |     |                  |
|                                          |                               |    |    | do. | all area         |
| 40500 m <sup>2</sup> Qty Page (35) 2hr ② |                               |    |    |     |                  |
| ③ 57.01/m <sup>2</sup>                   |                               |    |    | R.  | 2308920          |
| ③ Pot repair over bituminous surface     |                               |    |    |     |                  |
|                                          |                               |    |    | do. | all area         |
| 22.44 m <sup>2</sup> Qty Page (37) 2hr ③ |                               |    |    |     |                  |

④ 244.49/m<sup>2</sup> — R. 5773020

④ Maint of CD work — do — all  
01 Nos Qty Page (39) 2hr ④

④ 2273447/m<sup>2</sup> R. 2273200

⑤ cutting of branches of tree

03 Nos Qty Page (41) 2hr ⑤

④ 106.12/cut — R. 318200

⑥ Maint of already planted tree

02 Nos Qty Page (34) 2hr ⑥

④ 655200/cut — R. 1572020

C&P

YR 6/1/11  
23/3/24

Continuation

add 1 1/2 LRS

7480220

897620

748200

8452620

8455200

7607320

all less below 10%  
5/8/12  
JE