

4th Year Maintenance Bill

81

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Work - Maintenance of Road					
From NH 30A Bhuaipur Road					
Bhairuapatti via Chakjodiar,					
Mukundipur					
Agency Mahendra Kumar Sinha.					
Agr. No. 77-SBD/2018-19					
Actual date of completion - 28/05/2020					
RECORD ENTRY					
① Restoration of rain cuts					
-----20-----20-----41					
	78x	0.75x	1.20x	0.30	21.060 m ³
	64x	0.90x	1.20x	0.30	20.736 m ³
	56x	1.05x	1.20x	0.30	21.168 m ³
	48x	1.15x	1.20x	0.30	19.872 m ³
	52x	1.25x	1.20x	0.30	23.400 m ³
	24x	1.45x	1.20x	0.30	12.528 m ³
	36x	1.75x	1.20x	0.30	12.680 m ³
	14x	1.90x	1.20x	0.30	9.576 m ³
	16x	2.25x	1.15x	0.30	12.420 m ³
	10x	2.65x	1.15x	0.30	9.143 m ³
	12x	3.45x	1.10x	0.30	13.662 m ³
					186.245 m ³
② Maintenance of gutter shoulder					
-----20-----20-----41					
	2x	18x	3.40x	1.20	146.88 m ²
	2x	14x	5.60x	1.20	188.16 m ²
	2x	16x	5.90x	1.20	226.56 m ²
	2x	13x	7.25x	1.20	226.20 m ²
					787.80 m ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
B.F.					787.80m ²
2x	8x	9.40x	1.20		202.04m ²
2x	2x	11.60x	1.20		55.68m ²
					1046.52m ²
					1035.00m ²

③ Repair to Pot holes

.....20.....	20.....	E ₁			
48x	0.60x	0.50x	0.075		1.080m ³
56x	0.75x	0.60x	0.075		1.890m ³
36x	0.90x	0.75x	0.075		1.823m ³
24x	0.90x	0.90x	0.075		1.458m ³
16x	1.15x	0.95x	0.075		1.311m ³
12x	1.25x	1.05x	0.075		1.181m ³
6x	1.45x	1.15x	0.075		0.750m ³
4x	2.15x	1.35x	0.075		0.871m ³
1x	2.48x	1.00x	0.075		0.186m ³
					10.550m ³

④ Patch repair over Pot holes

.....20.....	20.....	E ₁			
48x	0.60x	0.50			1440m ²
56x	0.75x	0.60			2520m ²
36x	0.90x	0.75			2430m ²
24x	0.90x	0.90			1944m ²
16x	1.15x	0.95			1748m ²
12x	1.25x	1.05			1575m ²
6x	1.45x	1.15			1000m ²
4x	2.15x	1.35			1161m ²
1x	2.48x	1.00			248m ²
					14066m ²

Continuation
Total = 140.63m²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑤ Patch repair over B.T. Surface					
.....20.....20.....62					
Qty. Same as T488-82					
Item No - 04					
140.63 m ²					140.63 m ²
⑥ Maintenance of S.P. Culvert					
.....20.....20.....62					
2.00 No					2.00 No
⑦ Maintenance of Road Sign					
.....20.....20.....62					
2.30 K.M.					2.30 K.M.
⑧ Maintenance of K.P. & M. Stone					
.....20.....20.....62					
2.30 K.M.					2.30 K.M.
⑨ Cutting of branches of Trees					
.....20.....20.....62					
3.00 No					3.00 No
⑩ White washing on Parapet walls					
.....20.....20.....62					
2 x 6.15 x 0.60					29.52 m ²
2 x 2 x 6.15 x 0.40					9.84 m ²
2 x 4 x 0.40 x 0.60					1.92 m ²
					41.28 m ²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ABSTRACT OF COST</u>					
① Restoration of rain cuts					
.....20.....20.....E ₁					
186.245 m ² VTMBP-81					
@ Rs 354.81/m ²					Rs 66082.00
② Maintenance of earthen shoulder					
.....20.....20.....E ₁					
1035.00 m ² VTMBP-81					
@ Rs 514.57/m ²					Rs 53561.00
③ Repair of Pot holes					
.....20.....20.....E ₁					
10.55 m ² VTMBP-82					
@ Rs 9425.48/m ²					Rs 99439.00
④ Patch repair over Pot holes					
.....20.....20.....E ₁					
140.63 m ² VTMBP-82					
@ Rs 193.45/m ²					Rs 27205.00
⑤ Maintenance of H.A. culvert					
.....20.....20.....E ₁					
2.00 NO VTMBP-82					
@ Rs 1122.29/NO					Rs 2245.00
⑥ Maintenance of Road sign					
.....20.....20.....E ₁					
2.30 KM VTMBP-83					
@ Rs 1048.63/KM					Rs 2412.00
⑦ Maintenance of K.M. + H. stone					
.....20.....20.....E ₁					
					Rs 25103.00

Continuation

Scanned with CamScanner