

PMGSY-SC (Maint.)

PM.B.NO-3463

Schedule XLV-Form No. 134

मानक तौर पर निर्माण के आधार पर निर्माण के लिए निर्माण के लिए
नकल

प्रकार/मात्रा/सं- 43/5BD/2020-21

DIVISION

धर्म: श्री विनोद सिंह

श्री विनोद सिंह/सं- 43/5BD/2020-21 SUB-DIVISION

जगदीश

MEASUREMENT BOOK

PM.B.NO-3463

3rd year Maintenance


Roll
Roll No.
Roll No.

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/w:	M/o Road from Manpur				
	Tinnahenire via chennar ke				
	Ghar se Ramnagar kachhupok.				
Agency:	Si Ritesh Rayan.				
Agmt No:	43/SBD/2020-21				
D.O.C (act):	03/08/2021				
<u>Second entry:</u>					
① Restoration of stained---					
	14	2.05	0.625	0.30	5.38
	12	2.30	0.625	0.30	5.175
	9	2.40	0.625	0.30	4.05
	16	2.15	0.625	0.30	6.45
	12	2.05	0.625	0.30	4.61
	11	2.25	0.625	0.30	4.64
	10	1.75	0.625	0.30	3.28
	16	2.00	0.625	0.30	6.00
	12	2.30	0.625	0.30	5.175
	T. Qty =				44.76m ³
② Making up of Barms---					
	12	3.75	1.125		50.62m ²
	10	2.65	1.125		29.81
	9	3.25	1.125		32.91
	6	2.05	1.125		13.84
	15	3.00	1.125		50.625
	10	2.55	1.125		28.69
	T. Qty =				206.49m ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
③ Patch deep in over					
Repair of Pole 75mm -					
$1 \times 2.75 \times 0.40 \times 0.075 =$					0.08
$4 \times 2.00 \times 0.85 \times 0.075 =$					0.51
$6 \times 1.75 \times 0.75 \times 0.075 =$					0.59
$4 \times 1.25 \times 0.50 \times 0.075 =$					0.19
$3 \times 1.50 \times 0.65 \times 0.075 =$					0.22
$5 \times 0.75 \times 0.80 \times 0.075 =$					0.17
				T. Qty =	1.76 m ³
				Tested to	1.73 m ³
④ Patch deep in over					
$7 \times 0.65 \times 0.50 =$					2.275
$6 \times 0.75 \times 0.60 =$					2.70
$11 \times 1.15 \times 0.75 =$					9.49
$10 \times 1.00 \times 1.00 =$					10.00
$7 \times 1.25 \times 1.00 =$					8.75
$6 \times 0.90 \times 0.90 =$					4.86
				T. Qty =	38.07 m ²
⑤ Patch deep in over					
T. Qty same as ④ =					38.07 m ²
⑥ Maintenance of CD work.					
$1 \times 1.00 =$					1.00
				T. Qty =	1.00 NO

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑦ Maintenance of dead tree					
	1	1.02			1.02 km
				T. Qty = 1.02	
⑧ Maintenance of young tree					
	1	0.18			0.18 km
				T. Qty = 0.18 km	
⑨ Cutting of branch					
	1	2.10			2.10 NO
⑩ Cutting of shrubs					
	1	9.10			9.10
⑪ Trimming of grass/land					
	1	2.75	0.75		2.06
	1	2.10	0.10		1.25
				T. Qty = 3.31 m ²	
⑫ Maintenance of tree					
	82	1.10			82.10 x
 3/8/24 JC  3/8/24 K.K.					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Abstract of cost:</u>					
① Restoration of drain cut -					
TMB/ P-13	44.76	@	386.14	=	17284=00
② Making up of Berms - -					
TMB/ P-13	206.49	@	57.36	=	11844=00
③ Repair of Poles with w.p.N - -					
TMB/ P-14	1.73	@	12259.6	=	21208=00
④ Patch repair over poles - -					
TMB/P-14	38.07	@	338.78	=	12897=00
⑤ Patch repair over bitum - -					
TMB/P-14	38.07	@	351.90	=	13397=00
⑥ Maintenance of CD work					
TMB/p-14	1.00	@	2329.90	=	2330=00
⑦ Maintenance of road way					
TMB/p-15	1.02	@	1077.82	=	1099=00
⑧ Maintenance of drains - -					
TMB/p-15	0.18	@	628.24	=	115=00
⑨ cutting of Branch - -					
TMB/p-15	2.00	@	109.74	=	219=00
⑩ cutting of shoulders - -					
TMB/p-15	9.00	@	6.73	=	61=00
⑪ Trimming of grass - -					
TMB/p-15	3.31	@	2.24	=	7=00
⑫ Maintenance of lane					
TMB/p-15	82.00	@	674.37	=	55298=00
Total Rs.					1,35,759=00
OP-17					

B/A-14/135759=0

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Total	18:				135759=0
Less 10.96% below (-)					14879=0
(A) ←					120880=0
add 1% h.c on (A) (+)					1209=0
add 12% h.s.T on (A) (+)					14506=0
Total	18:				136595=0
					ctf
					03/08/14
					EE

Material statement:-

① Earth = 76.00 m³

② Stone aggregate = 0.85 m³

③ Stone dust = 0.15 m³

④ Stone chips = 2.08 m³

⑤ Emulsion PSI = 0.01 MT

⑥ " " SSI = 0.01 MT

⑦ Bitumen S90 = 0.1644 MT

03/08/14
EE