

Dimra Dhansei Path Dimra to Sarai Talq Fin

Schedule XLV Form No. 134. mmusy/sc)

P10070880

Bikramganj DIVISION

Dimra SUB-DIVISION

Measurement Book

No: 552

पञ्च दिना ३५१३२१११

1st year Maintenance

60

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
H/W Dinara-Dhansoi Path					
Dinara To Sarai Tola					
Agency - Gauri Shankar Upadhyay					
Agreement No - 31/SBD/20-21					
Actual Completion date					10.7.2
① Restoration of main cut					
2 x 2.9 x 1.1 x .30					1.91
5 x 2.1 x 1.0 x .30					3.15
3 x 3.1 x .90 x .30					2.51
2 x 1.8 x 1.12 x .30					1.21
6 x 1.4 x 1.1M x .30					2.72
1 x 10 x 1.12 x .30					3.36

5 x 1.7 x 1.0 x .30	2.55
4 x 2.1 x 1.1 x .30	2.72
2 x 1.9 x .90 x .30	1.02
1 x 5M x 1.1 x .30	1.65
3 x 1.9 x 1.0 x .30	1.71
2 x 2.1 x .90 x .30	1.13
2 x 2.2 x .80 x .30	1.05
5 x 1.6 x 1M x .30	2.40
2 x 1.9 x 1.1M x .30	1.25
1 x 5M x 1.12 x .30	1.68
4 x 2.1 x 1.0 x .30	2.52
3 x 5M x 1.1 x .30	4.95
2 x 5M x 1.12 x .30	3.36
4 x 4.2 x 1.0 x .30	5.04

Total = 48

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(4) Maintenance of CD					
		P-	62/2		
3 NOS @	1130.67	/cm			3392
(5) Maintenance of Sign					
		P-	62/3		
0.12 km @	1077.82	/km			As per DP 127
(6) Maintenance of 200m					
		P-	62/4		
0.14 km @	570.89	/km			80
(7) Cutting of branches tree and Shrub					
		P-	62/5		
2 NOS @	109.74	/cm			219
(8) Cutting of Shrub					
		P-	62/6		
10 NOS @	6.73	/cm			67
				Total	48,001
Add GST 12%					5760
Add L-c 1%					480
				Total	54244
Add 10% S.F.:-					
Restoration 46MB @ 24075/m					119
Shrub 331.76 @ 4.93/m					164
Patching 22.20m @ 4.94/m					33.00
				Total	54560
Levy 19.21% @ 568/m					10480
				Total	44080
				Total	44080
				Total	44080

Continuation