

52

M.M.G.S.Y (S.C)

Schedule XLV From No. 134.

MB No. 237
2018-19

DIVISION

पिपरा ३ ३३ २५

SUB-DIVISION

पु. वि. वि. वि. वि. वि.

Mahendra Kumar.

Measurement Book

पु. वि. वि. वि. वि. वि.

MB No. 237
2018-19

પ્રમાણિત બેઠા બાદ છે કે ૪૫
જાણી કુલ ૪૦ મલીન રાખ
ગોમત કુલ ૧૦૦ (મી) પાક છે
પેલે ૫૬ મી જામિયેટા જાલ
મહામત જામિયેટા નો મીટ
બેઠા બાદ છે


4/05/18
E.E
Amul
24/05/18

Sch. XLV-Form No. 134

DIVISION

SUB-DIVISION

Measurement Book

No. 277

Name of officer _____

Name of work -

Situation of work -

Agency by which work is executed -

Date of measurement -

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work -					
const. of road					
from Sidura to Tulla.					
Name of Agency -					
Sri Mahendra Kumar.					
Date of Agreement -					
Agreement No. -					
0358D/2018-19					
Date of start of work -					
12-12-17					
04.04.2018					
Date of completion -					
11.12.2018					

Record measurement -

Dated -

1. Setting out pillars

0.875 Km²

2. E/W calculation

Sl. No.	chain- age	Fill Area	mean Area	Dist- ance	Fill volume
1.	0	0.634			
2.	50	1.241	0.938	50	46.875
3.	100	1.685	1.463	50	73.150
4.	150	1.755	1.720	50	86.000
5.	200	1.746	1.751	50	87.525
6.	250	1.652	1.699	50	84.950
7.	300	2.631	2.142	50	107.075
8.	350	1.625	2.128	50	106.400

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ABSTRACT					
① Rectification of Rain cut with soil — all 70m					
Qty vide TMB PN-49					
27.52 m ³ @ 358 = 02/m ³ F 9853 = 0					
② Making up to 8m & double					
all 70m					
Qty vide TMB PN-49					
152.77 m ² @ F 59 = 24 F 9058 = 0					
③ Repair of pot hole with					
75mm WBS — all 70					
Qty vide TMB PN-50					
2.448 m ³ @ F 395 = 70/m ³ F 969 = 0					
④ Path Repair over pot hole with surface dressing — all 70					
Qty vide TMB PN-50					
61.77 m ² @ F 168 = 65/m ² F 10418 = 0					
⑤ Maint of Road sign — all 70					
Qty vide TMB PN-50					
0.13 km @ F 1030 = 54/km F 134 = 0					
⑥ Maint of 200mm & 150mm — all 70					
Qty vide TMB PN-50					
0.160 km @ F 645 = 47/km F 102 = 0					
					F 30534 = 0
less 1.54% below					F 470 = 0
					F 30064 = 0

Continuation

20/01/24
A/S
c/p
San 12/08/24
PR

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ABSTRACT					
① Repairing of Rain Coat					
with roof					
Qty vide	Tim B	PM. - 53			
28.62 m ² @ Rs 358.20/m ²					Rs 10247.00
② Making berm & shoulder					
Qty vide	Tim B	PM. - 53			
168.32 m ² @ Rs 59.29/m ²					Rs 9980.00
③ Repair of pot hole with					
75 mm 14 B M					
all 70.					
Qty vide	Tim B	PM. - 53			
3.135 m ² @ Rs 395.70/m ²					Rs 1240.00
④ Patch Repair over pot					
hole with two coat					
surface dressing					
all 70.					
Qty vide	Tim B	PM. - 54			
84.61 m ² @ Rs 168.65/m ²					Rs 14269.00
⑤ Maint. of Road sign					
Qty vide	Tim B	PM. - 54			
0.13 km @ Rs 1020.54/km					Rs 134.00
⑥ Maint of 200m x 1km of					
Qty vide	Tim B	PM. - 54			
0.24 km @ Rs 645.47/km					Rs 154.00
12% 1.54 % below					Rs 354.00
					Rs 354.52.00

Continuation

14/06/24
7/10/24
A.P.
CLP Sanj 22/08/24
26