

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
300 Yr maintenance					
Excessed m... maintenance of					
Lead from Chandualli to ^{Chauk} 9.70					
Chandualli to Chauk (Kushwaha - Jola)					
Any - Bannaya Construction Pvt. Ltd					
Andree - 848701/2020-21					
Dated 8-9-2021					
Dated 10/9/2024					
① Restoration of fence					
cuts using all comp/blebs					
10 x 15m x .90 x .30 =					40.50
10 x 15m x .75 x .30 =					47.25
1 x 15m x .60 x .30 =					2.70
					90.45 m ³
					lim 90.29 m ³
2. making up of Berms					
Shulds using all comp/blebs					
10 x 15m x 2.7 x .90 =					270. m ²
9 x 15m x 2 x .75 =					202.50
					472.50 m ²
					lim 465.81 m ²
3. Repair of pot holes					
3. filled using 75 mm B.M.					
using all					
8 x 4m x 2m x .075 =					4.80 m ³
6 x 3m x 1.50 x .075 =					2.025
					6.825 m ³

Continuation

lim 6.72 m³

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				22/3	157402 =
$\frac{6}{12}$ Gt of measured					
Planted trees					
Quail for greenable					11
on (6) 51 m					
@ 574.05/eh					29277 =
$\frac{7}{15}$ Gt of Road marking					
with all components					
Quail for greenable					11
on (7) 254.80 m					
@ 738.44/h2					187390
					374069

Add 128 Gt TP / 7h 48629 =

less 10 1.60 m 422698 =

42270 =

1330428 =

10/9/24

or