

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
4th year Maintenance					
Name of work — Maintenance					
of road from PMGSY Ladang,					
ke Sirawan more to Nathu					
bigha Under mmGSY (SU)					
Agency — m/s Singh Constn					
Agreement no. — 8850					2018-19
Actual Date of Completion —					
					05/08/2019
Date of Entry —					12/01/24

① Restoration of raincut
with soil

$2 \times 4 \times 30.4m \times 0.90m \times 0.30m$	$= 64.80m^3$
$2 \times 8.50m \times 1.8m \times 0.30m$	$= 2.70m^3$
$2 \times 30.4m \times 0.80m \times 0.30m$	$= 14.40m^3$
$2 \times 9.4m \times 0.95m \times 0.30m$	$= 5.13m^3$
$2 \times 2.10m \times 0.80m \times 0.30m$	$= 1.00m^3$
	$90.43m^3$

② Making up of Berm
Shoulder

$2 \times 4 \times 30.4m \times 1.0m$	$= 240.4m^2$
$2 \times 4 \times 30.4m \times 0.75m$	$= 180.4m^2$
$2 \times (30 + 17.0) \times 0.90$	$= 84.60m^2$
	$504.60m^2$

③ Repair of pot holes
filled with Br.

$19.60m \times 1.70m \times 0.075m$	$= 2.50m^3$
-------------------------------------	-------------

[illegible]

12/01/2024
At Homeballpur

Material & Statement

- (1) Soil — 166.12 m^3
- (2) Screening — 1.25 m^3
- (3) Stone metal — 7.22 m^3
- (4) Chnps — 10.51 m^3
- (5) Rs, — 0.044 m^3
- (6) Bit — 0.879 m^3

12/01/24
AE