

Sch. XLV-Form No. 134

58

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1) <u>Main. of road from Lakhmanta Derauli</u>					
Agency - Sri Mukund Singh					
Ay. No - 62800 / MMA/4/2017-2020					
Actual completion - 03/10/2020					
<u>Revised Slab</u>					
(a) <u>Revolutions of chain</u>					
culs → 05 →					
$8 \times 5.80 \times 9.00 \times 0.80 = 27.84$					
$6 \times 9.20 \times 8.10 \times 0.80 = 34.78$					
$10 \times 6.20 \times 1.80 \times 0.80 = 22.22$					
$4 \times 8.75 \times 0.95 \times 0.80 = 3.71$					
					88.65
) <u>Main. of Corkhara</u>					
Shoulder → 00 →					
$5 \times 7.00 \times 9.00 = 81.00$					
$4 \times 6.80 \times 2.20 = 59.84$					
$8 \times 5.20 \times 8.10 = 87.86$					
$5 \times 6.85 \times 2.00 = 68.50$					
$4 \times 8.45 \times 1.95 = 27.95$					
					823.95

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Absence of cost</u>					
① Restoration of train					
area — 00 —					
88.65 m <sup>2</sup> — wide — P- 58					
@ Rs 380.58/m <sup>2</sup> — L					Rs 33738.00
② Maint. of Gutter					
Shoulder — 00 —					
823.95 m <sup>2</sup> — wide — P- 58					
@ Rs 58.60/m <sup>2</sup> — L					Rs 47888.00
③ Maint. of Bituminous					
Surface — 00 —					
area — 00 —					
823.96 m <sup>2</sup> — wide — P- 58					
@ Rs 200.96/m <sup>2</sup> — L					Rs 178178.00
④ Maint. of 028m					
— 00 —					
67.40 m <sup>2</sup> — wide — P- 59					
@ Rs 415.65/m <sup>2</sup> — L					Rs 28015.00
⑤ Patch repair on already					
filled potholes — 00 —					
67.40 m <sup>2</sup> — wide — P- 59					
@ Rs 312.10/m <sup>2</sup> — L					Rs 21042.00
⑥ Maint. of slab culmrf.					
02. No. — wide — P- 59					
@ Rs 209.08/each — L					Rs 418.00

## **Continuation**