

Qty vide TMB P.No- (42)	
I.No- (2) 337.15 m ² @ 5735 =	19268.50
③ Repaired Pathways 15 mm BN-	
Qty vide TMB P.No- (43)	
I.No- (3) 3.125 m ³ @ 11869.05 =	36903.50
④ Patch repair Over patches	
20 mm premix capped d-	
Qty vide TMB P.No- (43)	
I.No. (4) 41.95 m ² @ 317.82 =	13333.20
⑤ Patch repair over bituminous	
20 mm premix d-	
Qty vide TMB P.No- (43)	
I.No. (5) 42.06 m ² @ 335.20 =	14099.20

Continuation

Particulars	Details of actual measurement			Contents of area
	No.	L.	B.	D.
⑥ Maint. of HPC				
Qty vide TMB P.No - (43)				
I.No. (87) 3 No @ 1109.67 =				3329.00
⑦ Maint. of slab culvert				
Qty vide TMB P.No (43)				
I.No. (88) 1 No @ 2291.44 =				2291.00
⑧ Maint. of Road signs				
Qty vide TMB P.No - (43)				
I.No. (89) 0-15 Km @ 1066.50 =				160.00
⑨ Maint. of 200m Kms stone				
Qty vide TMB P.No - (43)				
I.No. (90) 0-18 km @ 650.87 =				1170.00

⑩ Cutting of branch road				
Shrub de -				
Qty vide TMB P.No - (43)				
I.No. (91) 2 No @ 105.39 =				211.00
⑪ White washing of parapet				
Qty vide TMB P.No - (43)				
I.No. (92) 63 m ² @ 16.47 =				1038.00
Total RS =				11755.00
Less 50% Below RS =				11755.00
RS =				10579.00

Continuation				
--------------	--	--	--	--

46/08/20
 47/08/20
 48/08/20
 49/08/20
 50/08/20
 51/08/20
 52/08/20
 53/08/20
 54/08/20
 55/08/20
 56/08/20
 57/08/20
 58/08/20
 59/08/20
 60/08/20
 61/08/20
 62/08/20
 63/08/20
 64/08/20
 65/08/20
 66/08/20
 67/08/20
 68/08/20
 69/08/20
 70/08/20
 71/08/20
 72/08/20
 73/08/20
 74/08/20
 75/08/20
 76/08/20
 77/08/20
 78/08/20
 79/08/20
 80/08/20
 81/08/20
 82/08/20
 83/08/20
 84/08/20
 85/08/20
 86/08/20
 87/08/20
 88/08/20
 89/08/20
 90/08/20
 91/08/20
 92/08/20
 93/08/20
 94/08/20
 95/08/20
 96/08/20
 97/08/20
 98/08/20
 99/08/20
 100/08/20