

MUNSY - To3 to Bahera

Ag.No- 1658D/2020-2021

GLEN Schedule XLV-Form No. 134

Shorghati

DIVISION

Dobhi

SUB-DIVISION

Arunkumar Singh -

1210

Measurement Book

1st Year Maintenance bill

32

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Construction of Road					
From To Bahera					
Agency - Arun kr Singh					
Agreement No - 16 SBD/20-21					
Item ① Restoration of Raincubs.					
5x 3.10x 1.10x 0.300 =					5.11 m ³
6x 1.90x 1.15x 0.280 =					3.27 m ³
8x 3.10x 1.10x 0.300 = 8.88 m³					
10x 4.30x 1.15x 0.300 =					14.83 m ³
7x 3.90x 1.20x 0.250 =					8.19 m ³
6x 4.20x 1.10x 0.280 =					6.93 m ³

3x 1.10x 0.70x 0.300 =					0.69 m ³
3x 1.20x 0.60x 0.300 =					0.64 m ³
					34.34 m³
					39.66 m ³
Item ② Matching up of Berms					
Shoulder					
10x 4.10x 1.20 =					49.2 m ²
9x 3.80x 1.10 =					37.62 m ²
8x 5.20x 1.15 =					47.84 m ²
7x 6.10x 1.15 =					49.10 m ²
2x 0.80x 0.20 =					0.32 m²
7x 5.50x 1.15 =					44.27 m ²
8x 4.90x 1.25 =					49.00 m ²
8x 3.70x 1.00 =					29.60 m ²
					308.95 m ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Item ③	Repair of pot holes filled with 75 mm				
	12	0.350	0.300	0.0025	= 0.09 m ²
Item ④	Patch repair over pot holes				
	6	1.10	0.700		= 4.62 m ²
	10	1.20	0.900		= 10.80 m ²
	6	1.40	1.10		= 9.24 m ²
	5	1.30	0.800		= 5.20 m ²
					29.86 m ²
Item ⑤	Patch repair over bituminous surface				
	7	0.90	0.700		= 4.41 m ²
	8	1.30	0.800		= 8.32 m ²
	6	1.50	1.10		= 9.90 m ²
	6	1.60	0.700		= 6.72 m ²
					29.35 m ²
Item ⑥	Filling of creels and joints				
	2	10	30		= 600 m
	2	11	30		= 660 m
					1260 m
Item ⑦	Treatment of isolated failed pavement				
	4	0.700	0.400	0.0025	= 0.094 m ²
	5	0.900	0.500	0.0025	= 0.1125 m ²

Continuation

	ABSTRACT OF COST	
1/15.1	Restoration of Rainews	
	V.T.M.B.P.No - (32)	
	item no (1) — 39.66 m^3	
	@ $466.39 / \text{m}^3$ —	$18497 =$
2/15.2	Motoring up of Berms/ Shoulder	
	V.T.M.B.P.No - (32)	
	item no (2) — 306.95 m^2	
	@ $70.12 / \text{m}^2$ —	$21523 =$
3/15.3 (1)	Repair of pot holes	
	filled with 15 cm	
	V.T.M.B.P.No - (33)	
	item no (3) — 0.09 m^3	

Scanned with CamScanner

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(9/15.12) Maintenance of c/p works (Hydro pipe culvert)					
V.T.M.B.P.No. - (34)					
item no (9) — 3th					
Q 1529.28/H					1529.28
(10/15.13) white washing of ponto					
wall of c/p works					
V.T.M.B.P.No. - (34)					
item no (10) — 20.16 m ²					
Q 21.35/m ² —					430.20
(11/15.12.9) cutting of branches of Trees and shrubs					
V.T.M.B.P.No. - (34)					
item no (11) — 3th					
Q 155.93/H —					468.20
(12/15.12.10) cutting of shrubs from road way					
V.T.M.B.P.No. - (34)					
item no (12) — 720 H					
Q 9.58/H —					7377.20
(13/15.12.11) Pruning of grass and weeds					
V.T.M.B.P.No. - (34)					
item no (13) — 1440 m ²					
Q 3.19/m ² —					4594.20

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(14/15.9) P/V Sign main lanes					
V.T.M.B.P.No. (39)					
Item (14) — 0.7701m					
Q 1400.00/m —					1083.00
(15/15.11) Maintenance of 200m					
and 1cm stone					
V.T.M.B.P.No. (35)					
Item (15) — 0.7701m					
Q 840.76/m —					647.00
					105952.00
A. K. Singh					
07/02/23					

Continuation