

कार्यपालक अभियन्ता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, सहरसा

पत्रांक. 2260 अगु

सहरसा, दिनांक 20.12.24/

प्रेषक:-

कार्यपालक अभियन्ता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, सहरसा।

सेवा में,

नोडल पदाधिकारी,
3054 (MR) कोषांग,
बिहार, पटना।

विषय:- शीर्ष 3054 नई अनुरक्षण नीति-2018 अंतर्गत Initial Rectification and Surface renewal. कराये गये कार्य हेतु अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषयक कहना है कि विहित प्रपत्र में संलग्न विवरणी के अनुसार शीर्ष Mr 3054 New Maintenance Policy-2018. अन्तर्गत Fungi Bandh in Missing Link. पथ का Initial Rectification and Surface renewal कराये गये कार्य हेतु राशि Rs 64.27771/- (रूपये चौसठ लाख सताईस हजार सात सौ एकहतर मात्र) की आवश्यकता है।

अतः कार्यहित में अनुरोध है कि उक्त अधियाचित Rs 64.27771/- (रूपये चौसठ लाख सताईस हजार सात सौ एकहतर मात्र) उपलब्ध कराने की कृपा की जाय ताकि कराये जा रहे कार्यों का विपत्र भुगतान किया जा सके।

- अनु०:- (1) अधियाचना प्रपत्र
(2) IRI Value Report
(3) Map
(4) प्रमाण-पत्र।

विश्वासभाजन

19/12/24
19/12/24
19/12/24
कार्यपालक अभियन्ता
ग्रा०का०वि०, कार्य प्रमण्डल,
सहरसा

Name of Division:- RWD Works Division Saharsa

Rural Works Department
MR NEW MAINTENANCE POLICY-2018. ALLOTMENT & REQUISITION

SL. No.	Year	Name of Road	Name of Contractor (In English)	Project Id	Administrative Sanction		Agreement Amount (In Lacs)		Value of Rd (in million)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Allotment Received (in Lacs)	Total Expenditure as per MIS (in Lacs)	Value of Measurement (in Lacs)	Current Demand (in Lacs)	Remarks
					Length (In Km)	Amount (In Lacs)	Main Work	Maintenance								
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17
1	2023-24	Fungi Bandh in Missing Link.	Pankaj Kumar Singh	20904401008	1.820	104.671	64.27771	17.47940	2670	25	5%	0.00000	0.00000	64.27771	64.27771	Complete

19/12/24
D.A.O
RWD Works Division
Saharsa

19/12/24
Executive Engineer
RWD Works Division
Saharsa

**OFFICE OF THE EXECUTIVE ENGINEER
RWD WORKS DIVISION SAHARSA.**

**Name of Scheme:- Fungi Bandh in Missing Link.-,PACKAGE No- RM/SA/SAH/24/0001, Project ID-
20904401008.**

**Certified that all item wise 100%
Measurement has been taken by me**


19/12/24
Junior Engineer
RWD Work section kahara
Works Division Saharsa

**Certified that all item wise 50%
Measurement has been cheked by me**


19/12/24
Assistant Engineer
RWD Work Section Kahara
Works Division Saharsa

**Certified that all item wise 10%
Measurement has been cheked by me**


19/12/24
Executive Engineer
Rural work Department
Works Division Saharsa

Name of work : Fungi Bandhin Missing Link
Name of customer : Pankaj Kumar Singh

(R) Rural Road	
Good	Average
< 4000	4001 - 6000
Poor	> 6000

Date	Time	Test No	Distance(m)	Total Distance(m)	BUM(Per)	Speed(Km/Hr)	U/(mm/Km)	Corrected U (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction1	Remarks
15/12/2022	17:16:35	238	0	0	0.0 cm	15.7 Km/Hr	0.0 mm/Km	86	0.17	Good	25.902168	N	86.509292	E	Normal
15/12/2022	17:16:54	238	100	100	19.3 cm	33.1 Km/Hr	1900.0 mm/Km	1863	2.63	Good	25.902168	N	86.509292	E	Normal
15/12/2022	17:17:21	238	100	200	29.3 cm	24.9 Km/Hr	2900.0 mm/Km	2797	3.78	Good	25.902168	N	86.509292	E	Normal
15/12/2022	17:17:44	238	100	300	28.3 cm	43.6 Km/Hr	2800.0 mm/Km	2704	3.67	Good	25.902168	N	86.509292	E	Normal
15/12/2022	17:18:01	238	100	400	26.3 cm	44.5 Km/Hr	2600.0 mm/Km	2423	3.33	Good	25.902168	N	86.509292	E	Normal
15/12/2022	17:18:19	238	100	500	29.3 cm	24.9 Km/Hr	2900.0 mm/Km	2797	3.78	Good	25.898575	N	86.510241	E	Normal
15/12/2022	17:18:37	238	100	600	25.3 cm	44.5 Km/Hr	2600.0 mm/Km	2423	3.33	Good	25.898575	N	86.510241	E	Normal
15/12/2022	17:18:57	238	100	700	28.3 cm	43.8 Km/Hr	2800.0 mm/Km	2704	3.67	Good	25.898575	N	86.510241	E	Normal
15/12/2022	17:19:11	238	100	800	25.3 cm	44.5 Km/Hr	2500.0 mm/Km	2423	3.33	Good	25.898575	N	86.510241	E	Normal
15/12/2022	17:19:25	238	100	900	16.3 cm	27.0 Km/Hr	1600.0 mm/Km	1613	2.28	Good	25.894076	N	86.509034	E	Normal
15/12/2022	17:19:38	238	100	1000	29.3 cm	24.9 Km/Hr	2900.0 mm/Km	2707	3.78	Good	25.894076	N	86.509034	E	Normal
15/12/2022	17:19:51	238	100	1100	28.3 cm	43.6 Km/Hr	2800.0 mm/Km	2704	3.67	Good	25.894076	N	86.509034	E	Normal
15/12/2022	17:20:05	238	100	1200	25.3 cm	44.5 Km/Hr	2500.0 mm/Km	2423	3.33	Good	25.894076	N	86.509034	E	Normal
15/12/2022	17:20:17	238	100	1300	28.3 cm	43.6 Km/Hr	2800.0 mm/Km	2704	3.67	Good	25.894076	N	86.509034	E	Normal
15/12/2022	17:20:30	238	100	1400	24.3 cm	37.8 Km/Hr	2400.0 mm/Km	2310	3.21	Good	25.887574	N	86.509567	E	Normal
15/12/2022	17:20:54	238	100	1500	25.3 cm	44.5 Km/Hr	2500.0 mm/Km	2423	3.33	Good	25.887574	N	86.509567	E	Normal
15/12/2022	17:21:08	238	100	1600	29.3 cm	24.9 Km/Hr	2900.0 mm/Km	2707	3.78	Good	25.887574	N	86.509567	E	Normal
15/12/2022	17:21:24	238	100	1700	28.3 cm	43.6 Km/Hr	2800.0 mm/Km	2704	3.67	Good	25.887574	N	86.509567	E	Normal
15/12/2022	17:21:40	238	100	1800	25.3 cm	37.4 Km/Hr	2500.0 mm/Km	2423	3.33	Good	25.887574	N	86.509567	E	Normal


28/12/24

28/12/24

Name of work		: Fungi Bandhin Missing Link													
Name of customer		: Pankaj Kumar Singh													
		(R) Rural Road													
		Good		Average		Poor									
		< 4000		4001 - 6000		> 6000									
15/12/2022	17:21:54	238	100	1900	28.3 cm	43.6 Km/Hr	2800.0 mm/Km	2704	3.67	Good	25.887574	N	86.505967	E	Normal

[Signature]
20/12/24 A.E.

[Signature]
20/12/24



[Signature]
20/12/24
A.E.

[Signature]
20/12/24