

MMGISY(SC)

Schedule XLV-Form No. 134

T02 to Kendua

RWD(W), Div.-Imangay **DIVISION**

Block-Imangay **SUB-DIVISION**

Measurement Book

Cont:- M/S Shiva Enterprises

708

[illegible]

12000	135 year mscmm	28800=20
1790	1265 year of loss	
(1) Restoration of channels etc		
(2) ...		
width 592cm (1)		4403=20
80.46 m ³ @ Rs. 404=06/m ³ Rs. 32511=00		
(2) making up of berm shoulder		
stripping of excess soil		
width 592cm (2)		3204=20
444.70 m ² @ Rs. 60=28/m ² Rs. 26807=00		
(3) pot holes repair 75mm WBM.		
width 602cm (3)		4403=20
0.105 m ³ @ Rs. 9432=48/m ³ Rs. 990=00		
		Rs. 60308=00

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(4) Patching repair of 20mm concrete carpet etc. - 506			13.72	13.72	308=00
width - 60 item (4)					
37.06m ² @ Rs. 242.95/m ²			Rs.		9004=00
(5) Patch repair of 20mm mix seal surfacing etc. - 506					
width - 60 item (5)					
37.06m ² @ Rs. 259.10/m ²			Rs.		9602=00
(6) Crack filling of cracks and joints by caulking material etc. - 506					
width - 60 item (6)					
1590M @ Rs. 37.11/m			Rs.		5899=00
(7) Repair of isolated area of damaged concrete pavement					
width - 60 item (7)					
13.72m ² @ Rs. 242.95/m ²			Rs.		3333=00
(8) Repair of old joints sealant and resurfacing of construction					
width - 60 item (8)					
585m ² @ Rs. 24.13/m			Rs.		14116=00
(9) Maint. of C.P. works. H.P. etc.					
width - 61 item (9)					
5 No @ Rs. 1166.58 each			Rs.		5833=00
(10) Maint. of slab curbs etc.					
width - 61 item (10)					
2 No @ Rs. 2394.96 each			Rs.		4790=00
			Rs.		112885=00

Continuation

